

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURANC		Ref:	CS/INC24060026/Anp3	
IVIO	75 BRAS BASAH ROAD		Date:	12/09/2024	
		SINGAPORE 189557			
			Code:	INC	
1.	,				
	Insured Veh.	FBU 4290T	Veh. Inspected	SLW 5214D	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1281120-001	Excess	\$0.00	
	Assign From	YEE PEI LI	Assign Date	11/06/2024	
2. Vehicle Details					
	Make & Model	HYUNDAI ELANTRA	C.C	1591	
	Engine No.	G4FGJU134072	Year of Reg.	20/02/2018	
	Chassis No.	KMHD841CMJU628456	Colour	GOLD	
	Odometer	58645 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65R15	MICHELIN	6	
	L/H Front Tyre	195/65R15	MICHELIN	6	
	R/H Rear Tyre	195/65R15	MICHELIN	6	
	L/H Rear Tyre	195/65R15	MICHELIN	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	06/06/2024	Inspection Date	11/06/2024 (17:53)	
	Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
·					

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days