



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SBP288D

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

18941
SBP288D / 29/10/2012
WDD2043312F961877
27491030003339
MB/C 180 CGI (B/E) COUPE C20
027 775 Iridium sil/ 042 237 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WC000668	Credit	24/06/2024/ 12:05	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M-BPNSUN

POLICY NO/ACC DATE : A300668707QMY // 09/05/2024
DRIVE IN/TP VEHICLE NO. : 24/06/2024 // SLX3193M - CHINA
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

- A BPILAB
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.
- A BPIRES
RESPRAY BONNET & FRONT BUMPER
- A BPILAB
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT
- A BPILAB
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT
- M BPNSUN
SUNDRY
- M FRONT BUMPER
- M LH/ FRONT BUMPER CHROME MOULDING
- M RH/ FRONT BUMPER CHROME MOULDING
- M RH/ FRONT BUMPER MOUNTING RAIL
- M RH/ FRONT BUMPER BRACKET
- M CTR/ BASIC MOUNTING FOR BUMPER
- M FRONT IMPACT ABSORBER
- M RADIATOR GRILLE
- M MERCEDES STAR
- M MERCEDES STAR CARRIER
- M RADIATOR GRILLE SUPPORT
- M FRONT CROSS MEMBER
- M RH/ HEADLAMP FRAME
- M RH/ HEADLAMP UNIT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1.00	1488.87	00.00	1488.87
1.00	107.53	00.00	107.53
1.00	107.53	00.00	107.53
1.00	24.66	00.00	24.66
1.00	24.66	00.00	24.66
1.00	121.35	00.00	121.35
1.00	148.49	00.00	148.49
1.00	1001.82	00.00	1001.82
1.00	172.46	00.00	172.46
1.00	100.05	00.00	100.05
1.00	42.88	00.00	42.88
1.00	413.44	00.00	413.44
1.00	622.00	00.00	622.00
1.00	1059.96	00.00	1059.96

Taufik 97495749 WP 6/12/24 24pm

Kerlyn Ong Kai Li

Confirmed & accepted by

Taufik e1khant.com
Resurvey before paint

DID: 6771 4420 HP: 9186 5113
Email: kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Nett	9,670.70
9% GST on	9670.70
	870.36
Total Payable	10,541.06

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg