



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SBP288D

Vehicle & Document Information

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

WIP No 18941  
Reg No/Reg Date SBP288D / 29/10/2012  
Date In/Mileage 06/12/2024/ 108921  
Chassis No WDD2043312F961877  
Engine No 27491030003339  
Make/Model MB/C 180 CGI (B/E) COUPE C20  
Colour/Trim 027 775 Iridium sil/ 042 237 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	16/12/2024/ 14:45	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : A300668707QMY // 09/05/2024 DRIVE IN/TP VEHICLE NO. : 24/06/2024 // SLX3193M - CHINA DATE IN/DATE SURVEY: 06/12/2024 @ 1600 // TAUFILK LKK DIRECT SETTLEMENT : 18/09/2024 // CHINA - JENNY LEW				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				1440.00
A BPIRES RESPRAY BONNET & FRONT BUMPER			0.05	1600.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB TO REMOVE,REPLACE HEADLAMP WITH FOCUS . NETT				120.00
M BPNSUN SUNDRY				15.00
X MOULDING	1.00	107.53	00.00	107.53
X TRIM STRIP	1.00	107.53	00.00	107.53
X RADIATOR GRILLE	1.00	1001.81	00.00	1001.81
X MERCEDES STAR	1.00	172.46	00.00	172.46
X MERCEDES STAR CARRIER	1.00	100.05	00.00	100.05
X BRACING	1.00	42.88	00.00	42.88
X LOW BEAM BULB H7 12-55W	1.00	49.25	00.00	49.25 nec✓

THIS IS NOT AN OFFICIAL TAX INVOICE  
ESTIMATE

Finalization

Confirmed & accepted by

Nett 5,136.51  
9% GST on 5136.51 462.29  
Total Payable 5,598.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SBP288D

Vehicle & Document Information

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

WIP No 18941  
Reg No/Reg Date SBP288D / 29/10/2012  
Date In/Mileage 06/12/2024/ 108921  
Chassis No WDD2043312F961877  
Engine No 27491030003339  
Make/Model MB/C 180 CGI (B/E) COUPE C20  
Colour/Trim 027 775 Iridium sil/ 042 237 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	16/12/2024/ 14:38	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LOW BEAM BULB H7 12-55W	1.00	49.25	00.00	49.25

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

	<b>Nett</b>	<b>49.25</b>
<b>9% GST on</b>	<b>49.25</b>	<b>4.43</b>

Authorized signatory and company stamp

**Total Payable 53.68**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg