



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SBP288D

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **18941**
Reg No/Reg Date **SBP288D / 29/10/2012**
Date In/Mileage **06/12/2024/ 108921**
Chassis No **WDD2043312F961877**
Engine No **27491030003339**
Make/Model **MB/C 180 CGI (B/E) COUPE C20**
Colour/Trim **027 775 Iridium sil/ 042 237 Leather Fla**

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	16/12/2024/ 14:45	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : A300668707QMY // 09/05/2024								
DRIVE IN/TP VEHICLE NO. : 24/06/2024 // SLX3193M - CHINA								
DATE IN/DATE SURVEY: 06/12/2024 @ 1600 // TAUFILK LKK								
DIRECT SETTLEMENT : 18/09/2024 // CHINA - JENNY LEW								
A BPILAB								1440.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES							0.05	1600.00
RESPRAY BONNET & FRONT BUMPER								
A BPILAB							0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								
A BPILAB								120.00
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT								
M BPNSUN								15.00
SUNDRY								
X MOULDING					1.00	107.53	00.00	107.53
X TRIM STRIP					1.00	107.53	00.00	107.53
X RADIATOR GRILLE					1.00	1001.81	00.00	1001.81
X MERCEDES STAR					1.00	172.46	00.00	172.46
X MERCEDES STAR CARRIER					1.00	100.05	00.00	100.05
X BRACING					1.00	42.88	00.00	42.88
X LOW BEAM BULB H7 12-55W					1.00	49.25	00.00	49.25
Finalization								

Confirmed & accepted by

Nett **5,136.51**
9% GST on **5136.51** **462.29**
Total Payable **5,598.80**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SBP288D

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 18941
Reg No/Reg Date SBP288D / 29/10/2012
Date In/Mileage 06/12/2024/ 108921
Chassis No WDD2043312F961877
Engine No 27491030003339
Make/Model MB/C 180 CGI (B/E) COUPE C20
Colour/Trim 027 775 Iridium sil/ 042 237 Leather Fla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	16/12/2024/ 14:38	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LOW BEAM BULB H7 12-55W	1.00	49.25	00.00	49.25

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Authorized signatory and company stamp

	Nett	49.25
9% GST on	49.25	4.43
Total Payable		53.68

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg