

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

JP Lim Pac
Xiao Long

VEHICLE NO : SMS 362 B

CHASSIS NO : GK82103480

MAKE / MODEL : HONDA SHUTTLE

ACCIDENT DATE : 04.11.2024

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LIST ITEMS			
1	Rear bumper <i>Rehnd</i>	1	\$ 1189.00
2	Rear bumper side holder @ \$61.35 <i>RH anker</i>	2	\$ 61.35 122.70
3	Rear bumper clips <i>new</i>	1	\$ 50 60.00
4	Rear LH lamp <i>cracked</i>	1	\$ 494.00
5	Rear LH fender <i>Distorted</i>	1	\$ 1010.90
6	Rear LH fender inner shield <i>torn</i>	1	\$ 105.80
7	Rear LH sport rim <i>new</i>	1	\$ + 800.00
8	Rear LH tyre <i>new</i>	1	\$ + 380.00
9	Rear LH quater glass rubber <i>new</i>	1	\$ 210.30
			\$ 4372.70
<i>Rear Fender End Seal. 165.50</i>			\$ 3286.85
<i>torn</i>			\$ 2629.48
LESS 20% DISC			\$ 874.54
TOTAL			\$ 3498.16

LABOUR COST

1	To supply rear quater glass sealant	1	\$ 50 80.00
2	Remove + reinstall quater glass	1	\$ 60 100.00
3	Remove + reinstall petrol tank	1	\$ 80 150.00
4	Remove + reinstall reverse sensor	1	\$ 50 100.00
5	Remove + reinstall roof lining	1	\$ 150.00
6	Remove, replace + repair consistant to the accident	1	\$ 600 1000.00
7	Respray painting	1	\$ 400 1000.00
8	Tuff kote	1	\$ 80 100.00
TOTAL			\$ 2680.00

9 Remove + Refix Body sticker 1000.00

GRAND TOTAL \$ 6178.16

800
2620

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Cj
1/5 22/04/25

06 days

total 4749.48

1/5: 3.8k

3.8k