

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0849/2024/KS
DATE : 11-Nov-24
WIP : 37652

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/11/2024

YOUR INSURED VEH NO : SNG 8223 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR ANTON SHCHEKALOV
ADDRESS : 31 KEPPEL BAY VIEW
#15-90
SINGAPORE 098418
TELEPHONE : HP +65 87093459
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5148157041
VEHICLE NO : **SMS 4000 U**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 17/8/2020
ENGINE NO : DEM 024351
CHASSIS NO : WAUZZZF56LA019264
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Nov-24
PLACE OF ACCIDENT : 21 KEPPEL BAY VIEW, SINGAPORE
CONDO "REFLECTIONS AT KEPPEL BAY"
NO2 ENTER PARKING

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 4000 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00	
3	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
4	TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,200.00	
5	TO RESPRAY FRONT BUMPER RHS FRONT FENDER AND RHS FRONT DOOR.	\$	3,000.00	
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$	7,932.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 4000 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,802.00	
2	FRONT BUMPER SECURING STRIP	2	\$ 90.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 329.00	
4	FRONT BUMPER AIR GUIDE - RH	1	\$ 56.00	
5	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 169.00	
6	FRONT BUMPER TRIM - RH	1	\$ 60.00	
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 46.00	
8	FRONT PARKING AID SENSOR - RH	1	\$ 286.00	
9	FRONT PARKING AID SENSOR SEAL RING	6	\$ 17.00	
10	FRONT FENDER - RH	1	\$ 1,264.00	
11	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 62.00	
12	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 92.00	
13	FRONT FENDER BRACKET - RH	1	\$ 45.00	
14	FRONT FENDER RIVET - RH	1	\$ 26.00	
15	FRONT FENDER BRACKET - RH	1	\$ 73.00	
16	FRONT FENDER BRACKET - RH	1	\$ 56.00	
17	FRONT FENDER BRACE - RH	1	\$ 177.00	
18	FRONT FENDER LOWER BRACKET - RH	1	\$ 72.00	
19	FRONT FENDER COVER - RH	1	\$ 45.00	
20	FRONT HEADLIGHT COVER - RH	1	\$ 55.00	
SUB TOTAL SPARE PARTS		:	\$ 5,822.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 4000 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER COVER - RH	1	\$ 20.00	
22	FRONT FENDER COVER - RH	1	\$ 90.00	
23	FRONT FENDER CHROME TRIM - RH	1	\$ 192.00	
24	FRONT WHEEL HOUSING LINER - RH	1	\$ 332.00	
25	FRONT WHEEL SPOILER - RH	1	\$ 92.00	
26	WHEEL HOUSING LINER ATTACHMENT PARTS - RH	1	\$ 190.00	
27	LED HEADLIGHT MATRIX - RH	1	\$ 9,204.00	
28	LED HEADLIGHT SPACER - RH	3	\$ 150.00	
29	LIFT CYLINDER - RH	1	\$ 238.00	
30	LIFT CYLINDER BRACKET - RH	1	\$ 19.00	
31	LIFT CYLINDER HOSE	1	\$ 118.00	
32	FRONT DOOR CHROME TRIM - RH	1	\$ 192.00	
33	SIDE MEMBERS ATTACHMENT PARTS - RH	1	\$ 153.00	
34	SIDE MEMBERS ADHESIVE TAPES - RH	1	\$ 233.00	
35	FRONT RIM - RH	1	TBC	
36	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 11,723.00	
TOTAL LABOUR CHARGES		:	\$ 7,932.00	
GRAND TOTAL		:	\$ 19,655.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT