Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co,Reg,No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Toh, Yuslinda Date: 12 Nov 2024

Preliminary Advice

Vehicle No : SBK888Z Accident Date : 06/11/2024 Policy No. : 7230058635 Make : AUDI E-TRON Excess Assignment Date : 08/11/2024 : S\$600.00 Date of Inspection : 12/11/2024 : 6

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

> 55 UBI ROAD 1 SINGAPORE 408699

Est. Duration of Repair

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	51,026.00
Revised Amount	:S\$	19,066.00
Check Items (Estimated)	:S\$	1,654.00
Total	:S\$	20,720.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	255,000.00
COE / PARF Rebate	:S\$	142,188.00

Salvage Value :S\$

Margin for Repair 112,812.00 :S\$

Remarks

(x)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us
	have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (x) to part prices and labour cost check.