

# TSL AUTO PRO SELECTION PTE LTD

TO	: INCOME	DATE	26/11/2024
VEHICLE NO	: SLJ5211E (2016)	<i>Hui Rong</i>	
VEHICLE MODEL	: NISSAN QASHQAI 1.2		
CHASSIS NO	: SJNFEAJ11U1709291		

### CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>P/S</i>	1	\$ 755.40	\$ 755.40
2	REAR BUMPER SIDE HOLDER <i>JM</i>	1	\$ 35.90	\$ 35.90
3	TAILLAMP <i>JM</i>	1	\$ 323.70	\$ 323.70
4	TAILLAMP PANEL	1	\$ 192.30	\$ 192.30
5	REAR FENDER <i>P/S</i>	1	\$ 1,081.40	\$ 1,081.40
6	REAR FENDER ARC GARNISH <i>lt</i>	1	\$ 583.60	\$ 583.60
7	REAR FENDER INNER TRIM BOARD <i>new</i>	1	\$ 361.70	\$ 361.70
8	REAR FENDER INNER SHIELD <i>new</i>	1	\$ 202.10	\$ 202.10
9	REAR FENDER AIR VENT <i>new</i>	1	\$ 62.80	\$ 62.80
10	REAR DOOR <i>seated</i>	1	\$ 1,487.60	\$ 1,487.60
11	REAR DOOR LOCK <i>JM</i>	1	\$ 196.70	\$ 196.70
12	REAR DOOR WEATHERSTRIPE <i>JM</i>	1	\$ 187.40	\$ 187.40
13	REAR DOOR LOWER PROTECTOR <i>lt</i>	1	\$ 452.10	\$ 452.10
14	REAR DOOR INNER TRIM BOARD <i>JM</i>	1	\$ 844.40	\$ 844.40
15	REAR DOOR GLASS REGULATOR C/W MOTOR <i>JM</i>	1	\$ 487.90	\$ 487.90
16	REAR WHEEL HUB C/W BEARING <i>JM</i>	1	\$ 381.90	\$ 381.90

*2523.30*  
*2270.97*

TOTAL PRICE: \$ 7,636.90  
LESS 10% \$ 763.69  
SUB TOTAL PRICE: \$ 6,873.21

### SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR FENDER ARC GARNISH <i>lt</i>	1 S T	\$ 20.00	\$ 20.00
3	REAR FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4	REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
5	REAR DOOR BLACK TAPE <i>new</i>	1	\$ 60.00	\$ 60.00
6	REAR WHEEL RIM <i>lt</i>	1	\$ 880.00	\$ 880.00
7	REAR TYRE <i>new</i>	1	\$ 250.00	\$ 250.00

TOTAL: \$ 1,300.00

*680*

**LABOUR**

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	300	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	600	
3	WIRING CHECK	\$ 50.00	X	
4	TO APPLY TUFF COAT	\$ 150.00	X	
5	TO REMOVE UPHOLSTERY	\$ 150.00	X	
6	TO TRANSFER DOOR FITTINGS	\$ 150.00	60	
7	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	60.00
8	TO REMOVE REVERSE SENSOR	\$ 100.00	X	
		\$ 2,550.00		

**ESTIMATE REPORT**

TOTAL PARTS COST: \$ 8,173.21  
 TOTAL LABOUR COST: \$ 2,950.00  
 TOTAL REPAIR COST: \$ 11,123.21

1040

total: 3990.97

h/s: 3.2k

03Days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: