

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : SJG3646L
Vehicle Model : KIA CERATO FORTE
Accident Date : 04.11.2024
Original Reg Date : 23.06.2009 (31.05.2029)

Date : 06.11.2024
Chassis : KNAFH221295073726
TP Ins. CTP

Yan.

ESTIMATE

1	1 pc	Bonnet Inner Lock			125.60	+
2	1 pc	Bonnet Lock Cable			85.00	+
3	1 pc	Bonnet Hinges			69.80	+
4	1 pc	Bonnet			787.50	+
5	1 pc	Front Bumper			865.20	687
6	1 set	Front Bumper Side Retainers	75.20		150.40	+
7	1 set	Front Bumper Clips			50.00	30
8	1 pc	Front Bumper Fog lamp			327.50	2
9	1 pc	Front Bumper Fog lamp garnish			193.50	285
10	1 pc	Front Bumper Fog lamp wiring harness			455.60	+
11	1 pc	Front Bumper Reinforcement			677.20	+
12	1 pc	Front Bumper Sponge			145.70	+
13	1 pc	Front Support Panel			1,231.20	+
14	1 pc	Front Radiator			1,044.50	+
15	1 pc	Front Condenser			1,123.40	+
16	1 set	Headlamps	689.50		1,379.00	689.50
17	2 pc	Headlamps Bottom Retainers	114.90		229.80	+
18	1 pc	Front Grille			623.50	+
19	1 pc	Front Fender LH			588.50	+
20	1 pc	Front Fender inner cowling LH			195.20	✓
21	1 pc	Front door LH			\$ 1,227.80	+
22	2 pc	Front door hinges LH	58.90		\$ 117.80	+
23	1 pc	Front door weatherstrip LH			\$ 168.90	+
24	1 pc	Front knuckle arm LH			\$ 478.50	2
25	1 pc	Front wheel hub bearing LH			\$ 425.30	2
26	1 pc	Front lower arm LH			\$ 436.50	2
27	1 pc	Front shock absorber LH			\$ 390.60	+
28	1 pc	Front steering rack and pinion			\$ 1,893.20	+
29	1 pc	Front driveshaft LH			\$ 1,023.80	+

subtotal 16,510.50
Less 10% 1,651.05
total 14,859.45

302780
272430

Special Nett

1	1 pc	Front fender inner cowling clips <i>new</i>	30.00	+
3	1 pc	Front bumper lower lip (accessories) <i>Del</i>	1,200.00	880
4	1 set	Sideskirt(accessories) <i>new</i>	1,200.00	785 +
5	1 pc	Front bumper clips <i>in</i>	30.00	✓
6	1 pc	Front rims (set) <i>out</i>	1,800.00	580
7	1 pc	Front sport rim tyre <i>new</i>	380.00	+

1890

Labour charge

Panel Beating	1,600.00	400
Spray painting	1,600.00	600
Check Wiring on headlamp and focussing	100.00	30
To perform computerised wheel alignment	180.00	80
To remove front undercarriage	350.00	200
To remove steering rack and pinion	550.00	+
Anti rust	180.00	30
Water coolant leak test	80.00	+
Air con system pressure test	100.00	+
Remove and transfer front door mechanism	150.00	+

\$ 24,389.45

1340

Admin Lj
H/S 06/11/24.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Oblys
Supplementary: 238.86
Total: 5793.16
H/S: 4.6K
4.6K

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	SJG3646L	Date of Request	08.11.2024
Vehicle Model	KIA CERATO	Number of Days to Extend (If any)	
S/N	PART DESCRIPTION		LIST PRICE
1	ENGINE UNDER COVER <i>torn</i>		\$265.40 ✓

265 40
Supplementary : 23886

CITY TYREAUTO PTE LTD
219 KAKI BUKIT AVE 1
SHUN LI INDUSTRIAL PARK
SINGAPORE 416044
TEL: 67466686
H/P: 85153676

Work Order: R008025
 License: SJG3646L
 Date: 6.11.24 15:31

Kia : Cerato/Forte : 2019- (BD/BDm) : without Independent Rear Suspension : Rest of World

Front : Left

Actual	Before	Specified Range
1°49'	1°49'	-0°53' 0°07'
4°30'	4°30'	4°00' 5°00'
0°49'	0°49'	-0°03' 0°09'
-1°19'	-1°19'	13°30' 14°30'
0°30'	0°30'	12°37' 14°37'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°49'	-0°49'	-0°53' 0°07'
4°30'	4°30'	4°00' 5°00'
0°27'	0°27'	-0°03' 0°09'
1°19'	1°19'	13°30' 14°30'
0°30'	0°30'	12°37' 14°37'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
2°38'	2°38'	
0°00'	0°00'	
-2°38'	-2°38'	
1°16'	1°16'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°13'	-1°13'	-1°42' -0°42'
0°19'	0°19'	-0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°05'	-1°05'	-1°42' -0°42'
0°05'	0°05'	-0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°07'	-0°07'	
0°25'	0°25'	-0°04' 0°32'
0°07'	0°07'	