LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: AIG ASIA PACIFIC INSURANCE PTE LTD From: LKK Auto Consultants Pte Ltd

78 SHENTON WAY #09-16

AIG BUILDING

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: PANG, NICOLE-XS Date: 05/09/2024

PRELIMINARY ADVICE

Vehicle No SMW 872A Accident Date 17/06/2024

Make BMW 335I CLAIM No. TP / 9218242253SG

Assignment Date 26/06/2024 Excess - Inspection Date 19/6/2024 Est. Duration of Repair 13

Inspected At: HD PERFECT AUTOWORK PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| LUMP SUM | \$ 24,800.00 |
|---------------------------|-----------------|
| Total | \$ 30,991.61 |
| "Check" Items Amount | \$0.00 |
| Revised Estimate Amount: | \$ 30,991.61 |
| Workshop Estimate Amount: | \$ 72,438.16 |

Total Loss Consideration

| Book Value | \$0.00 |
|-------------------|------------------|
| Market Value | \$ 110,000.00 |
| COE / PARF Rebate | \$ 28,157.00 |
| Salvage Value | \$ 81,843.00 |
| Margin for Repair | |

Remarks

| [|] | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|---|---|--|
| | | Kindly let us have your authorisation. |

[] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.