ASS. REC. BY:	S/CTI24110176/Kvh3
Kenneth ASS	SIGNMENT
From: Date:	Rain SEGRA
Estimated Cost:	Veh No: JN/9 0348/1 Yr Regn: 10, 2:
OD /TP/WS/TP RES/OD RES/EVA/INV/MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Traller or
To Inspect Vehicle No:	
at Workshop m/s Tony Luck	Color C.C. 1332
of 7788	2001 C MISURED / SIG / NI / NA
Insured: SLD 3761D	Sp.Reading 3282) T/Radio: Insured / Std / NI / NA Eng/No:
Policy No.	
Claims No. SNM24D205928	C/No: W/////838421 441234 Gen. Cond; Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Cfient's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/RIm / STO A/Rim or
	Tyre Size: F: 225/45 R18
(Policy Condition)	R: =
Remark: The veh had commenced its N/S O/S	BS J DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: \$ 195K	Front
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. Rear
GIA / PR Seen: Consistent?: Yes or No	L/Bal. P mm L/Bal. P
Est. Repairs: 4 days Res.: Yes or No	DOA 19/1 / 101
Lum Sum: /-13-/ % 3 Val.: Yes or No	Survey held at D.O.I. 0.0.1.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	Old T NIS T OIC T ROOMED OF
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Account instruction	
21/11 & 7131.50 (m/m	
	the state of the s
21/11/24 Re-confirmed final fig \$7111.50 with \$	Steven (Red 5041.70, 41%)
On the same of the	
Oate/Time, File Pass to? Prell. Report Day	s Of Repair: 4
	survey No. of Trip: Survey Fee:
2	Transportable:
Add Fee:	: Site Insp (\$)s-Rssi
Report Format :	: Interview (\$), Fields
-ump Sum / I.B.I: (S	Tech Invs (\$). Others
	Weekend (\$
	Nate destination for the property of the contraction of the contractio

SJ0G24AL000B-01 / JP Knights Pte Ltd ENTRY DATE & TIME: 21/10/2024 10:35 (SGT) SUBMITTED BY: Flash Reporting VERSION: 2 (06/11/2024 15:12 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 21/10/2024 10:35 (SGT) Reported by **Actual Driver** Date of Accident 19/10/2024 12:50 (SGT) **Exact Location of Accident** Punggol Wy, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNM8548A INSURED/POLICYHOLDER Is company? Yes Name Of Registered Owner MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD Company Reg No 1XXXXX778Z **Email Address** too_tong.tan@mercedes-benz.com Mobile Phone No (Phone) +65-91997950 Alternative Phone No. (Office) +65-82821711

VEHICLE PARTICULARS

Manufacturer Mercedes Model Cla180 Variant COUPE PROGRESSIVE LN Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC 1332 Vehicle Fuel Petrol-Electric First Regisration Date Chassis no W1K1183842N441234 Effective Date/Time of Ownership **INSURANCE COMPANY**

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd. Policy Number / Cover Note Number SP2003907937

DRIVER

Element Driver	
Name of Driver	VINCENT LEE TIONG WOON (VINCENT LI ZHONG'EN)
NRIC No	SXXXX700D
Date Of Birth	15/12/1973
Occupation	Indoor
Driving Pass Date	02/08/1994
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	30 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91997950
Alt. Phone Number	-
Email Address	too_tong.tan@mercedes-benz.com
Address	104 PUNGGOL WALK #04-11
Address complement	-
Postcode	828792
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	110
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry
	=-7
OTHER INFORMATION	
OTHER IN ORIGINATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	
	2
	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s)	No
soliciting/offering accident claims assistance? Translator's name	No
Translator's ID	
Translator's phone number	-
Translator's email	-
Original language used in the statement	-
Original language used in the statement	-
PASSENGER 1	
Name	UNKNOWN
Gender	Female
DETAILS OF POLICE ACTION	
Was the assidant reported to the malical	
Was notice of intended Propagation given?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	•

CIRCUMSTANCES OF ACCIDENT

ON 19 OCT 2024 AT ABOUT 1250HRS I WAS DRIVING WITH VEHICLE A BEARING REGISTRATION NUMBER SNM8548A ENROUTE FROM TPE TOWARDS TO MY HOMELOT AT PUNGGOL WALK, WHILE DRIVING ALONG PUNGGOL WALK SUDDENLY MY FRONT UNKNOWN VEHICLE JAMMED BRAKED AND VEHICLE A MANAGED TO STOP ON TIME BUT VEHICLE B UNABLE TO BREAK ONTIME AND COLLIDED ONTO REAR OF VECHILE A. DAX AND HIS WIFE INJURED AT NECK AND LATER WILL GO CLINIC FOR CHECK UP.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD3761D Vehicle Manufacturer Honda Vehicle Model VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR Vehicle Variant Vehicle Colour Vehicle Category Private hire Name of Driver Contact Number (Phone) +65-98522060 Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

INJURED 2

Name of injured person Gender	WIFE Female
Phone No	-
Address	104 PUNGGOL WALK #04-11
Address Complement	-
Post Code	828792
Approximate Age Years Old	-
Injuries Sustained	INJURED NECK
Injured person in which vehicle?	SNM8548A
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set, out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer, such, Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

aravintan

Policyholder's Signature / Date & Time

Driver's Signature (Mariver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

19 OCT 2024 1440HRS

PUNGGOL WAY A-SNM8548A B-SLD3761D

Describe Circumstances of the Accident

South of the Michael Control of the Michael C
ON 19 OCT 2024 AT ABOUT 1250HRS I WAS DRIVING WITH VEHICLE A BEARING REGISTRATION NUMBER SNM8548A ENROUTE FROM TPE TOWARDS TO MY HOMELOT AT PUNGGOL WALK, WHILE DRIVING ALONG PUNGGOL WALK SUDDENLY MY FRONT UNKNOWN VEHICLE JAMMED BRAKED AND VEHICLE A MANAGED TO STOP ON TIME BUT
VEHICLE B UNABLE TO BREAK ONTIME AND COLLIDED ONTO REAR OF VECHILE A. DAX AND HIS WIFE INJURED AT NECK AND LATER WILL GO CLINIC FOR CHECK UP.

Declaration

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date &

Time

Driver's Signature (If driver is not the policyholder) / Date & Time 190CT2024

1440HRS

акаvınтаn

Witnessed by Reporting Centre Personnel



TEL :

YOUR REF NO

CLAIM TYPE

TP INS. CO.

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

: MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08

WESTGATE TOWER

SINGAPORE 608531

ATTN: ACCOUNTS DEPT

Not Norhank

FAX: Purmy B& paing

4-: lays

ARTY & 7131.50

: SLD3761D : THIRD PARTY

: CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE

ACCIDENT DATE : 19/10/2024 TP VEH REG NO : SLD3761D

ESTIMATE

NO : QUOT202411-000016(00)

DATE : 07/11/2024 **POLICY NO** : SP2003907937 VEH REG NO : SNM8548A

MAKE/MODEL: MERCEDES BENZ CLA 180 COUPE PROGRESSIVE LN

CHASSIS NO : W1K1183842N441234 **ENGINE NO** : 28281480066117

: 2023

Estimate Repair Cost to Vehicle No: SNM8548A

	Description	Q	uantity	Unit Price	Amount	
				<u>S\$</u>	<u>S\$</u>	
	NET PRICE				R	
1	Bootlid		1	2,516.00	2,516.00	
2	Bootlid 'CLA180' emblem		1	241.00	Ma 241.00	
3	Bootlid centre logo		1	202.00	10 202.00	
4	Bootlid weatherstrip		1	225.00	M 225.00	
5	Bootlid reflector - LH		1	647.00	647.00	7
6	Rear end panel		1	1,532.00	<i>n</i> 1,532.00	X
7	The same of the sa		Br	102.00	J- 102.00	8
8	Rear bumper		1	1,564.00	1,564.00	
9	Rear bumper reinforcement		1	560.00	Bu 560.00	7
10	Rear bumper centre inner frame		1	120.00	cm 120.00	2
11	Rear bumper reflector - RH / LH		2	55.00	Sh 110.00	x
12	Rear bumper sensor		2	353.00	<i>T</i> ~ 706.00	X
13	Rear bumper sensor seals		6	12.00	Ma 72.00	2
14	Rear bumper clips		15	10.00	Na 150.00	_
15	Rear bumper lower garnish	LKK Auto Consultants hence	notify 1	555.00	ne 555.00	_
16	Rear bumper lower centre chrome	the Repairer of the following:	1	130.00	D1-1130.00	-
17	Rear bumper lower chrome - RH / LH	 To resurvey before/after spray pai To display damaged part(s) during 	nting 2	158.00	S= 316.00	X
		Parts prices are subject to confirm	ation	-	9,748.00	"
		 Third party survey is on a "Without 	Prejudice" basis	Less 10%	974.80	
		 No illegal modification(s) is allowe 	d	-	8,773.20	
	SPECIAL NET	 Supplementary item(s) must be re is subject to final approval from Institute 	surveyed and		al .	
	Bootlid 'C&C' emblem		surance yompany	40.00	Ma 40.00	
19	Rear number plate	Acknowledged by Repairer	1	40.00	ne 40.00	
	LABOUR	Signature: Date:			80.00	
20	LABOUR	And Andrews and An	The second secon			601
	To transfer damaged bootlid interior mecha	anism to new bootild	1	120.00	120.00	2 ~
	To check & rectify wiring system		1	80.00	80.00	
	To remove & refit rear bumper sensor		1	100.00	100.00	
23	To remove & fix rear interior garnishes & tri repairs	mpoard to facilitate the	1	180.00	180.00	20
24	To panel beat and straighten rear chassis f	rame, rear floorboard	1	1,500.00	1,500.00	50
	panel, to cut & weld rear end panel, including	ng repalcement of		.,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
25	parts and align where necessary, to refit & To putty & spray on affected areas	adjust the same	4	4 000 00	60 OL	
20	To putty a spray on anected areas		1	1,200.00	1,200.00	



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08

WESTGATE TOWER SINGAPORE 608531

TEL :

FAX:

ATTN: ACCOUNTS DEPT

YOUR REF NO : SLD3761D

: THIRD PARTY

CLAIM TYPE TP INS. CO.

: CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2023

ACCIDENT DATE : 19/10/2024 TP VEH REG NO : SLD3761D

ESTIMATE

NO

: QUOT202411-000016(00)

DATE

: 07/11/2024

POLICY NO

: SP2003907937

VEH REG NO : SNM8548A

MAKE/MODEL : MERCEDES BENZ CLA 180

COUPE PROGRESSIVE LN CHASSIS NO : W1K1183842N441234

ENGINE NO

: 28281480066117

Estimate Repair Cost to Vehicle No: SNM8548A

Quantity	Unit Price	Amount
	<u>\$\$</u>	<u>S\$</u>
1	120.00	120.00
		3,300.00
	TOTAL	S\$ 12,153.20
ADD G	ST @ 9.00%	1,093.80
GR	AND TOTAL	S\$ 13,247.00
	1 ADD G	1 120.00

SINGAPORE DOLLAR THIRTEEN THOUSAND TWO HUNDRED FORTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE