



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1
1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :
ATTN : ACCOUNTS DEPT

FAX : *Referring B4 pain*

YOUR REF NO : SLD3761D
CLAIM TYPE : THIRD PARTY
TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE
ACCIDENT DATE : 19/10/2024
TP VEH REG NO : SLD3761D

4 days
7131.50

ESTIMATE

NO : QUOT202411-000016(00)
DATE : 07/11/2024
POLICY NO : SP2003907937
VEH REG NO : SNM8548A
MAKE/MODEL : MERCEDES BENZ CLA 180
COUPE PROGRESSIVE LN
CHASSIS NO : W1K1183842N441234
ENGINE NO : 28281480066117
REG. DATE : 2023

Estimate Repair Cost to Vehicle No : SNM8548A

Description	Quantity	Unit Price S\$	Amount S\$
NET PRICE	1	2,516.00	2,516.00
1 Bootlid	1	241.00	241.00
2 Bootlid 'CLA180' emblem	1	202.00	202.00
3 Bootlid centre logo	1	225.00	225.00
4 Bootlid weatherstrip	1	647.00	647.00
5 Bootlid reflector - LH	1	1,532.00	1,532.00
6 Rear end panel	1	102.00	102.00
7 Rear end panel top garnish	1	1,564.00	1,564.00
8 Rear bumper	1	560.00	560.00
9 Rear bumper reinforcement	1	120.00	120.00
10 Rear bumper centre inner frame	2	55.00	110.00
11 Rear bumper reflector - RH / LH	2	353.00	706.00
12 Rear bumper sensor	6	12.00	72.00
13 Rear bumper sensor seals	15	10.00	150.00
14 Rear bumper clips		555.00	555.00
15 Rear bumper lower garnish		130.00	130.00
16 Rear bumper lower centre chrome		158.00	316.00
17 Rear bumper lower chrome - RH / LH			9,748.00
		Less 10%	974.80
			8,773.20
SPECIAL NET			
18 Bootlid 'C&C' emblem		40.00	40.00
19 Rear number plate		40.00	40.00
			80.00
LABOUR			
20 To transfer damaged bootlid interior mechanism to new bootlid	1	120.00	120.00
21 To check & rectify wiring system	1	80.00	80.00
22 To remove & refit rear bumper sensor	1	100.00	100.00
23 To remove & fix rear interior garnishes & trimboard to facilitate the repairs	1	180.00	180.00
24 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut & weld rear end panel, including replacement of parts and align where necessary, to refit & adjust the same	1	1,500.00	1,500.00
25 To putty & spray on affected areas	1	1,200.00	1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1
1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL : FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SLD3761D

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 19/10/2024

TP VEH REG NO : SLD3761D

ESTIMATE

NO : QUOT202411-000016(00)
DATE : 07/11/2024
POLICY NO : SP2003907937
VEH REG NO : **SNM8548A**
MAKE/MODEL : MERCEDES BENZ CLA 180
COUPE PROGRESSIVE LN
CHASSIS NO : W1K1183842N441234
ENGINE NO : 28281480066117
REG. DATE : 2023

Estimate Repair Cost to Vehicle No : **SNM8548A**

Description	Quantity	Unit Price	Amount
		S\$	S\$
26 To apply rust proofing on repaired and replaced panels	1	120.00	120.00
			3,300.00
		TOTAL	S\$ 12,153.20
		ADD GST @ 9.00%	1,093.80
		GRAND TOTAL	S\$ 13,247.00

SINGAPORE DOLLAR THIRTEEN THOUSAND TWO HUNDRED FORTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE