

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : SNM24D206271 Date: 19th November 2024

Our Ref : CS/CTI24110177/Tvh3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SNM 8608K INSURED VEHICLE: XE 4811P ACCIDENT ON 06/11/2024

Instruction was received to inspect the vehicle Reg. No. SNM 8608K. The inspection was conducted on 08/11/2024 at the premises of M/s Twin Wheels Auto Trading Enterprise, 38 Woodlands Industrial Park E1 #03-14, Singapore 757700.

The following vehicle information was recorded:

Registration Number : SNM 8608K

Make/Model : Mazda 6 4-Door Sedan 2.0L Sp.6eat

Year of Registration : 2015 Body Colour : White

Chassis Number : JM6GJ1071F0147164

Engine Capacity : 1998 cc Speedometer Reading : 132208 km

The vehicle sustained damages at the front o/s portion. The Estimated repair cost of such vehicle is S\$5,044.80 (Sin Dollars: Five Thousand Forty Four And Cents Eighty Only.) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "**Total Loss**".

(a) If the vehicle to be "Total Loss" Market Value	S\$	6,200.00 (6	est)	
Less: LTA Reimbursement Value (RV)	(S\$	5,251.00)		
Nett Liability	S\$	949.00		
			S\$	949.00
(b) If the vehicle to be "Repair"				
Repair Cost (Est)	S\$	5,044.80		
Nett Liability			S\$	5,044.80
(a) - (b) =			(S\$	4,095.80)

The amount of estimated saving of S\$4,095.80 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

MOHAMAD TAUFIKH M.MATAI, AMSAE-A Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.