

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

⇒ China

## ESTIMATE

1st Nov 2024

Estimate No. : b1 71805  
Date Estimated : 14/11/2024  
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Seow Khim Chuang (Xiao Jinchuan)  
Blk 10 Pari Dedap Walk  
#09-21

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

Singapore 486062

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL      | MILEAGE |
|-----------|-------------------|------------|------------|---------|
| SMU7690Y  | WBA5F32070FH84693 | 28/08/2020 | 320i Sedan | 52567   |

### DESCRIPTION

### VALUE

To replace front bumper, right front fender and all damage attachment

1700 2,560.00

To respray front bumper and right front fender

1,923.00

To carry out body cavity preservation.  
(Per panel).

X11 118.00

To check electrical wiring

177.00

To remove old PDC assembly, replace damaged parts and  
reconnect to new bumper including conduct check for  
proper function.

177.00

To replace right headlight.

481.00

Sundries.

80 150.00

Total Labour 1:

5,576.00

### DESCRIPTION

### QTY

### PRIC

### VALUE

FRT RH SIDE PANEL BRACKET 3 ? x su

1

64.95

64.95

FRT RH SIDE PANEL BRACKET 1 ? x su

1

64.95

64.95

FRT RH SIDE PANEL ? x su

1

887.15

887.15

FRT SHOCK ABSORBER ? x su

1

99.50

99.50

FRT BOTTOM IMPACT ABSORBER ? x su

1

71.10

71.10

FRT BUMPER CARRIER ? x su

1

718.20

718.20

RH SUPPORT ? x su

1

156.90

156.90

FRT BUMPER PANEL PRIMED (M/PDC/PMA) cm

1

1,394.55

1,394.55

RH HEADLIGHT LED AHL su

1

3,755.35

3,755.35

Total Parts :

7,212.65