



Final Report

Estimate No. : **b1 71805**
Date Estimated : **14/11/2024**
Prepared By : **Jack Ng Guo Ming**

Page No. :

- ESTIMATE REPAIR FOR -

Seow Khim Chuang (Xiao Jinchuan)
Blk 10 Pari Dedap Walk
#09-21

Singapore 486062

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMU7690Y	WBA5F32070FH84693	28/08/2020	320i Sedan	52567

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper panel, RH top guide, RH support, RH trim grille with PDC include making good the front RH fender and carrying out other necessary repairs caused by the accident	1,700.00		1,700.00
To respray front bumper and front RH fender	1,923.00		1,923.00
To check electrical wiring system at the front section for proper function	177.00		177.00
To remove old PDC assembly, replace damaged parts and reconnect to bumper include conducting checks for proper function	177.00		177.00
To replace RH high intensity headlight include functionality programming and conducting checks for proper function	481.00		481.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RH BUMPER TOP GUIDE	20.55	1.00	0.00	20.55
# RH SUPPORT (NSW)	123.85	1.00	0.00	123.85
# RH TRIM GRILLE WITH PDC (M/PDC)	91.30	1.00	0.00	91.30
FRT BUMPER PANEL PRIMED (M/PDC/PMA)	1,394.55	1.00	0.00	1,394.55
RH HEADLIGHT LED AHL	3,755.35	1.00	0.00	3,755.35

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W





Final Report

SUPPLEMENTARY ITEMS

Total Labour :	4,538.00
Total Parts :	5,385.60
Total Labour & Parts (before GST) :	9,923.60
Deduction for Excess :	
Total Repair Costs less Excess:	9,923.60
GST @9%:	893.12
Grand Total :	10,816.72