

VINS

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : **ECICS LIMITED**
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/122024/7903
Date : 02-12-2024
Accident Date : 29-10-2024

Vehicle Details

Make & Model : Toyota NOAH HYBRID S-Z
Chassis No : ZWR900091172
Registration No : SNL4789C

NOT Withheld
Recovery Bk pain
14 days *Ex \$2000*

S/N	Description	Qty	Amount (\$)	
1	FRONT BONNET (ORDER)	1.00	<i>RM</i> \$850.00	✓
2	BONNET RH HINGE	1.00	<i>RM</i> \$50.00	✓
3	BONNET LH HINGE	1.00	<i>RM</i> \$50.00	✓
4	BONNET INSULATOR	1.00	<i>mi</i> \$170.00	✓
5	BONNET MOULDING	1.00	<i>mi</i> \$190.00	✓
6	BONNET LOCK	1.00	<i>RM</i> \$70.00	✓
7	BONNET LOCK CABLE	1.00	\$40.00	?
8	BONNET STAND (ORDER)	1.00	<i>R</i> \$30.00	X
9	BONNET STAND CLIP (ORDER)	1.00	<i>mi</i> \$20.00	✓
10	RH HEADLAMP	1.00	<i>Bo</i> \$1,300.00	✓
11	LH HEADLAMP	1.00	<i>Bo</i> \$1,300.00	✓
12	FRONT GRILLE ASSY	1.00	<i>CM</i> \$1,100.00	✓
13	FRONT GRILLE EMBLEM	1.00	<i>mi</i> \$50.00	✓
14	FRONT RADAR (ORDER)	1.00	\$620.00	?
15	FRONT LH BUMPER	1.00	<i>ms cm</i> \$250.00	✓
16	FRONT RH BUMPER	1.00	<i>CM</i> \$250.00	✓
17	FRONT BUMPER RH FOG LAMP	1.00	\$240.00	?
18	FRONT BUMPER LH FOG LAMP	1.00	\$240.00	?
19	FRONT BUMPER TOWING COVER	1.00	<i>mi</i> \$30.00	✓
20	FRONT RH BUMPER TOP SUPPORT BRACKET	1.00	<i>di</i> \$70.00	✓
21	FRONT LH BUMPER TOP SUPPORT BRACKET	1.00	<i>di</i> \$70.00	✓
22	FRONT BUMPER SPONGE (ORDER)	1.00	<i>CM</i> \$70.00	✓
23	FRONT BUMPER REINFORCEMENT (ORDER)	1.00	<i>RM</i> \$290.00	✓
24	FRONT BUMPER REINFORCEMENT RH BRACKET (ORDER)	1.00	<i>RM</i> \$140.00	✓
25	FRONT BUMPER REINFORCEMENT LH BRACKET (ORDER)	1.00	<i>RM</i> \$140.00	✓
26	FRONT BUMPER LOWER BEAM	1.00	\$200.00	?
27	FRONT BUMPER LOWER BEAM RH BRACKET	1.00	\$70.00	?
28	FRONT BUMPER LOWER BEAM LH BRACKET	1.00	\$70.00	?
29	FRONT BUMPER LOWER BEAM SPONGE	1.00	<i>CM</i> \$70.00	✓
30	FRONT BUMPER UNDER COVER	1.00	\$150.00	?
31	FRONT BUMPER CLIPS	10.00	<i>RM</i> \$20.00	✓

VIN'S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

32	FRONT BUMPER LOWER SPOILER (ORDER)	1.00		\$450.00	?
33	FRONT BUMPER PARKING SENSOR	2 1.00		\$720.00	?
34	FRONT PARKING SENSOR WIRE HARNESS	1.00		\$150.00	?
35	FRONT SUPPORT TOP PANEL	1.00	B	\$280.00	—
36	FRONT SUPPORT RH SIDE PANEL	1.00	B	\$270.00	—
37	FRONT SUPPORT LH SIDE PANEL	1.00	A	\$270.00	—
38	FRONT SUPPORT LOWER PANEL	1.00		\$260.00	?
39	BRACE PANEL	1.00	B	\$80.00	—
40	AIRCON CONDENSOR (ORDER) (ORI)	1.00	Pu	\$800.00	—
41	AIRCON DISCHARGE PIPE	1.00		\$280.00	?
42	RADIATOR (ORDER) (ORI)	1.00		\$920.00	?
43	RADIATOR TOP HOSE	1.00		\$40.00	?
44	RADIATOR LOWER HOSE (ORDER)	1.00		\$40.00	?
45	RADIATOR RH SIDE GUIDE	1.00	CM	\$80.00	—
46	RADIATOR LH SIDE GUIDE	1.00	CM	\$80.00	—
47	RADIATOR FAN MOTOR ASSY (ORDER)	1.00		\$750.00	?
48	RADIATOR NECK FILLER	1.00		\$40.00	?
49	RADIATOR TOP BUSH	1.00	ru	\$20.00	—
50	RADIATOR LOWER BUSH	1.00		\$20.00	?
51	RADIATOR SPARE TANK (ORDER)	1.00	du	\$130.00	—
52	WIPER TANK (ORDER)	1.00	du	\$100.00	—
53	WIPER TANK NECK	1.00		\$60.00	?
54	WIPER TANK MOTOR	1.00		\$140.00	?
55	HORN	1.00	du	\$60.00	—
56	VEHICLE APPROACHING SPEAKER ASSEMBLY	1.00		\$130.00	?
57	RESONATOR (ORDER)	1.00	CM	\$120.00	—
58	RESONATOR INTAKE HOSE	1.00	du	\$130.00	—
59	RESONATOR AIR DUCT	1.00		\$60.00	?
60	AIR CLEANER BOX (ORDER)	1.00	CM	\$450.00	—
61	AIR CLEANER BOX HOSE (ORDER)	1.00		\$60.00	?
62	AIR CLEANER BOX SUPPORT BRACKET	1.00		\$50.00	?
63	INTAKE MANIFOLD (ORDER)	1.00		\$350.00	?
64	INTAKE MANIFOLD HEAT SHIELD	1.00		\$140.00	?
65	AIRCON COMPRESSOR (ORDER)	1.00		\$2,800.00	?
66	FUSE BOX @ LH (ORDER)	1.00		\$140.00	?
67	FUSE BOX LOWER COVER	1.00		\$130.00	?
68	BATTERY TRAY	1.00	CM B	\$140.00	—
69	BATTERY TRAY BRACKET	1.00	n	\$70.00	X
70	HYBRID INVERTER ASSY (W/ CONVERTER) (ORDER)	1.00		\$4,500.00	?
71	RH ENGINE MOUNTING (ORDER)	1.00		\$420.00	?
72	RH ENGINE MOUNTING BRACKET	1.00		\$280.00	?
73	LH ENGINE MOUNTING	1.00		\$130.00	?
74	GEARBOX MOUNTING (ORDER)	1.00		\$260.00	?
75	FRONT RH FENDER (ORDER)	1.00	Bu	\$400.00	—

76	FRONT LH FENDER (ORDER)
77	FRONT RH FENDER INNER SHIELD
78	FRONT LH FENDER INNER SHIELD
79	FRONT FENDER INNER SHIELD CLIPS
80	FRONT RH FENDER GLASS (ORDER)
81	FRONT LH FENDER GLASS (ORDER)
82	FRONT RH FENDER GAP INSULATOR
83	FRONT LH FENDER GAP INSULATOR
84	FRONT WINDSCREEN GLASS (ORDER)
85	FRONT WINDSCREEN GLASS RH MOULDING (ORDER)
86	FRONT WINDSCREEN GLASS LH MOULDING (ORDER)
87	WIPER GARNISH
88	WIPER GARNISH RH SIDE COVER
89	WIPER GARNISH LH SIDE COVER
90	DASHBOARD (ORDER)
91	STEERING WHEEL AIR BAG (ORDER)
92	PASSENGER AIRBAG (ORDER)
93	RH ROOF AIRBAG (ORDER)
94	LH ROOF AIRBAG (ORDER)
95	ROOF LINING (ORDER)
96	FRONT RH SEAT BELT (ORDER)
97	FRONT LH SEAT BELT (ORDER)
98	AIRBAG ECU (ORDER)
99	AIRBAG SENSOR

1.00	Bn	\$400.00	✓
1.00		\$170.00	?
1.00		\$170.00	?
20.00	me	\$40.00	✓
1.00		\$240.00	?
1.00		\$240.00	?
1.00		\$110.00	?
1.00		\$110.00	?
1.00	CM	\$850.00	✓
1.00	Am	\$90.00	✓
1.00	Sn	\$90.00	X
1.00	Od	\$380.00	✓
1.00	mi	\$40.00	✓
1.00	mi	\$40.00	✓
1.00	CM	\$900.00	✓
1.00	Am	\$1,800.00	✓
1.00	u	\$2,200.00	✓
1.00	u	\$2,100.00	✓
1.00	u	\$2,100.00	✓
1.00	Deform	\$2,800.00	✓
1.00	Jn	\$800.00	✓
1.00	Jn	\$800.00	✓
1.00	me	\$1,700.00	✓
2.00	me	\$340.00	✓

\$43,520.00
\$4,352.00

Margin: 10%

\$47,872.00

100	FRONT NO. PLATE
101	FENDER GLASS GUM
102	WINDSCREEN GUM
103	COOLANT
104	BATTERY
105	TO REMOVE AND REPLACE FENDER GLASS
106	TO REFILL AIRCON GAS
107	TO REMOVE AND REPLACE FRONT WINDSCREEN
108	TO REMOVE AND REPLACE ROOF LINING
109	TO RESET AIRBAG SYSTEM
110	TO RESET HEADLAMP SYSTEM
111	TO REMOVE AND REPLACE DASHBOARD
112	TO RESET RADAR SYSTEM
113	TO REMOVE AND REFIX ENGINE
114	TO REPAIR DAMAGES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1.00	mi	\$40.00	✓
1.00		\$60.00	?
1.00	me	\$80.00	40Jn
1.00	me	\$80.00	40Jn
1.00	Od	\$180.00	50Jn
1.00		\$120.00	?
1.00		\$150.00	100l
1.00		\$180.00	120l
1.00		\$280.00	120l
1.00		\$280.00	200l
1.00		\$280.00	160l
1.00		\$380.00	250l
1.00		\$380.00	?
1.00		\$500.00	?
1.00		\$1,800.00	900l

VIN'S

115

TO SPRAY PAINTING

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

1.00

\$1,800.00

Subtotal w/o GST:

\$54,462.00

STATEMENT OF ACCOUNT

Dear Sirs,

We are pleased to inform you that your account with us is now closed. The balance of your account is \$54,462.00. This amount is due to you and is being credited to your bank account. The credit will be made within 7 days of the date of this statement.

Yours faithfully,

Yours faithfully,

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Yours faithfully,

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,

Yours faithfully,