

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPU24B00022900	Date of Loss:	29/10/2024
Vehicle Reg. No.:	SNL4789C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MUHAMMED FAIROL BIN ABDULLAH		
Make/Model:	TOYOTA NOAH HYBRID, 1.8 (A)	Vehicle Reg. Date:	15/08/2023
Vehicle Colour:	WHITE		
Engine No:	2ZR2V20768	Chassis No:	ZWR900091172
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	30		
Remarks:	PERSON IN CHARGE CELIA HP. 92740999 AVCLAIMS@MYCARWORKSHOP.COM.SG		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	15,742.10
Miscellaneous Items	235.00
Labour	6,180.00
Paintwork Labour	2,800.00
Towing	0.00
Gross Total (S\$)	24,957.10
+ GST 9.00% (S\$)	2,246.14
Nett Amount (S\$)	27,203.24

This claim is handled by: LAI YEAN KUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 08 Nov 2024)
Parts: M1-MPV **TOYOTA NOAH HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's **(Price-denominated Standard List)**
Print Code: Accord Auto Services Pte Ltd/SNL4789C/08/11/2024 13:18
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Windscreen <i>cm</i>	0.00	0.00	*880.00 F
2	1		*Front Windscreen Moulding <i>u</i>	0.00	0.00	*60.00 F
3	1		*Front Windscreen Rain Sensor Tap <i>?</i>	0.00	0.00	-
4	1		*Front Bonnet <i>bu</i>	0.00	0.00	*1,100.00 F
5	1		*Front Bonnet Stopper <i>u</i>	0.00	0.00	-
6	1		*Front Bonnet Seal/Rubber <i>u</i>	0.00	0.00	-
7	1		*Front Bonnet Insulator <i>cm</i>	0.00	0.00	-
8	1		*Front Bonnet Stand <i>X</i>	0.00	0.00	-
9	1		*Front Bonnet Stand Clip <i>X</i>	0.00	0.00	-
10	1		*Front Bonnet Lock <i>lt</i>	0.00	0.00	*70.00 F
11	2		*Front Bonnet Hinge <i>lt</i>	0.00	0.00	*120.00 F
12	1		*Front Wiper Garnish <i>de</i>	0.00	0.00	-
13	1		*Front Grille Top <i>lt</i>	0.00	0.00	*140.00 F
14	1		*Front Grille Emblem <i>me</i>	0.00	0.00	*50.00 F
15	1		*Front Grille Chrome Assy <i>cm</i>	0.00	0.00	*350.00 F
16	1		*Front Grille Base <i>ca</i>	0.00	0.00	-
17	1		*Front Radar <i>?</i>	0.00	0.00	*650.00 F
18	1		*Front Bumper <i>de</i>	0.00	0.00	*450.00 F
19	2		*Front Bumper Side Retainer <i>cm</i>	0.00	0.00	*96.00 F
20	1		*Front Bumper Side Lower Chrome Moulding <i>su</i>	0.00	0.00	-
21	1		*Front Bumper Lower Lip <i>?</i>	0.00	0.00	-
22	1		*Front Bumper Under Cover <i>lt</i>	0.00	0.00	-
23	1		*Front Reinforcement Bar <i>lt</i>	0.00	0.00	*250.00 F
24	1		*Front Lock Brace Panel <i>lt</i>	0.00	0.00	-
25	2		*Front Headlamp <i>bu</i>	0.00	0.00	*2,600.00 F
26	2		*Front Headlamp Lower Bracket <i>bu</i>	0.00	0.00	-
27	2		*Front Headlamp Chrome Moulding <i>cm</i>	0.00	0.00	-
28	1		*Horn <i>X</i>	0.00	0.00	*65.00 F
29	1		*Support Panel <i>lt</i>	0.00	0.00	-
30	1		*Support Panel Top Garnish <i>cm</i>	0.00	0.00	-
31	2		*Front Fender <i>lt</i>	0.00	0.00	*800.00 F
32	2		*Front Fender Shield <i>de</i>	0.00	0.00	-
33	2		*Front Fender Side Cover	0.00	0.00	-
34	1		*Front LH Fender Inner Panel <i>repair</i>	0.00	0.00	-
35	1		*Aircon Condenser <i>lt</i>	0.00	0.00	*550.00 F
36	1		*Aircon Condenser Pipe <i>?</i>	0.00	0.00	-
37	1		*Aircon Condenser Hose <i>?</i>	0.00	0.00	-
38	1		*Radiator <i>lt</i> <i>photo</i>	0.00	0.00	*600.00 F
39	1		*Radiator Top Hose <i>?</i>	0.00	0.00	-
40	1		*Radiator Lower Hose <i>?</i>	0.00	0.00	-
41	2		*Radiator Stopper Upper <i>X</i>	0.00	0.00	-
42	2		*Radiator Stopper Lower <i>?</i>	0.00	0.00	-
43	1		*Radiator Fan Motor, Blade & Cowling <i>?</i>	0.00	0.00	*700.00 F
44	1		*Washer Tank <i>de</i>	0.00	0.00	*55.00 F
45	1		*Washer Tank Cap	0.00	0.00	-

Accord Auto Services Pte Ltd/SNL4789C/08/11/2024 13:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Part No.	Particulars	%Disc	%Depr	Amount
1	*Spare Tank <i>de /</i>	0.00	0.00	*175.00 F
1	*Spare Tank Cap <i>X</i>	0.00	0.00	-
1	*Airduct Hose @ Fix At Suuport Panel <i>?</i>	0.00	0.00	-
1	*Air Cleaner Box Assy <i>cm /</i>	0.00	0.00	-
1	*Battery Tray <i>cm /</i>	0.00	0.00	-
1	*Battery Tray Bracket <i>?</i>	0.00	0.00	-
1	*Fuse Box - Cover <i>?</i>	0.00	0.00	-
1	*Fuse Box <i>?</i>	0.00	0.00	-
1	*Engine Mounting Set <i>?</i>	0.00	0.00	-
1	*Intake Manifold	0.00	0.00	*380.00 F
1	*Air Intake Resonator <i>?</i>	0.00	0.00	-
1	*Hybird Coolant Hose <i>?</i>	0.00	0.00	-
1	*Injector Harnes <i>?</i>	0.00	0.00	-
1	*Fuel Injector <i>?</i>	0.00	0.00	-
1	*Alternator <i>?</i>	0.00	0.00	-
1	*Starter <i>?</i>	0.00	0.00	-
1	*Aircon Compressor <i>?</i>	0.00	0.00	-
1	*Engine Bay Harness <i>?</i>	0.00	0.00	-
1	*Dashboard <i>cm /</i>	0.00	0.00	-
1	*LH Airbag <i>AG /</i>	0.00	0.00	*1,450.00 F
1	*RH Airbag <i>AG /</i>	0.00	0.00	*1,600.00 F
1	*LH Roof Airbag <i>AG /</i>	0.00	0.00	-
1	*RH Roof Airbag <i>AG /</i>	0.00	0.00	-
1	*Roof Linning <i>de /</i>	0.00	0.00	-
1	*Front LH Seat Belt <i>AG /</i>	0.00	0.00	-
1	*Front LH Seat Belt Bucket <i>X</i>	0.00	0.00	-
1	*Front RH Seat Belt <i>AG /</i>	0.00	0.00	-
1	*Front RH Seat Belt Bucket <i>X</i>	0.00	0.00	-
2	*Airbag Sensor <i>AG /</i>	0.00	0.00	*360.00 F
1	*Airbag Control Unit <i>AG /</i>	0.00	0.00	-
1	*Front Bumper Sponge <i>cm /</i>	0.00	0.00	-
2	*Front Reinforcement Arm <i>HA /</i>	0.00	0.00	-
1	*Front Lower Reinforcement <i>?</i>	0.00	0.00	-
2	*Front Headlamp HID/LED Control Unit <i>cm /</i>	0.00	0.00	-
2	*Front Headlamp Control Unit <i>?</i>	0.00	0.00	-
2	*Foglight <i>RH-cm / LH-X</i>	0.00	0.00	*760.00 F
2	*Front Bumper Sensor <i>?</i>	0.00	0.00	-
1	*Front Bumper Sensor Harness <i>?</i>	0.00	0.00	-
1	*Front LH Radiator Airduct <i>cm /</i>	0.00	0.00	-
1	*Front RH Radiator Airduct <i>cm /</i>	0.00	0.00	-

F=Franchise part.

Sub Total (\$\$)	14,311.00
+ Margin on L,N Items 10.00% (\$\$)	1,431.10
Total Parts (\$\$)	15,742.10

Accord Auto Services Pte Ltd/SNL4789C/08/11/2024 13:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT BOTH SIDE FENDER SHIELD CLIPS <i>AL</i> ✓		
2	1	FRONT BUMPER & GRILLE CLIPS <i>AL</i> ✓	20	40.00
3	1	FRONT WINDSCREEN SEALANT <i>AL</i> ✓		40.00
4	1	NUMBER PLATE WITH FRAME <i>AL</i> ✓	40	80.00
5	1	RADIATOR TOP GARNISH & UNDER ENGINE COVER CLIPS <i>AL</i> ✓	35	45.00
			40	50.00
Sub Total (\$\$)				235.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	Spray Painting to All Affected Areas	New	1900	2,800.00
(*Pearl Colour Basis. Including Body On Affected Area)				

Labour Items

2	Labour Remove / Refix Accident Damages Parts To Knock , Jack, Cut Weld And Realign Accident Affected Area	New	2000	3,800.00
(* Including Body Alignment On Affected Area)				
3	Check Wiring System & Light	New	80	120.00
4	To Remove/Replace Intake Manifold	New	150	180.00
5	To Repair/Adjust/Realign Front Main Chassis & Crossmember	New	250	350.00
6	To Remove/Refix/Replace Front Both Seat Belt & Buckle	New	150	200.00
7	To Remove/Refix/Replace The Necessary Attachment In Connection LH & RH Airbag, Dashboard ,Steering Column,Clock Spring & Etc...	New	300	500.00
8	Computer Diagnostic (Reset Airbag Control Unit & Necessary In Connect)	New	200	300.00
9	To Remove/Replace/Refix Support Panel, Radiator & Aircon Condenser (Remove pipe,hose & Etc... Top Up Coolant, Aircon Gas & Etc...)	New	180	280.00
10	Computer Diagnostic After Repair(*Bumper Sensor & etc...)	New	250	350.00
11	To Remove/ Refix/ Reinstall Front Windscreen	New		100.00

Gross Labour Cost (\$\$) 8,980.00

Accord Auto Services Pte Ltd/SNL4789C/08/11/2024 13:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes:
 Passu
 Hp 90010068
 18 days
 L/S
 11/11/24
 EXCHG. TBA
 Repair
 Rep after repair



Toyota Noah Hybrid 1.8A S-Z

\$182,888 Instalment \$1,533/mth

PREMIUM AD

Shortlist

Loan Calculator

- Overview
- Financial
- Leasing
- Photo
- Research

Depreciation	\$19,820 / year
Reg. Date	25-Jul-2023 (8yrs 8mths 12days COE left)
Manufactured	2023
Mileage	11,000 km (8.4k / year)
Transmission	Auto
Engine Cap	1,797 cc
Road Tax	\$974 / year
Power	103.0 kW (138 bhp) View specs of the Toyota Noah
Curb Weight	1,670 kg
Fuel Type	Petrol-Electric
COE	\$119,399
OMV	\$31,320
ARF	\$20,848
Dereg Value	\$111,155 as of today
No. of Owners	1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	669J
Vehicle Details	
Vehicle No.:	SNL4789C
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID S-Z
Primary Colour:	White
Manufacturing Year:	2023
Engine No.:	2ZR2V20768
Chassis No.:	ZWR900091172
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$30,810.00
Original Registration Date:	15 Aug 2023
First Registration Date:	15 Aug 2023
Transfer Count:	0
Actual ARF Paid:	\$20,134.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2033
PARF Rebate Amount:	\$15,100.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2033
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$121,000.00
COE Rebate Amount:	\$105,940.00
Total Rebate Amount:	\$121,040.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 12 Nov 2024

OK