



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: CHARMAINE KONG			Ref: CS/LPC24110191/Anh3e2(N) Date: 14/10/2025 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	XE 2467M	Veh. Inspected	SGQ 2882K
	Policy No.		Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030121	Excess (\$)	0.00
	Assign From	CHARMAINE KONG	Assign Date	11/11/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA VELLFIRE	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTNGF3DH208023954	Colour	BLACK
	Odometer	56249 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/45 R19	KUMHO	6 mm
	L/H Front Tyre	245/45 R19	KUMHO	6 mm
	R/H Rear Tyre	245/45 R19	KUMHO	6 mm
	L/H Rear Tyre	245/45 R19	KUMHO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	02/11/2024	Inspection Date	12/11/2024
	Survey held at	2020 SPRAY PAINTING PTE LTD 8 KAKI BUKIT AVENUE 4, #03-19, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	