

2020 SPRAY PAINTING PTE LTD
8 KAKI BUKIT AVE 4
#03-19 PREMIER @KAKI BUKIT
SINGAPORE 415875

TO	: LONPAC	DATE	: 12/11/2024
VEHICLE NO	: SGQ2882K (2020)		
VEHICLE MODEL	: TOYOTA VELLFIRE		
CHASSIS NO	: JTNGF3DH208023954		

Hui Rong

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Dehnd</i>	1	\$ 1,105.40	\$ 1,105.40 ✓
2	REAR BUMPER SIDE HOLDER <i>alc</i>	1	\$ 146.90	\$ 146.90 ✓
3	REAR BUMPER REFLECTOR <i>new</i>	1	\$ 123.90	\$ 123.90 x
4	REAR BUMPER SENSOR <i>new</i>	1	\$ 367.00	\$ 367.00 x
5	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 25.00	\$ 100.00 ✓
6	REAR BUMPER TOW COVER <i>new</i>	1	\$ 49.40	\$ 49.40 x
7	TAILLAMP <i>cracked</i>	1	\$ 689.20	\$ 689.20 ✓
8	TAILLAMP LOWER APRON <i>Dehnd</i>	1	\$ 394.30	\$ 394.30 ✓
9	TAILLAMP LOWER APRON RETAINER <i>new</i>	1	\$ 98.20	\$ 98.20 +
10	REAR FENDER <i>Dehnd</i>	1	\$ 2,355.80	\$ 2,355.80 ✓
11	REAR FENDER INNER SHIELD	1	\$ 236.80	\$ 236.80 x
12	REAR FENDER INNER TRIM	1	\$ 2,024.20	\$ 2,024.20 x
13	REAR AIR CON BLOWER	1	\$ 345.40	\$ 345.40 x
14	REAR BLIND SPOT MODULE	1	\$ 2,008.30	\$ 2,008.30 x

4791.60
3593.70

TOTAL PRICE: \$ 13,194.80
 LESS 25% \$ 3,298.70
 SUB TOTAL PRICE: \$ 9,896.10

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 ✓
2	REAR BUMPER STICKER WRAP <i>n</i>	1	\$ 400.00	\$ 400.00 ✓
3	TAILLAMP LOWER APRON CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00 ✓
4	TAILLAMP LOWER APRON STICKER WRAP <i>n</i>	1	\$ 200.00	\$ 200.00 ✓
5	REAR FENDER INNER SHIELD CLIPS (SET) <i>3AP</i>	1	\$ 30.00	\$ 30.00 +
6	REAR FENDER INNER TRIM CLIPS (SET) <i>3AP</i>	1	\$ 30.00	\$ 30.00 +
7	REAR FENDER SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00 ✓
8	REAR FENDER GLASS SEALANT <i>n</i>	1	\$ 40.00	\$ 40.00 ✓
9	REAR FENDER STICKER WRAP <i>n</i>	1	\$ 400.00	\$ 400.00 ✓

TOTAL: \$ 1,230.00

970

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	500	
3	WIRING CHECK	\$ 50.00	30	
4	TO REMOVE REAR BUMPER SENSOR	\$ 100.00	50	
5	TO REMOVE UPHOLSTERY	\$ 150.00	40	
6	TO SPRAY TUFF COAT	\$ 150.00	60	
5	TO REMOVE REAR FENDER GLASS	\$ 120.00	50	
6	TO REMOVE AIR CON BLOWER & TO TOP UP AIR CON GAS	\$ 120.00	X	
TOTAL:		\$ 2,390.00		

ESTIMATE REPORT

TOTAL PARTS COST: \$ 10,886.80

TOTAL LABOUR COST: \$ 2,890.00

TOTAL REPAIR COST: \$ 13,776.80

1330

Total: 5893.70

W/S: 4.7K.

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: