



P/P \$ 5762.18 QUOTATION Not Authorised as means 11/11/24 3 days whisper before party.

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 1
DOCUMENT NO.: 1563
DOCUMENT DATE: 05/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: 1
WIP NO.: 22298
REF. NO.:
DATE IN:
EXT. WTY: 27/05/2029
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: CX5 2.0 AT M-HYBRID LUXURY SPO
CHASSIS NO.: JM6KF2W7AR0102055
ENGINE NO.: PE10761735
REG NO.: SNR1443M
REGN DATE: 28/05/2024

DESCRIPTION:

Item	Description	Qty.	Unit Price SGD	Stk/Status	Gross amount SGD	GST Code
NOTES	CHINA TAIPING TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE FRT BUMPER & GRILLE TOP. 792			792	2,376.00	S
SUB	AND ALL ACCIDENT AFFECTED AREA. TO RESPRAY FRT BUMPER, GRILLE TOP & BONNET. 758			758	3,024.00	S
SUB	TO TRANSFER FRONT SENSORS. 180			180	330.00	S
SUB	TO SUPPLY NUMBER PLATE. 500			500	140.00	S ✓
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 120			120	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. 180			180	300.00	S
SUB	SUNDRIES.				50.00	S 20
KSD5-50-031A	BUMPER, FRONT KF De/can	1.00	994.32	*NO STOCK	994.32	S ✓
KSD4-50-151	BRACKET RHF BUMP LWR KF nu	1.00	11.13	*NO STOCK	11.13	S ✓
KSD4-50-161	BRACKET LHF BUMP LWR KF nu	1.00	11.13	*NO STOCK	11.13	S ✓
KSD4-50-103	COVER RHF BUMPER KF 11	1.00	14.84	*NO STOCK	14.84	S X
KSD4-50-104	COVER LHF BUMPER KF 1w1	1.00	15.77	STOCK	15.77	S ✓
KD45-50-1K5A	PIN, LOCATOR nu	2.00	2.36	*NO STOCK	4.72	S ✓
KB8A-50-0T1A	RETAINER(R), FRT KF 11	1.00	15.77		15.77	S X

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

TRANS EUROKARS Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 2
DOCUMENT NO.: 1563
DOCUMENT DATE: 05/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 22298
REF. NO.:
DATE IN: 27/05/2029
EXT. WTY: 0
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: CX5 2.0 AT M-HYBRID LUXURY SPO
CHASSIS NO.: JM6KF2W7AR0102055
ENGINE NO.: PE10761735
REG NO.: SNR1443M
REGN DATE: 28/05/2024

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
KB8A-50-0U1A	RETAINER(L),FRT KF	1.00	15.77	*NO STOCK	15.77	S X
KSD4-50-153	BRACKET(R),FRT BUMPER	1.00	39.53	STOCK	39.53	S X
KSD4-50-163	BRACKET LHF BUMPER KF/KG4	1.00	39.53	*NO STOCK	39.53	S X
KSD6-50-032	FRT BUMPER LWR KF IPM5	1.00	1,039.33	*NO STOCK	-1,039.33	S /
B45A-56-146A	FASTENER	5.00	2.36	*NO STOCK	- 11.80	S /
BGV4-56-145	CLIP	10.00	2.36	*NO STOCK	- 23.60	S /
KSD4-50-180A	HOLDER LICENSE PLATE KF/KG4	1.00	101.48	*NO STOCK	101.48	S X
KSD4-50-A11	BBCOVER,TOWING HOOK-	1.00	37.68	*NO STOCK	37.68	S X
KPF1-50-111	FOAM,BUMPER FRT KF/KG4	1.00	55.30	*NO STOCK	55.30	S X
FD01-68-AC3	FASTENER	2.00	5.31	*NO STOCK	10.62	S X
KPF1-50-070A	REINF FRT BUMPER KF	1.00	596.58	STOCK	596.58	S X
G001-67-061	PAD,PROTECTOR	2.00	7.08	*NO STOCK	- 14.16	S /
KSD5-50-7J0	MOULD RHF FRT BUMPER KF IPM5	1.00	337.82	*NO STOCK	337.82	S X
KSD5-50-7K0	MOULD LHF FRT BUMPER KF IPM5	1.00	337.82	*NO STOCK	337.82	S X
KSD4-50-7E1A	BIGRILLE,UP,RADIATOR KF	1.00	126.01	STOCK	126.01	S X
TK21-50-355	RIVET	8.00	7.42	STOCK	- 59.36	S /
S51S-51-833	RIVET,SPLASH SHIELD	8.00	3.12	*NO STOCK	- 24.96	S /
K0A2-50-710A	GRILLE,RADIATOR KG	1.00	1,363.90	*NO STOCK	-1,363.90	S /
KSH7-51-031D	HEADLAMP RH W/AFS KF	1.00	4,087.61	*NO STOCK	4,087.61	S X
KSH7-51-041D	HEADLAMP LH W/AFS KF	1.00	4,087.61	*NO STOCK	4,087.61	S X

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



TRANSEUROKARS
Eurokars Group

Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402
23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 3
DOCUMENT NO.: 1563
DOCUMENT DATE: 05/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: 1
WIP NO.: 22298
REF. NO.:
DATE IN:
EXT. WTY: 27/05/2029
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: CX5 2.0 AT M-HYBRID LUXURY SPO
CHASSIS NO.: JM6KF2W7AR0102055
ENGINE NO.: PE10761735
REG NO.: SNR1443M
REGN DATE: 28/05/2024

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
DFR5-56-145	CLIP	2.00	6.49	*NO STOCK	12.98	S
FB01-50-133C	NUT,CLIP	4.00	3.29	STOCK	13.16	S
KA0G-51-730	MASCOT,FRONT KF	1.00	113.71	*NO STOCK	113.71	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	* GST Code	Rate	Service/Goods	GST
Parts 13,618.00	O	-		-
Surcharge 0.00	S	9.00%	20,088.00	1,807.92
Labour 6,470.00				
Menus 0.00				

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross	20,088.00	1,807.92	21,895.92
Less: Deposit**	0.00	0.00	0.00
Amount Due	20,088.00	1,807.92	21,895.92

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 1
DOCUMENT NO.: 1630
DOCUMENT DATE: 03/12/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV:
CSP/OP CODE: Wong Chun Wei
DEPT: I
WIP NO.: 22298
REF. NO.:
DATE IN:
EXT. WTY: 27/05/2029
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: CX5 2.0 AT M-HYBRID LUXURY SPO
CHASSIS NO.: JM6KF2W7AR0102055
ENGINE NO.: PE10761735
REG NO.: SNR1443M
REGN DATE: 28/05/2024

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross GST	
					amount	Code
			SGD		SGD	
NOTES	CHINA TAIPING TP CLAIM				0.00	O
SUB	MZ CX5 UBI				792.00	S
	TO REMOVE & REPLACE FRT BUMPER & GRILLE TOP. AND ALL ACCIDENT AFFECTED AREA. - PO24171					
SUB	MZ CX5 UBI				756.00	S
	TO RESPRAY FRT BUMPER, GRILLE TOP & BONNET. - PO24171					
SUB	MZ CX5 UBI				180.00	S
	TO TRANSFER FRONT SENSORS. - PO24171					
SUB	MZ CX5 UBI				140.00	S
	TO SUPPLY NUMBER PLATE. - PO24171					
SUB	MZ CX5 UBI				120.00	S
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. - PO24171					

**This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

**Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.*



TRANSEUROKARS
Eurokars Group

Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6846 1700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417



MAZDA

QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 2
DOCUMENT NO.: 1630
DOCUMENT DATE: 03/12/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV:
CSP/OP CODE: Wong Chun Wei
DEPT: I
WIP NO.: 22298
REF. NO.:
DATE IN:
EXT. WTY: 27/05/2029
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: CX5 2.0 AT M-HYBRID LUXURY SPO
CHASSIS NO.: JM6KF2W7AR0102055
ENGINE NO.: PE10761735
REG NO.: SNR1443M
REGN DATE: 28/05/2024

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	MZ CX5 UBI TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. - PO24171				180.00	S
SUB	MZ CX5 UBI SUNDRIES. - PO24171				20.00	S
KSD5-50-031A	BUMPER, FRONT KF	1.00	994.32	*ISSUED	994.32	S
KSD4-50-151	BRACKET RHF BUMP LWR KF	1.00	11.13	*ISSUED	11.13	S
KSD4-50-161	BRACKET LHF BUMP LWR KF	1.00	11.13	*ISSUED	11.13	S
KSD4-50-104	COVER LHF BUMPER KF	1.00	15.77	*ISSUED	15.77	S
KD45-50-1K5A	PIN, LOCATOR	2.00	2.36	*ISSUED	4.72	S
KSD6-50-032	FRT BUMPER LWR KF IPM5	1.00	1,039.33	*ISSUED	1,039.33	S
B45A-56-146A	FASTENER	5.00	2.36	*ISSUED	11.80	S
BGV4-56-145	CLIP	10.00	2.36	*ISSUED	23.60	S
G001-67-061	PAD, PROTECTOR	2.00	7.08	*ISSUED	14.16	S
TK21-50-355	RIVET	8.00	7.42	*ISSUED	59.36	S
S51S-51-833	RIVET, SPLASH SHIELD	8.00	3.12	*ISSUED	24.96	S
KOA2-50-710A	GRILLE, RADIATOR KG	1.00	1,363.90		1,363.90	S

	GST Code	Rate	Service/Goods	GST
Parts	O	-		-
Surcharge	S	9.00%	5,762.18	518.60
Labour				
Menus				

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross	5,762.18	518.60	6,280.78
Less: Deposit**	0.00	0.00	0.00
Amount Due	5,762.18	518.60	6,280.78

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417