(08/11/13) wef
ASS. REC. BY: MCreus

REF: CS/C7/24110192/Unh3e2

From: Date:	Veh No: 5NR 1443M Yr Regn: 28/05/24
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TE / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or CA/
To Inspect Vehicle No: $\leq N / 2 \mid \Psi \Psi \mid M$	Make: mc 2dg CX-5' c.c 1998
at Workshop m/s Trong Eurle	Colour Bhu A/C: Insured / Std / NI / NA
of	Sp.Reading / 2 488 T/Radio: Insured / Std / NI / NA
Insured: SMF 3631D	Eng/No:
Policy No.	C/NO: JM6KF2W7AR0102053
Claims No.	Gen. Cond; Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorde / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (SJRim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 225/5-5-7/9 R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO)YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. S mm L/Bal. S mm
Est. Repairs: 7 days Res.: Yes or No	D.O.A. 01/11/24 D.O.I. 11/11/24
Lum Sum: /-3./ % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: LAG/17 R-9	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction 9,7 2/4.	
12/24 PIP \$ 1-762.18 inhound MI	2 wry. (Red, \$ 14325.82,71%)
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 3
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee:	
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$
	TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	502A
Vehicle No.:	SNR1443M
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2024
Vehicle Make:	MAZDA
Vehicle Model:	CX-5 2.0 AT M-HYBRID LUXURY SPORTS I7
Primary Colour:	Blue
Manufacturing Year:	2024
Engine No.:	PE10761735
Chassis No.:	JM6KF2W7AR0102055
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$22,530.00
Original Registration Date:	28 May 2024
First Registration Date:	28 May 2024
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$23,542.00 [[]]
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 May 2034
PARF Rebate Amount: Intended COE Rebate Details	\$17,656.00
COE Expiry Date:	27 May 2034
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$105,002.00
COE Rebate Amount:	\$100,203.00
Total Rebate Amount: Message	\$117,859.00
You will not be eligible for any COF rebate from the cur	rent COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 11 Nov 2024

View page in Desktop

Terms of Service | Privacy | PDPA

Compare

sacarmart			Login Sign Up
New Used Electric Loan	Rent Sell Directory	y e-Shop Insurance	Articles Forum Resources
Home Used Cars Listing All Category Filter Q 2	Search		Save Search
리 Any status X 2022 X Sort by Any Status, Date Posted (Newest)			
4 Vehicles Car Make Ca	ar Model Price Range	Depreciation	2022 Mileage
EMAINS.	Exquisitely maintained insi your preference. Flexible lo	twork! Stunning white exteride out, view with high expension available, all trade ins a non obligation viewing! Stri	Jun-2022 The symths COE left) 47,000 km 1,998 cc Trior paired with black interior! The ectations! Flexible viewing hours at re welcomed. Contact our sales lectly by appointment only. Compare
		/mth \$2 Owners years loan, PHV loan, full lo	Feb-2022 s 3mths COE left) 13,000 km 1,998 cc oan and high bank loan. Balloon d! Trade in welcome. Viewing by Compare
SOLD	Mazda CX-5 2.0A Luxury 1 Owner Unit! White in colo	or. \$0 driveaway available! s interior, huge boot space.	27-May-2022 (7yrs 6mths COE left) (7) N.AK 1,998 cc \$1 Owner Well maintained. This good looking High trade in available, call for a no
SOLD	from trusted company wit years. Must view the car to	View Similar maintained by agent. High th a peace of mind. Carzwor appreciate. Trade in and lo appointment to view today	23-Aug-2022 (7yrs 9mths COE left) (2) N.AK 21,998 cc (2) 1 Owner trade in for your used vehicle. Buy an available. Call our friendly

PREMIUM AD

Compare



PIP \$ 1762.18

1563

22298

05/11/2024

Lee Yao Sheng

CODE: CUSTOMER:

MODEL:

REG NO .:

C0006

CHINA TAIPING (SINGAPORE) PTE LT

CX5 2.0 AT M-HYBRID LUXURY SPO

ADDRESS: 3 ANSON ROAD

CONTACT NO.: 6389 6111

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

JM6KF2W7AR0102055

PE10761735

28/05/2024

SNR1443M

PAGE NO .: DOCUMENT NO .: DOCUMENT DATE:

POS ID:MU

PRINTED BY: SERVICE ADV:

CSP/OP CODE: Lee Yao Sheng

DEPT: WIP NO .:

REF. NO .:

DATE IN: EXT. WTY: MILEAGE:

27/05/2029

REGN DATE:

CHASSIS NO .:

ENGINE NO.:

DESCRIPTION:				Stk/Status	Gross	GST
Item	Description		Qty. U	nit Price	amount (
				SGD	SGD	
NOTES	CHINA TAIPING TP CLAIM				0.00	0
SUB	TO REMOVE & REPLACE FRT BUMPER &	792		792	2,376.00	S
	GRILLE TOP.					
	AND ALL ACCIDENT AFFECTED AREA.	7:-				
SUB	TO RESPRAY FRT BUMPER, GRILLE TOP &	758		758	3,024.00	S
	BONNET.			0		
SUB	TO TRANSFER FRONT SENSORS.			180	330.00	S
SUB	TO SUPPLY NUMBER PLATE.			sin	140.00	S
SUB	TO CHECK ELECTRICAL SYSTEM			120	250.00	S
	FOR PROPER FUNCTIONING.			18	1 200 00	C
SUB	to reprogramme after the			100		S
	ACCIDENT REPAIR WORKS.			1 40	50.00	SZI
SUB	SUNDRIES.		1.00	NO STOCK	-994.32	S
	BIBUMPER, FRONT KF De/CA7		1.00	994.32 *NO STOCK	11.13	5
KSD4-50-151	BRACKET RHF BUMP LWR KF		1.00	11.13 *NO STOCK	- 11.13	5
KSD4-50-161	BRACKET LHF BUMP LWR KF		1.00	11.13 *NO STOCK	14.84	SX
KSD4-50-103	COVER RHF BUMPER KF		1.00	14.84 *NO STOCK	15.77	5-
KSD4-50-104	COVER LHF BUMPER KF 1~1		1.00	15.77 STOCK		5-
KD45-50-1K5A			2.00	2.36 *NO STOCK	∠4.72 15.77	5 7
KB8A-50-0T1A	RETAINER(R), FRT KF		1.00	15.77	15.//	3 /



TRANSELROKARS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A



^{*}This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



CODE:

C0006

CUSTOMER:

CHINA TAIPING (SINGAPORE) PTE LT

CX5 2.0 AT M-HYBRID LUXURY SPO

3 ANSON ROAD ADDRESS:

CONTACT NO.: 6389 6111

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

PAGE NO .: DOCUMENT NO .: DOCUMENT DATE: 2 1563 05/11/2024

MU

PRINTED BY: SERVICE ADV:

CSP/OP CODE:

Lee Yao Sheng

Lee Yao Sheng

DEPT:

POS ID:

WIP NO .:

22298

REF. NO .:

DATE IN: EXT. WTY: MILEAGE:

27/05/2029

CHASSIS NO.: JM6KF2W7AR0102055 ENGINE NO .: REG NO .:

MODEL:

PE10761735 SNR1443M

REGN DATE:

28/05/2024

DESCRIPTION:		Oty	Stk/Status Unit Price	Gross	
tem	Description	Qty.		amount (Code
			SGD NO STOCK		- A
KB8A-50-0U1A	RETAINER(L), FRT KF	1.00	15.77 STOCK	15.77	S
SD4-50-153	BRACKET(R), FRT BUMPER	1.00	39.53 *NO STOCK	39.53	S 7X
(SD4-50-163	BRACKET LHF BUMPER KF/KG4 _^ A	1.00	39.53 *NO STOCK	39.53	
(SD6-50-032	EDT RIMADER IM/R KEIPMS	1.00	1,039.33 *NO STOCK	-1,039.33	S
345A-56-146A	EACTENED	5.00	2.36 NO STOCK	- 11.80	5
BGV4-56-145	CLIP	10.00	2.36 *NO STOCK	- 23.60	S
SD4-50-180A	HOLDER LICENSE PLATE KF/KG4 NF	1.00	101.48 *NO STOCK	101.48	-
(SD4-50-A11	BBCOVER, TOWING HOOK-	1.00	37.68 *NO STOCK	37.68	SX
KPF1-50-111	FOAM, BUMPER FRT KF/KG4	1.00	55.30 *NO STOCK	55.30	SX
FD01-68-AC3	FASTENER	2.00	5.31 *NO STOCK	10.62	5 %
KPF1-50-070A	REINF FRT BUMPER KF	1.00	596.58 STOCK	596.58	
G001-67-061	PAD, PROTECTOR	2.00	7.08 *NO STOCK	- 14.16	5 3
KSD5-50-710	MOULD RHF FRT BUMPER KF IPM5 AS	1.00	337.82 *NO STOCK	337.82	0
KSD5-50-7K0	MOULD LHF FRT BUMPER KF IPM5 1	1.00	337.82 *NO STOCK	337.82	~
	ABIGRILLE, UP. RADIATOR KF	1.00	126.01 STOCK	126.01	SX
TK21-50-355	RIVET	8.00	7.42 STOCK	59.36	S
S51S-51-833	RIVET, SPLASH SHIELD	8.00	3.12 *NO STOCK	- 24.96	
K0A2-50-710A	A GRILLE, RADIATOR KG	1.00	1,363.90 *NO STOCK	1,363.90	
KSH7-51-031		1.00	110 010 011	4,087.61	~ *
KSH7-51-041		1.00	4,087.61	4,087.61	S /



TRANSEUROKARS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres:

5 Ubi Close Singapore 408605 23 Leng Kee Road Singapore 159095
5ales Tel: 6395 8888 Service Tel: 6395 8899
5ales Fax: 68461700 Service Fax: 6744 9402 5ales Fax: 6476 7073 Service Fax: 6476 7417

^{*}This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



CODE:

C0006

CUSTOMER:

CHINA TAIPING (SINGAPORE) PTE LT

CX5 2.0 AT M-HYBRID LUXURY SPO

ADDRESS:

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

DOCUMENT NO .: DOCUMENT DATE: 1563

MU

3

05/11/2024

POS ID:

PAGE NO .:

PRINTED BY:

SERVICE ADV:

CSP/OP CODE:

Lee Yao Sheng

Lee Yao Sheng

DEPT:

WIP NO .:

22298

REF. NO .: DATE IN:

EXT. WTY: MILEAGE:

27/05/2029

ENGINE NO .: REG NO .: **REGN DATE:**

MODEL:

PE10761735 SNR1443M 28/05/2024

CHASSIS NO.: JM6KF2W7AR0102055

DESCRIPTION:

CONTACT NO.: 6389 6111

Item	Description	Qty. Unit Price	Gross GST amount Code	
		SGD *NO STOCK	SGD	
DFR5-56-145	CLIP AA	2.00 6.49 STOCK 4.00 3.29 NO STOCK	12.98 S	
FB01-50-133C KA0G-51-730	MASCOT, FRONT KF 11	4.00 3.29 *NO STOCK 1.00 113.71	113.71 S	

	•	GST Code	Rate	Service/Goods	GST
Parts	13,618.00	0	-		
Surcharge			9.00%	20,088.00	1,807.92
Labour	6,470.00				
Menus	0.00	e visual inchection	n and she	uld there be more dama	ges found during

the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross .	20,088.00	1,807.92	21,895.92
Less: Deposit*	0.00	0.00	0.00
Amount Due	20,088.00	1,807.92	21,895.92

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE No.

Date:

Customer signature

Authorised signature

TRANSEUROKARS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres:

5 Ubi Close Singapore 408605
5 ales Tel: 6395 8888 Service Fax: 6744 9402
5 ales Fax: 68461700 Service Fax: 6744 9402
5 Ubi Close Singapore 408605
5 ales Fax: 68461700 Service Fax: 6744 9402
5 ales Fax: 6476 7073 Service Fax: 6476 7417



CODE: CUSTOMER: C0006

CHINA TAIPING (SINGAPORE) PTE LT

ADDRESS: 3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

DOCUMENT DATE: POS ID:MU

PRINTED BY:

DOCUMENT NO .:

PAGE NO .:

SERVICE ADV:

CSP/OP CODE:

Wong Chun Wei

22298

03/12/2024

Wong Chun Wei

1630

CONTACT NO.: 6389 6111

MODEL:

CX5 2.0 AT M-HYBRID LUXURY SPO

CHASSIS NO.: JM6KF2W7AR0102055 ENGINE NO .:

PE10761735

REG NO .: REGN DATE: SNR1443M 28/05/2024 DEPT: WIP NO .:

REF. NO .: DATE IN:

EXT. WTY: MILEAGE:

27/05/2029

DESCRIPTION:

Item	Description	Qty, Unit Price	Gross G amount Co	
		SGD	SGD	ouc
NOTES	CHINA TAIPING TP CLAIM		0.00	0
SUB	MZ CX5 UBI		792.00	S
	to remove & replace frt bumper &			
	GRILLE TOP.			
	AND ALL ACCIDENT AFFECTED AREA.			
	- PO24171			
SUB	MZ CX5 UBI		756.00	S
	to respray frt bumper, grille top &			
	BONNET.			
	- PO24171			
SUB	MZ CX5 UBI		180.00	S
	to transfer front sensors.			
	- PO24171			
SUB	MZ CX5 UBI		140.00	S
	to supply number plate.			
	- PO24171			
SUB	MZ CX5 UBI		120.00	S
	TO CHECK ELECTRICAL SYSTEM			
	FOR PROPER FUNCTIONING.			
	- PO24171			



TRANS**EUROKARS**Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

5 Ubi Close Singapore 408605

Showrooms & Service Centres:

23 Leng Kee Road Singapore 159095 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Tel: 6603 6118 Service Tel: 6603 6128 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417

^{*}This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



CODE:

C0006

CUSTOMER:

CHINA TAIPING (SINGAPORE) PTE LT

ADDRESS:

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER SINGAPORE 079909

PAGE NO .:

DOCUMENT NO .:

2 1630

DOCUMENT DATE:

03/12/2024 MU

POSID:

PRINTED BY:

Wong Chun Wei

SERVICE ADV:

CSP/OP CODE:

Wong Chun Wei 22298

CONTACT NO.: 6389 6111

MODEL:

CX5 2.0 AT M-HYBRID LUXURY SPO

CHASSIS NO.: JM6KF2W7AR0102055 ENGINE NO .:

PE10761735

REG NO .: REGN DATE: SNR1443M 28/05/2024 WIP NO .: REF. NO .:

DEPT:

DATE IN:

EXT. WTY:

27/05/2029

MILEAGE:

DESCRIPTION:

Item	Description	Qty.	Unit Price SGD	Stk/Status	Gross amount SGD	
SUB	MZ CX5 UBI TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS PO24171	5			180.00	S
SUB	MZ CX5 UBI SUNDRIES. - PO24171				20.00	S
KSD5-50-031AF	BIBUMPER, FRONT KF	1.00	994.32	*ISSUED	994.32	S
KSD4-50-151	BRACKET RHF BUMP LWR KF	1.00	11.13	*ISSUED	11.13	S
KSD4-50-161	BRACKET LHF BUMP LWR KF	1.00	11.13	*ISSUED *ISSUED	11.13	S
KSD4-50-104	COVER LHF BUMPER KF	1.00	15.77	*ISSUED	15.77	S
KD45-50-1K5A	PIN,LOCATOR	2.00	2.36	*ISSUED	4,72	S
KSD6-50-032	FRT BUMPER LWR KF IPM5	1.00	1,039.33	*ISSUED	1,039.33	S
B45A-56-146A	FASTENER	5.00	2.36	*ISSUED	11.80	S
BGV4-56-145	CLIP	10.00	2.36	*ISSUED	23.60	S
G001-67-061	PAD, PROTECTOR	2.00	7.08	*ISSUED	14.16	S
TK21-50-355	RIVET	8.00	7.42	*ISSUED	59.36	S
S51S-51-833	RIVET, SPLASH SHIELD	8.00	3.12	*ISSUED	24.96	S
K0A2-50-710A	GRILLE, RADIATOR KG	1.00	1,363.90		1,363.90	S

		GST Code	Rate	Service/Goods	GST
Parts	3,574.18	0	-		-
Surcharge	0.00	S	9.00%	5,762.18	518.60
Labour	2,188.00				
Menus	0.00				
*This is only an i	estimate from ou	visual inspection	n and sho	uld there be more dama	ges found during

the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross *	5,762.18	518.60	6,280.78
Less: Deposit**	0.00	0.00	0.00
Amount Due	5,762.18	518.60	6,280.78

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE No.

Date:

Customer signature

Authorised signature

TRANSELROKARS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres:

5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402
Sales Fax: 6476 7073 Service Fax: 6476 7417