

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 22/06/2024
TP Veh Reg No: WD6337X

Estimate No: EST2400242
Date: 25 Jun 2024

Veh Reg No: SMQ9094B
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3801182698
Reg. Date: 09/12/2029
Your Ref No: WD6337X

Estimate Repair Cost to Vehicle No :SMQ9094B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC FRT BUMPER	533.90	
2	1 PC FRT BUMPER REINFORCEMENT	432.50	
3	1 PC FRT BUMPER SIDE RETAINER RH	108.70	
4	1 PC FRT BUMPER GRILLE	384.90	
5	1 PC FRT BUMPER TOWING COVER	78.00	
6	1 PC FRT GRILLE	204.20	
7	1 PC FRT FOG LAMP RH	346.20	
8	1 PC FRT FOG LAMP COVER RH	90.50	
9	1 PC FRT FENDER RH	827.50	
10	1 PC FRT FENDER COWLING RH	222.80	
11	1 PC REAR FENDER INNER TRIM RH	141.30	
12	1 PC HEADLAMP RH	1,393.40	
13	1 PC FRT DOOR RH	1,183.30	
14	2 PCS FRT DOOR HINGE	240.00	
15	1 PC FRT DOOR CHECK RH	199.40	
16	1 PC FRT DOOR RUBBER RH	221.40	
17	1 PC FRT DOOR OUTER MOULDING RH	81.70	
18	1 PC FRT DOOR GLASS CHANNEL RH	132.30	
19	1 PC FRT DOOR SIDE MIRROR RH	1,360.50	
20	1 PC FRT DOOR SIDE MIRROR COVER RH	118.50	
21	1 PC FRT RH DOOR LOCK	655.30	
22	1 PC FRT DOOR OUTER HANDLE RH	478.70	
23	1 PC FRT RH DOOR KEY LOCK COVER	65.60	
24	1 PC FRT DOOR RH TRIM	942.30	
25	1 PC FRT DOOR REGULATOR RH	299.00	
26	1 PC FRT DOOR REGULATOR MOTOR RH	765.50	
27	1 PC FRT RH DOOR BLACK TAPE	82.00	
28	1 PC REAR DOOR RH	1,013.40	
29	2 PCS REAR DOOR HINGE RH	240.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 22/06/2024
TP Veh Reg No: WD6337X

Estimate No: EST2400242
Date: 25 Jun 2024

Veh Reg No: SMQ9094B
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3801182698
Reg. Date: 09/12/2029
Your Ref No: WD6337X

Estimate Repair Cost to Vehicle No :SMQ9094B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC REAR DOOR CHECK RH	199.40	
31	1 PC REAR DOOR LOCK RH	607.90	
32	1 PC REAR DOOR OUTER HANDLE RH	159.80	
33	1 PC REAR DOOR HANDLE COVER RH	65.60	
34	1 PC REAR DOOR GLASS REGULATOR RH	209.40	
35	1 PC REAR DOOR GLASS REGULATOR RH MOTOR	996.60	
36	1 PC REAR DOOR GLASS CHANNEL RH	108.70	
37	1 PC REAR DOOR OUTER MOULDING RH	81.70	
38	1 PC REAR DOOR TRIM RH	805.10	
39	1 PC REAR DOOR RUBBER RH	210.60	
40	1 PC REAR DOOR RH BLACK TAPE	76.00	
41	1 PC REAR FENDER RH	1,120.10	
42	1 PC REAR FENDER MUDFLAP RH	101.80	
43	1 PC REAR FENDER INNER TRIM RH	356.40	
44	1 PC REAR BUMPER	570.90	
45	1 PC REAR BUMPER SIDE RETAINER RH	167.90	
46	1 PC REAR BUMPER RETAINER -SMALL	65.00	
47	1 PC FRT SPORTS RIM RH	1,891.90	
48	1 PC FRT SHOCK ABSORBER RH	453.60	
49	1 PC FRT LOWER ARM RH	1,321.50	
50	1 PC FRT KNUCKLE ARM RH	717.50	
51	1 PC FRT WHEEL HUB RH	644.10	
52	1 PC FRT BEARING RH	210.60	
53	1 PC REAR SPORTS RIM RH	1,891.90	
		25,876.80	
		Less 25%	6,469.20
			19,407.74
	Special Net		
54	1 SET FRT BUMPER CLIPS	60.00	
55	1 SET FRT BUMPER GRILLE CLIPS	40.00	
56	2 PCS FRT BUMPER "L" PLATE BRACKET	70.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 22/06/2024
TP Veh Reg No: WD6337X

Estimate No: EST2400242
Date: 25 Jun 2024

Veh Reg No: SMQ9094B
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3801182698
Reg. Date: 09/12/2029
Your Ref No: WD6337X

Estimate Repair Cost to Vehicle No :SMQ9094B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
57	1 SET FRT GRILLE CLIPS	40.00	
58	1 SET FRT FENDER COWLING CLIPS RH	40.00	
59	1 PC FRT DOOR STICKER RH	280.00	
60	1 PC REAR RH DOOR STICKER	280.00	
61	1 SET REAR FENDER MUDFLAP CLIPS RH	30.00	
62	1 PC REAR FENDER STICKER	290.00	
63	1 SET REAR FENDER INNER TRIM CLIPS	40.00	
64	1 PC REAR WINDSCREEN SEALANT	60.00	
65	1 PC REAR WINDSCREEN INNER SEAL RUBBER	60.00	
66	1 SET REAR BUMPER CLIPS	40.00	
67	2 PCS REAR BUMPER 'L' PLATE BRACKET	70.00	
68	1 SET REAR BUMPER STICKER	280.00	
69	1 PC FRT TYRE RH	380.00	
		2,060.00	2,060.00
	Labour		
70	1 TO CHECK WIRING	50.00	
71	1 TO REMOVE AND REFIT FRT DOOR GLASS	100.00	
72	1 TO REMOVE AND REFIT REAR DOOR GLASS	100.00	
73	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	
74	1 TO REMOVE AND REFIT FRT AND REAR DOOR TRIM	100.00	
75	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
76	1 TO REPLACE FRT DOOR STICKERS	80.00	
77	1 TO REPLACE REAR DOOR STICKERS	80.00	
78	1 TO REPLACE REAR FENDER STICKER	80.00	
79	1 TO REPLACE REAR BUMPER STICKER	80.00	
80	1 TO REMOVE AND REFIT UNDERCARRIAGE	300.00	
81	1 TO CHECK WHEEL ALIGNMENT	120.00	
82	1 TO SPRAY PANEL SEALANT	100.00	
83	1 TO SPRAY PAINTING	2,000.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 22/06/2024
TP Veh Reg No: WD6337X

Estimate No: EST2400242
Date: 25 Jun 2024

Veh Reg No: SMQ9094B
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3801182698
Reg. Date: 09/12/2029
Your Ref No: WD6337X

Estimate Repair Cost to Vehicle No :SMQ9094B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
84	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,300.00	
		5.810.00	5.810.00
	Total		S\$ 27,277.74
	Add GST @ 9%		2,455.00
	Total Amount Payable		<u>S\$ 29,732.74</u>

TOTAL: SINGAPORE DOLLAR TWENTY NINE THOUSAND SEVEN HUNDRED THIRTY TWO
AND CENTS SEVENTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE