

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

Veron

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2400242

Date: 25 Jun 2024

Veh Reg No: SMQ9094B

Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3801182698

Reg. Date: 09/12/2029

Your Ref No: WD6337X

Claim Type: Third Party

Accident Date: 22/06/2024

TP Veh Reg No: WD6337X

Estimate Repair Cost to Vehicle No :SMQ9094B

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC FRT BUMPER <i>Del'd</i>	533.90	-
2	1 PC FRT BUMPER REINFORCEMENT <i>new</i>	432.50	+
3	1 PC FRT BUMPER SIDE RETAINER RH <i>new</i>	108.70	+
4	1 PC FRT BUMPER GRILLE <i>new</i>	384.90	+
5	1 PC FRT BUMPER TOWING COVER <i>new Missing</i>	78.00	+
6	1 PC FRT GRILLE <i>new</i>	204.20	+
7	1 PC FRT FOG LAMP RH <i>new</i>	346.20	+
8	1 PC FRT FOG LAMP COVER RH <i>new</i>	90.50	+
9	1 PC FRT FENDER RH <i>Dist'd</i>	827.50	-
10	1 PC FRT FENDER COWLING RH <i>Del'd</i>	222.80	+
11	1 PC REAR FENDER INNER TRIM RH <i>new Del'd</i>	141.30	+
12	1 PC HEADLAMP RH <i>new</i>	1,393.40	+
13	1 PC FRT DOOR RH <i>Dist'd</i>	1,183.30	-
14	2 PCS FRT DOOR HINGE <i>But</i>	240.00	+
15	1 PC FRT DOOR CHECK RH <i>But</i>	199.40	+
16	1 PC FRT DOOR RUBBER RH <i>new</i>	221.40	+
17	1 PC FRT DOOR OUTER MOULDING RH <i>new</i>	81.70	+
18	1 PC FRT DOOR GLASS CHANNEL RH <i>new</i>	132.30	+
19	1 PC FRT DOOR SIDE MIRROR RH <i>new</i>	1,360.50	+
20	1 PC FRT DOOR SIDE MIRROR COVER RH <i>new</i>	118.50	+
21	1 PC FRT RH DOOR LOCK <i>But</i>	655.30	-
22	1 PC FRT DOOR OUTER HANDLE RH <i>new</i>	478.70	+
23	1 PC FRT RH DOOR KEY LOCK COVER <i>new</i>	65.60	+
24	1 PC FRT DOOR RH TRIM <i>new</i>	942.30	+
25	1 PC FRT DOOR REGULATOR RH <i>But</i>	299.00	+
26	1 PC FRT DOOR REGULATOR MOTOR RH <i>new</i>	765.50	+
27	1 PC FRT RH DOOR BLACK TAPE <i>new</i>	82.00	+
28	1 PC REAR DOOR RH <i>Dist'd</i>	1,013.40	+
29	2 PCS REAR DOOR HINGE RH <i>But</i>	240.00	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2400242
Date: 25 Jun 2024

Veh Reg No: SMQ9094B
Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3801182698
Reg. Date: 09/12/2029
Your Ref No: WD6337X

Claim Type: Third Party
Accident Date: 22/06/2024
TP Veh Reg No: WD6337X

Estimate Repair Cost to Vehicle No :SMQ9094B

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC REAR DOOR CHECK RH <i>and</i>	199.40	✓
31	1 PC REAR DOOR LOCK RH <i>and</i>	607.90	✓ 465
32	1 PC REAR DOOR OUTER HANDLE RH <i>3 new</i>	159.80	+
33	1 PC REAR DOOR HANDLE COVER RH	65.60	+
34	1 PC REAR DOOR GLASS REGULATOR RH <i>and</i>	209.40	✓
35	1 PC REAR DOOR GLASS REGULATOR RH MOTOR <i>new</i>	996.60	+
36	1 PC REAR DOOR GLASS CHANNEL RH <i>new</i>	108.70	+
37	1 PC REAR DOOR OUTER MOULDING RH <i>new</i>	81.70	+
38	1 PC REAR DOOR TRIM RH <i>Replaced</i>	805.10	✓ 750
39	1 PC REAR DOOR RUBBER RH <i>new</i>	210.60	+
40	1 PC REAR DOOR RH BLACK TAPE <i>new</i>	76.00	-
41	1 PC REAR FENDER RH <i>Replaced</i>	1,120.10	-
42	1 PC REAR FENDER MUDFLAP RH <i>Replaced</i>	101.80	✓
43	1 PC REAR FENDER INNER TRIM RH <i>new</i>	356.40	+
44	1 PC REAR BUMPER <i>Replaced</i>	570.90	-
45	1 PC REAR BUMPER SIDE RETAINER RH <i>replaced</i>	167.90	✓
46	1 PC REAR BUMPER RETAINER -SMALL <i>new</i>	65.00	+
47	1 PC FRT SPORTS RIM RH <i>lt</i>	1,891.90	1000(SN)
48	1 PC FRT SHOCK ABSORBER RH <i>new</i>	453.60	+
49	1 PC FRT LOWER ARM RH <i>but</i>	1,321.50	965
50	1 PC FRT KNUCKLE ARM RH <i>and</i>	717.50	✓
51	1 PC FRT WHEEL HUB RH <i>and</i>	644.10	✓
52	1 PC FRT BEARING RH <i>and</i>	210.60	✓
53	1 PC REAR SPORTS RIM RH <i>new</i>	1,891.90	+
		25,876.80	
Less 25%		6,469.20	19,407.74
Special Net			
54	1 SET FRT BUMPER CLIPS <i>new</i>	60.00	30
55	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>	40.00	+
56	2 PCS FRT BUMPER "L" PLATE BRACKET <i>new</i>	70.00	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2400242

Date: 25 Jun 2024

Veh Reg No: SMQ9094B

Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3801182698

Reg. Date: 09/12/2029

Your Ref No: WD6337X

Claim Type: Third Party

Accident Date: 22/06/2024

TP Veh Reg No: WD6337X

Estimate Repair Cost to Vehicle No :SMQ9094B

Quantity	Description	List Price	Amount
		SS	SS
57	1 SET FRT GRILLE CLIPS <i>neu</i>	40.00	+
58	1 SET FRT FENDER COWLING CLIPS RH <i>neu</i>	40.00	- 30
59	1 PC FRT DOOR STICKER RH <i>neu</i>	280.00	220
60	1 PC REAR RH DOOR STICKER <i>neu</i>	280.00	220
61	1 SET REAR FENDER MUDFLAP CLIPS RH <i>neu</i>	30.00	+ 10
62	1 PC REAR FENDER STICKER <i>neu</i>	290.00	200
63	1 SET REAR FENDER INNER TRIM CLIPS <i>neu</i>	40.00	+
64	1 PC REAR WINDSCREEN SEALANT <i>neu</i>	60.00	40
65	1 PC REAR WINDSCREEN INNER SEAL RUBBER <i>neu</i>	60.00	30
66	1 SET REAR BUMPER CLIPS <i>neu</i>	40.00	30
67	2 PCS REAR BUMPER 'L' PLATE BRACKET <i>neu</i>	70.00	30
68	1 SET REAR BUMPER STICKER <i>neu</i>	280.00	250
69	1 PC FRT TYRE RH <i>neu</i>	380.00	+
		2.060.00	2.060.00

Labour

70	1	TO CHECK WIRING	50.00	30
71	1	TO REMOVE AND REFIT FRT DOOR GLASS	100.00	80 40
72	1	TO REMOVE AND REFIT REAR DOOR GLASS	100.00	40 40
73	1	TO REMOVE AND REFIT SEAT CUSHION	200.00	+
74	1	TO REMOVE AND REFIT FRT AND REAR DOOR TRIM	100.00	60
75	1	TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
76	1	TO REPLACE FRT DOOR STICKERS	80.00	x
77	1	TO REPLACE REAR DOOR STICKERS	80.00	x
78	1	TO REPLACE REAR FENDER STICKER	80.00	+
79	1	TO REPLACE REAR BUMPER STICKER	80.00	+
80	1	TO REMOVE AND REFIT UNDERCARRIAGE	300.00	200
81	1	TO CHECK WHEEL ALIGNMENT	120.00	80
82	1	TO SPRAY PANEL SEALANT	100.00	60
83	1	TO SPRAY PAINTING	2,000.00	1200

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 3
SINGAPORE 038988

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 22/06/2024
TP Veh Reg No: WD6337X

Estimate No: EST2400242

Date: 25 Jun 2024

Veh Reg No: SMQ9094B

Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3801182698

Reg. Date: 09/12/2029

Your Ref No: WD6337X

Estimate Repair Cost to Vehicle No :SMQ9094B

Quantity	Description	List Price	Amount
84	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	SS 2,300.00 1400.	SS
	3230	5,810.00	5,810.00
	Total		S\$ 27,277.74
	Add GST @ 9%		2,455.00
	Total Amount Payable		S\$ 29,732.74

TOTAL: SINGAPORE DOLLAR TWENTY NINE THOUSAND SEVEN HUNDRED THIRTY TWO AND CENTS SEVENTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

Adrian L
2/5 27/06/24.
14 Days.

total: 17690.25

2/5 14150

14150