

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SNK 8879E**
Made : Honda
Model : Shuttle Hybrid 1.5 Auto
Chassis No : GP72206885

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper <i>Dented</i>	1	\$ 1,150.60	\$ <i>1050</i> 1,150.60
2	Rear Bumper Side Retainer RH <i>3pc</i>	1	\$ 38.50	\$ 38.50
3	Rear Bumper Side Retainer LH <i>3pc</i>	1	\$ 38.50	\$ 38.50
4	Rear Bumper Reflector RH <i>3pc</i>	1	\$ 78.50	\$ 78.50
5	Rear Bumper Reflector LH <i>3pc</i>	1	\$ 78.50	\$ 78.50
6	Rear Bumper Side Sponge RH <i>new</i>	1	\$ 98.50	\$ 98.50
7	Rear Bumper Side Sponge LH <i>new</i>	1	\$ 98.50	\$ 98.50
8	Rear Bumper Bracket RH <i>new</i>	1	\$ 38.70	\$ 38.70
9	Rear Bumper Bracket LH <i>new</i>	1	\$ 38.70	\$ 38.70
10	Rear Bumper Tow Cover <i>new</i>	1	\$ 32.50	\$ 32.50
11	Rear Tailgate <i>Dented</i>	1	\$ 1,243.10	\$ <i>1193</i> 1,243.10
12	Rear Tailgate Lock <i>new</i>	1	\$ 207.10	\$ 207.10
13	Rear Tailgate Windscreen Glass <i>new</i>	1	\$ 1,230.10	\$ 1,230.10
14	Rear Tailgate Windscreen Glass Top Moulding <i>3pc</i>	1	\$ 67.80	\$ 67.80
15	Rear Tailgate Windscreen Glass Bottom Moulding <i>3pc</i>	1	\$ 89.40	\$ 89.40
16	Rear Tailgate Windscreen Glass Side Moulding <i>2</i>	2	\$ 62.50	\$ 125.00
17	Third Brake Lamp <i>new</i>	1	\$ 256.00	\$ 256.00
18	Rear Tailgate Reflector Lamp RH <i>3pc</i>	1	\$ 389.30	\$ 389.30
19	Rear Tailgate Reflector Lamp LH <i>3pc</i>	1	\$ 389.30	\$ 389.30
20	Rear Tailgate Outer Garnish w Chrome <i>3pc</i>	1	\$ 456.60	\$ 456.60
21	Rear Tailgate Inner Trim Board <i>3pc</i>	1	\$ 396.00	\$ 396.00
22	Rear Tailgate Inner Side Trim RH <i>3pc</i>	1	\$ 128.20	\$ 128.20
23	Rear Tailgate Inner Side Trim LH <i>3pc</i>	1	\$ 128.20	\$ 128.20
24	Rear Tailgate Inner Upper Trim <i>3pc</i>	1	\$ 108.70	\$ 108.70
25	Rear Tailgate Weatherstrip <i>new</i>	1	\$ 196.80	\$ 196.80
26	Rear Tailgate Emblem <i>new</i>	1	\$ 49.80	\$ 49.80
27	Rear Tailgate "Shuttle" Emblem <i>3pc</i>	1	\$ 69.90	\$ 69.90
28	Rear Tailgate "Hybrid" Emblem <i>3pc</i>	1	\$ 70.40	\$ 70.40
29	Rear Tailgate Inner Handle <i>3pc</i>	1	\$ 89.30	\$ 89.30
30	Rear Tailgate Wiper Motor <i>3pc</i>	1	\$ 320.60	\$ 320.60
31	Rear Tailgate Wiper Arm <i>3pc</i>	1	\$ 78.60	\$ 78.60

32	Rear Tailgate Wiper	1	\$	34.60	\$	34.60	+
33	Rear Taillamp Assembly RH	1	\$	570.50	\$	570.50	+
34	Rear Taillamp Assembly LH	1	\$	570.50	\$	570.50	+
35	Rear Taillamp Panel RH	1	\$	377.80	\$	377.80	+
36	Rear Taillamp Panel LH	1	\$	377.80	\$	377.80	+
37	Rear End Panel Antenna	1	\$	169.00	\$	169.00	+
38	Rear End Panel Buzzer	1	\$	152.50	\$	152.50	+
39	Rear End Panel <i>Dented</i>	1	\$	580.80	\$	580.80	+
40	Rear Side End Panel RH <i>Regr</i>	1	\$	416.00	\$	416.00	+
41	Rear Side End Panel LH <i>Regr</i>	1	\$	416.00	\$	416.00	+
42	Rear End Panel Top Garnish <i>crackd</i>	1	\$	176.80	\$	176.80	+
43	Rear Floor Panel <i>crackd</i>	1	\$	1,056.80	\$	1,056.80	+
44	Rear Floor Panel Top Board <i>the m</i>	1	\$	395.00	\$	395.00	+
45	Rear Compartment Box <i>crackd</i>	1	\$	482.00	\$	482.00	+
46	Rear Compartment Box Lid Assembly	1	\$	504.00	\$	504.00	+
47	Rear Compartment Box Lid Cover	1	\$	126.50	\$	126.50	+
48	Rear Compartment Inner Floor Board Cover	1	\$	952.30	\$	952.30	+
49	Rear Floor Under Cover LH	1	\$	186.00	\$	186.00	+
50	Rear Exhaust Pipe	1	\$	614.70	\$	614.70	+
51	Rear Exhaust Pipe Heat Shield	1	\$	89.80	\$	89.80	+
52	Rear Exhaust Pipe Mounting	2	\$	28.60	\$	57.20	+
53	Rear Fender LH	1	\$	1,136.00	\$	1,136.00	+
54	Rear Fender Inner Trim Board LH	1	\$	499.60	\$	499.60	+
55	Rear Fender Inner Shield LH	1	\$	67.70	\$	67.70	+
Parts Sub Total :					\$	17,791.60	
20% Discount					\$	3,558.32	
PARTS TOTAL :					\$	14,233.28	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$		
1	Rear Number Plate <i>the m</i>	1	\$ 50.00	\$	50.00	x
2	Rear Bumper Clips - Set <i>the m</i>	1	\$ 50.00	\$	50.00	30
3	Rear Taillamp Assembly Clips - Set <i>the m</i>	1	\$ 50.00	\$	50.00	+
4	Rear Tailgate Reflector Lamp Clips - Set <i>the m</i>	1	\$ 50.00	\$	50.00	+
5	Rear Tailgate Inner Trim Clips - Set <i>the m</i>	1	\$ 40.00	\$	40.00	30
6	Rear Tailgate Outer Garnish Clips - Set <i>the m</i>	1	\$ 40.00	\$	40.00	x
7	Rear End Panel Top Garnish Clips - Set <i>the m</i>	1	\$ 50.00	\$	50.00	20
8	Rear Fender Inner Trim Board Clips - Set <i>the m</i>	1	\$ 80.00	\$	80.00	30
9	Rear Fender Inner Shield Clips - Set <i>the m</i>	1	\$ 60.00	\$	60.00	+
10	Rear Tailgate Windscreen Glass Sealant <i>the m</i>	1	\$ 120.00	\$	120.00	60
11	Rear Fender Glass Sealant LH <i>the m</i>	1	\$ 120.00	\$	120.00	+
12	Rear Tailgate Sealant <i>the m</i>	1	\$ 150.00	\$	150.00	+
13	Rear End Panel Sealant <i>the m</i>	1	\$ 150.00	\$	150.00	60
14	Rear End Panel Side RH Sealant <i>the m</i>	1	\$ 150.00	\$	150.00	+

15	Rear End Panel Side LH Sealant	1	\$	150.00	\$	150.00
16	Rear Floor Panel Sealant	1	\$	150.00	\$	150.00
17	Rear Fender LH Sealant	1	\$	150.00	\$	150.00
18	Rear Tailgate Windscreen Glass Solar Film	1	\$	450.00	\$	450.00
19	Rear Bumper Reverse Sensor - Set	1	\$	250.00	\$	250.00
20	Rear Tailgate Reverse Camera	1	\$	500.00	\$	500.00
SPECIAL NETT TOTAL :					\$	2,810.00

Nos.	LABOUR	S\$ TOTAL	
1	To Panel Beat, Remove & Refix Parts	\$	2,400.00
2	To Spray Paint Affected Areas	\$	1,800.00
3	Wiring & Bulb Check	\$	100.00
4	To Transfer Rear Tailgate Mechanism	\$	150.00
5	To Remove & Refix Rear Tailgate Windscreen Glass	\$	150.00
6	To Remove & Refix Rear Fender LH Glass	\$	150.00
7	To Remove & Refix Rear Bumper Reverse Sensor	\$	120.00
8	To Remove & Refix Rear Tailgate Reverse Camera	\$	150.00
9	To Remove & Refix Rear Exhaust Pipe	\$	120.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$	150.00
11	To Remove & Refix Fuel Tank to facilitate repairs	\$	200.00
12	To apply anti rust on affected parts	\$	100.00
13	To Conduct Water Leak Test	\$	100.00
14	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$	480.00
LABOUR TOTAL :		\$	6,170.00

PARTS TOTAL : \$ 14,233.28

SPECIAL NETT TOTAL : \$ 2,810.00

LABOUR TOTAL : \$ 6,170.00

GRAND TOTAL : \$ 23,213.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Ling
A/S 12/11/24
06 Days