



Regnant Automotive Pte Ltd
Address: 53 Ubi Ave 1 #01-09 Paya Ubi
Industrial Park (S) 408934
Tel: 8088 0109
UEN No.: 202403813N

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve before/after spray painting
- To reserve damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATION QUOTE

GDH2012000313

ATTN : MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GBH 6572K
MAKE MODEL : TOYOTA HIACE
REFERENCE :
DOA : 02.11.2024
CLAIM TYPE : THIRD PARTY CLAIM

Acknowledged by Repairer
Signature: _____
Date: _____

PARTS	QTY	LIST PRICE (\$)		
REAR TAILGATE	1	\$ 3,728.00	bt	1950
REAR TAILGATE EMBLEM "TOYOTA"	1	\$ 117.10	nel	63
REAR TAILGATE CENTRE GARNISH	1	\$ 215.60	X nn	
REAR TAILGATE LOCK	1	\$ 345.20	bt	264
REAR TAILGATE LOCK COVER	1	\$ 158.90	cut	58.10
REAR TAILGATE LOCK STRIKER	1	\$ 124.20	X nn	
REAR TAILGATE INNER TRIM BOARD	1	\$ 585.40	X nn	
TAILGATE WEATHERSTRIP	1	\$ 404.30	cut	391
REAR TAILLAMP RH/LH	2	\$ 1,132.00	X nn	
REAR TAILLAMP LOWER CORNER PANEL RH/LH	2	\$ 419.00	Ry	
REAR BUMPER	1	\$ 794.00	de	673
REAR BUMPER LOWER BRACKETS	4	\$ 263.60	bt	
REAR BUMPER INNER STEP PANEL	1	\$ 422.50	bt	245.50
REAR BUMPER SIDE RETAINER RH/LH	2	\$ 136.80	X nn	
REAR END PANEL INNER TOP CHROME GARNISH	1	\$ 289.00	bt	185.60
REAR END PANEL OUTER	1	\$ 540.00	bt	
REAR END PANEL INNER	1	\$ 621.20	X nn	
REAR SIDE PANEL RH/LH	1	\$ 710.60	X nn	
REAR SPARE TYRE BRACKET	1	\$ 621.80	X nn	
		\$ 11,629.20		4633.80
	LESS 25%	\$ 2,907.30		
	TOTAL	\$ 8,721.90		3475.35

SPECIAL NEW ITEMS	QTY	LIST PRICE (\$)	REMARKS	
REAR BUMPER CLIP	1 SET	\$ 80.00	30 nel	
REAR TAILGATE STICKER "70KM/H"	1	\$ 50.00	nel	30
REAR TAILGATE STICKER "HIACE"	1	\$ 50.00	nel	40
REVERSE CAMERA	1	\$ 350.00	X nn	
REVERSE SENSOR	1 SET	\$ 200.00	nn	
REAR CAR PLATE NUMBER WITH BARCKET	1	\$ 80.00	X nn	
REAR TAILGATE INNER TRIM BOARD CLIP	1 SET	\$ 80.00	20 nel	
		\$ 890.00		320

LABOUR	LIST PRICE (\$)	REMARKS	
BALANCE B/F	\$ 9,611.90		
CHECK REAR WIRING AND LIGHTING SYSTEM	\$ 150.00	30	
REMOVE, REFIT LINING, TRIM AND GARNISH	\$ 100.00	60	
DIAGNOIS CHECK AND CLEAR FAULT CODE	\$ 100.00	X nn	
REMOVE AND RENEW REAR REVERSE SENSOR	\$ 120.00	40	
TRANSFER PARTS, ATTACHMENT FROM OLD PART TO NEW	\$ 200.00	60	
PANEL BEATING ON AFFECTED AREAS AND RENEW PART	\$ 800.00	500 700	1590
SPRAY PAINTING ON AFFECTED AREAS	\$ 800.00	500 700	
	SUBTOTAL	\$ 1,800.00	
	GRAND TOTAL	\$ 11,411.90	

Taufik 97495749 / 62563561
WP 19/11/24 E 1pm
5 days
Resurvey after repair
taufik@lkhauto.com

3475.35
320
1590
5385.35
2/5/4300
5 days
*