

A.S.S. REC. BY: TaufikREF: CS/SMR24110195/Tnp3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_

Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_

5

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBH6572KYr Regn: 278, 08

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiacecc 2754Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 105225

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GBH2012000313

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 195/R15R: 195/R15☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. \_\_\_\_\_

D.O.I. 19/11/2012Survey held at Regent Antares 712

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufik confirmed lump sum \$4300 and 5 days  
(red, \$7111.9, 62%)

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$



: Interview (\$



: Tech. Invs (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Formal:

Formal: 1/2 to 1/2



Regnant Automotive Pte Ltd  
Address: 53 Ubi Ave 1 #01-09 Paya Ubi  
Industrial Park (S) 408934  
Tel: 8088 0109  
UEN No.: 202403813N

**LKK Auto Consultants hence notify the Rep of the following:**

- To reserve before/after spray painting
- To replace/damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

### ESTIMATION QUOTE

GDH2012000313

ATTN : MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GBH 6572K  
MAKE MODEL : TOYOTA HIACE  
REFERENCE :  
DOA : 02.11.2024  
CLAIM TYPE : THIRD PARTY CLAIM

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

PARTS	QTY	LIST PRICE (\$)	
REAR TAILGATE	1	\$ 3,728.00	bt ✓
REAR TAILGATE EMBLEM "TOYOTA"	1	\$ 117.10	nel ✓
REAR TAILGATE CENTRE GARNISH	1	\$ 215.60	x
REAR TAILGATE LOCK	1	\$ 345.20	bt ✓
REAR TAILGATE LOCK COVER	1	\$ 158.90	cut ✓
REAR TAILGATE LOCK STRIKER	1	\$ 124.20	x
REAR TAILGATE INNER TRIM BOARD	1	\$ 585.40	x
TAILGATE WEATHERSTRIP	1	\$ 404.30	wt ✓
REAR TAILLAMP RH/LH	2	\$ 1,132.00	x
REAR TAILLAMP LOWER CORNER PANEL RH/LH	2	\$ 419.00	Ry
REAR BUMPER	1	\$ 794.00	de ✓
REAR BUMPER LOWER BRACKETS	4	\$ 263.60	bt ✓
REAR BUMPER INNER STEP PANEL	1	\$ 422.50	bt ✓
REAR BUMPER SIDE RETAINER RH/LH	2	\$ 136.80	x
REAR END PANEL INNER TOP CHROME GARNISH	1	\$ 289.00	bt ✓
REAR END PANEL OUTER	1	\$ 540.00	bt ✓
REAR END PANEL INNER	1	\$ 621.20	xR
REAR SIDE PANEL RH/LH	1	\$ 710.60	x
REAR SPARE TYRE BRACKET	1	\$ 621.80	x
		\$ 11,629.20	
	LESS 25%	\$ 2,907.30	
	TOTAL	\$ 8,721.90	

SPECIAL NEW ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 80.00	30 nel ✓
REAR TAILGATE STICKER "70KM/H"	1	\$ 50.00	nel ✓
REAR TAILGATE STICKER "HIACE"	1	\$ 50.00	nel ✓
REVERSE CAMERA	1	\$ 350.00	x
REVERSE SENSOR	1 SET	\$ 200.00	rw ✓
REAR CAR PLATE NUMBER WITH BARCKET	1	\$ 80.00	x
REAR TAILGATE INNER TRIM BOARD CLIP	1 SET	\$ 80.00	20 nel ✓
		\$ 890.00	

LABOUR	LIST PRICE (\$)	REMARKS
BALANCE B/F	\$ 9,611.90	
CHECK REAR WIRING AND LIGHTING SYSTEM	\$ 150.00	30
REMOVE, REFIT LINING, TRIM AND GARNISH	\$ 100.00	60
DIAGNOIS CHECK AND CLEAR FAULT CODE	\$ 100.00	x
REMOVE AND RENEW REAR REVERSE SENSOR	\$ 120.00	40
TRANSFER PARTS, ATTACHMENT FROM OLD PART TO NEW	\$ 200.00	60
PANEL BEATING ON AFFECTED AREAS AND RENEW PART	\$ 800.00	600 700
SPRAY PAINTING ON AFFECTED AREAS	\$ 800.00	600 700
SUBTOTAL	\$ 1,800.00	
GRAND TOTAL	\$ 11,411.90	

Taufik 97495749 / 62563561  
WP 19/11/24 E 1pm - 5 days  
e/s Resurvey after repair  
taufik@lkhauto.com