



QUOTATION

P/P # 3565-05

No of Additional
man 3 days
22/11/24
Take photo before repair

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 2.5L PREMIUM BLACK LS
CHASSIS NO.: JM6GL1031J0131604
ENGINE NO.: PY21026707
REG NO.: SLU2680X
REGN DATE: 28/11/2017

PAGE NO.: 1
DOCUMENT NO.: 1595
DOCUMENT DATE: 18/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV: Lee Yao Sheng
CSP/OP CODE: I
DEPT: 22813
WIP NO.: 22813
REF. NO.:
DATE IN: 27/11/2022
EXT. WTY: 0
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	MS FIRST TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA.			792	1,584.00	S
SUB	TO RESPRAY REAR BUMPER.			756	1,512.00	S
SUB	TO TRANSFER REVERSE SENSORS.			180	330.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			180	300.00	S
SUB	SUNDRIES.			nu	50.00	S
GJY1-50-221	REAR BUMPER GJ/GL	1.00	1,260.75	*NO STOCK	1,260.75	S
BHN1-50-0Z1A	GROMMET, SCREW	4.00	2.36	*NO STOCK	9.44	S
B45A-56-146A	FASTENER	6.00	2.36	STOCK	14.16	S
G4YL-50-EL1 13	COVER(L), TOWING HOOK	1.00	43.80	*NO STOCK	43.80	S
G4YL-50-EK1 13	COVER(R), TOWING HOOK	1.00	43.80	STOCK	43.80	S
DFR5-50-251	BRACKET, BUMPER SKYACTIV	1.00	4.64	*NO STOCK	4.64	S
GHK1-50-260	REINF., REAR BUMPER GJ/GL	1.00	523.08	*NO STOCK	523.08	S
KD45-67-UC5A1	RETAINER RR SENSOR	2.00	15.77	*NO STOCK	31.54	S
GMK6-67-UC1	1 SENSOR, ULTRASONIC KE/BN	2.00	184.59	*NO STOCK	369.18	S
GS1D-50-EM1A	TAPE, PROTECTOR	4.00	7.42	*NO STOCK	29.68	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402
23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN:MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 2.5L PREMIUM BLACK LS
CHASSIS NO.: JM6GL1031J0131604
ENGINE NO.: PY21026707
REG NO.: SLU2680X
REGN DATE: 28/11/2017

PAGE NO.: 2
DOCUMENT NO.: 1595
DOCUMENT DATE: 18/11/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 22813
REF. NO.:
DATE IN:
EXT. WTY: 27/11/2022
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
GMC8-67-290	CORD,SHORT GL	1.00	178.10	*NO STOCK	178.10	S
GJA1-51-153	GASKET(R),RR.COMB.GJ/GL	1.00	39.62	STOCK	39.62	S
GJA1-51-163	GASKET(L),RR.COMB.GJ/GL	1.00	39.62	STOCK	39.62	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	2,587.41	O	-	-			
Surcharge	0.00	S	9.00%	6,613.41	595.21	7,208.62	
Labour	4,026.00						
Menus	0.00						
Gross					6,613.41	595.21	7,208.62
Less: Deposit**					0.00	0.00	0.00
Amount Due					6,613.41	595.21	7,208.62

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



TRANSEUROKARS
Eurokars Group

Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 6369 3003, BRN. 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 6846 1700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 2.5L PREMIUM BLACK LS
CHASSIS NO.: JM6GL1031J0131604
ENGINE NO.: PY21026707
REG NO.: SLU2680X
REGN DATE: 28/11/2017

PAGE NO.: 1
DOCUMENT NO.: 1628
DOCUMENT DATE: 03/12/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV:
CSP/OP CODE: Wong Chun Wei
DEPT: 1
WIP NO.: 22813
REF. NO.:
DATE IN:
EXT. WTY: 27/11/2022
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross GST	
					amount	Code
			SGD		SGD	
NOTES	MS FIRST TP CLAIM				0.00	O
SUB	MZ 6 UBI				792.00	S
	TO REMOVE & REPLACE REAR BUMPER.					
	AND ALL ACCIDENT AFFECTED AREA.					
	- PO24223					
SUB	MZ 6 UBI				756.00	S
	TO RESPRAY REAR BUMPER.					
	- PO24223					
SUB	MZ 6 UBI				180.00	S
	TO TRANSFER REVERSE SENSORS.					
	- PO24223					
SUB	MZ 6 UBI				120.00	S
	TO CHECK ELECTRICAL SYSTEM					
	FOR PROPER FUNCTIONING.					
	- PO24223					
SUB	MZ 6 BUI				180.00	S
	TO REPROGRAMME AFTER THE					
	ACCIDENT REPAIR WORKS.					
	- PO24223					

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA6 2.5L PREMIUM BLACK LS
CHASSIS NO.: JM6GL1031J0131604
ENGINE NO.: PY21026707
REG NO.: SLU2680X
REGN DATE: 28/11/2017

PAGE NO.: 2
DOCUMENT NO.: 1628
DOCUMENT DATE: 03/12/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV: Wong Chun Wei
CSP/OP CODE: I
DEPT: 22813
WIP NO.: 27/11/2022
REF. NO.: 0
DATE IN: 0
EXT. WTY: 0
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	MZ 6 UBI SUNDRIES. - PO24223				20.00	S
GJY1-50-221	REAR BUMPER GJ/GL	1.00	1,260.75	*ISSUED	1,260.75	S
BHN1-50-0Z1A	GROMMET,SCREW	4.00	2.36	*ISSUED	9.44	S
B45A-56-146A	FASTENER	6.00	2.36	*ISSUED	14.16	S
G4YL-50-EL1 13	COVER(L),TOWING HOOK	1.00	43.80	*ISSUED	43.80	S
G4YL-50-EK1 13	COVER(R),TOWING HOOK	1.00	43.80	*ISSUED	43.80	S
DFR5-50-251	BRACKET,BUMPER SKYACTIV	1.00	4.64	*ISSUED	4.64	S
KD45-67-UC5A1	RETAINER RR SENSOR	2.00	15.77	*ISSUED	31.54	S
GS1D-50-EM1A	TAPE,PROTECTOR	4.00	7.42	*ISSUED	29.68	S
GJA1-51-153	GASKET(R),RR.COMB.GJ/GL	1.00	39.62	*ISSUED	39.62	S
GJA1-51-163	GASKET(L),RR.COMB.GJ/GL	1.00	39.62	*ISSUED	39.62	S

	GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	1,517.05	O	-	-			
Surcharge	0.00	S	9.00%	3,565.05	320.85	3,885.90	
Labour	2,048.00						
Menus	0.00						
Gross					3,565.05	320.85	3,885.90
Less: Deposit**					0.00	0.00	0.00
Amount Due					3,565.05	320.85	3,885.90

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



TRANS EUROKARS
Eurokars Group

Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417