

GRAND TOTAL

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBJ 1221X						
REPLACEMENT OF PARTS							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	FRONT BUMPER	DEFORMED	\$760.00	\$760.00			
1	FRONT BUMPER BRACKET LH	BENT	\$280.00	\$280.00			
1	FRONT GRILLE	SCRATCHED	\$864.00	\$611.00			
1	FRONT OUTER PANEL	BENT	\$1,150.00	\$1,085.00			
1	FRONT INNER PANEL (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00			
1	FRONT CORNER PANEL LH	SCRATCHED	\$485.00	\$310.00			
1	WING MIRROR (ROUND) LH	MISSING	\$95.00	\$95.00			
1	HEADLAMP LH	BROKEN	\$670.00	\$569.00			
1	SIGNAL LAMP LH	BROKEN	\$252.00	\$162.00			
1	FRONT DOOR LH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00			
1	STEP PANEL GARNISH LH	CRACKED	\$320.00	\$158.00			
1	COOLING COIL HOUSING (ADDITIONAL)	CRACKED	\$1,140.00	\$900.00			
	LESS 15.00% DISCOUNT		(\$902.40)	(\$739.50)			
			\$5,113.60	\$4,190.50			
	Special	Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	FRONT NUMBER PLATE (SN)	BENT	\$35.00	\$35.00			
1	ADVERTISEMENT STICKER (SN)	NECESSARY	\$300.00	\$200.00			
1	DOOR ROC STICKER (SN)	NECESSARY	\$20.00	\$20.00			
	, ,		\$355.00	\$255.00			
	φ555.00						
	Labo						
	Description of Parts LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
	FRONT INNER PANEL AND FRONT DOOR LH		\$1,000.00	\$800.00			
	TO RESPRAY AFFECTED PORTION		\$1,000.00	\$800.00			
	TO CHECK AND RECONNECT ALL NECCESSARY WIRINGS		\$30.00	\$30.00			
	RUST PROOFING		\$50.00	\$50.00			
	TO TOP UP AIRCON GAS (ADDITIONAL)		\$120.00	\$120.00			
			\$2,200.00	\$1,800.00			
			I T	I I			

\$7,668.60

\$6,245.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	\$5,000.00
Report Ref No: CS/TP24110198/Rnp3m4	

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.