Days Of Repair:

Add Fee:

Resurvey No. of Trip:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation

**Photos** 

TOTAL

Time. File Page 107

Time, Fig Return to?

Report Format :

: Preli. Report

Final Report

## > Back to OneMotoring

| Enquire I | PARF/COE | Rebate for | Registered | Vehicle |
|-----------|----------|------------|------------|---------|
|-----------|----------|------------|------------|---------|

| /ehicle Owner Particulars                          | Company  |  |  |  |
|--|--|--|--|--|
| Owner ID Type:                                     | Company  |  |  |  |
| Owner ID:  | 839G   |  |  |  |
| /ehicle Details                                    | SHB2883A   |  |  |  |
| /ehicle No.:                                       | No.  |  |  |  |
| /ehicle to be Exported:                            | 30 Nov 2024  |  |  |  |
| ntended Deregistration Date:                       |  |  |  |  |
| Vehicle Make:                                      | TOYOTA   |  |  |  |
| Vehicle Model:                                     | PRIUS 5DR HATCHBACK (AUTO)   |  |  |  |
| Primary Colour:                                    | Yellow   |  |  |  |
| Manufacturing Year:                                | 2018   |  |  |  |
| Engine No.:  | 2ZR2C14829   |  |  |  |
| Chassis No.:                                       | JTDKB3FUX03080419  |  |  |  |
| Maximum Power Output:                              | 90.0 kW (120 bhp)  |  |  |  |
| Open Market Value:                                 | \$26,605.00  |  |  |  |
| Original Registration Date:                        | 31 May 2019  |  |  |  |
| First Registration Date:                           | 31 May 2019  |  |  |  |
| Transfer Count:                                    | 0  |  |  |  |
| Actual ARF Paid:                                   | \$14,247.00  |  |  |  |
| Intended PARF Rebate Details                       |  |  |  |  |
| PARF Eligibility:                                  | Yes  |  |  |  |
| PARF Eligibility Expiry Date:                      | 30 May 2027  |  |  |  |
| PARF Rebate Amount:<br>Intended COE Rebate Details | \$9,972.00   |  |  |  |
| COE Expiry Date:                                   | 30 May 2027  |  |  |  |
| COE Category:                                      | A - Car up to 1600cc & 97kW (130bhp)   |  |  |  |
| COE Period(Years):                                 | 8  |  |  |  |
| PQP Paid:  | \$22,309.00  |  |  |  |
| COE Rebate Amount:                                 | \$6,964.00   |  |  |  |
| Total Rebate Amount:                               | \$16,936.00  |  |  |  |
| Message  | orther renewed. The vehicle must be deregistered once the COE expires, or when |  |  |  |

reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Nov 2024

## **BIFROST AUTO PTE LTD**

## REPAIR ESTIMATE

|                  | A | - | _ |
|------------------|---|---|---|
| 1)               | н |   | _ |
| $\boldsymbol{L}$ | r |   | _ |

11-Nov-24

INSURANCE:

MSIG

MODEL:

TOYOTA PRIUS

VEHICLE NO .:

SHB 2883 A

| DESCRIPTION                             | QTY | LIST PRICE | AMOUNT     |
|---|-----|------------|------------|
| REAR BUMPER                             | 1   | \$503.04   | \$503.04   |
| REAR BUMPER CLIPS                       | 1   | \$22.00    | \$22.00    |
| REAR BUMPER SIDE CLIP                   | 1   | \$25.00    | \$25.00    |
| REAR BUMPER UNDER SIDE COVER (LH)       | 1   | \$232.00   | \$232.00   |
| REAR FENDER, LH 2001                    | 1   | \$992.04   | \$992.04   |
| PANEL SUB-ASSY, REAR DOOR, LH Quil      | 1   | \$1,258.30 | \$1,258.30 |
| REAR DOOR HINGE UPPER                   | 1   | \$82.30    | \$82.30    |
| REAR DOOR HINGE LOWER                   | 1   | \$82.30    | \$82.30    |
| REAR DOOR CHECK                         | 1   | \$153.00   | \$153.00   |
| REAR DOOR INNER LOCK                    | 1   | \$644.70   | \$644.70   |
| MOTOR, POWER WINDOW REGULATOR REAR , LH | 1   | \$941.80   | \$941.80   |
| REGULATOR, FRONT DOOR WINDOW REAR, LH   | 1   | \$228.40   | \$228.40   |
| REAR DOOR RUBBER SEAL OUTER             | 1   | \$257.90   | \$257.90   |
| PANEL SUB-ASSY, FRONT DOOR, LH          | 1   | \$1,264.00 | \$1,264.00 |
| FRONT DOOR INNER LOCK                   | 1   | \$688.80   | \$688.80   |
| FRONT DOOR HINGE UPPER                  | 1   | \$91.20    | \$91.20    |
| FRONT DOOR HINGE LOWER                  | 1   | \$91.20    | \$91.20    |
| FRONT DOOR CHECK                        | 1   | \$153.52   | \$153.52   |
| FRONT DOOR WHETHER STRIP                | 1   | \$457.90   | \$457.90   |
| MOTOR ASSY, POWER WINDOW FRT, LH        | 1   | \$941.80   | \$941.80   |
| REGULATOR, FRONT DOOR WINDOW FRT, LH    | 1   | \$228.40   | \$228.40   |
| MIRROR ASSY, OUTER REAR VIEW, LH        | 1   | \$1,728.70 | \$1,728.70 |
| Rocker Panel Outer Garnish              | 1   | \$576.00   | \$576.00   |
| REAR TYRE RIM (LH)                      | 1   | \$1,555.00 | \$1,555.00 |
| REAR WHEEL CAP (LH)                     | 1   | \$177.70   | \$177.70   |
| REAR WHEEL BEARING HUB assy             | 1   | \$610.20   | \$610.20   |

| REAR SHOCK ABSORBER                    |    | 1 | \$118.30   | \$118.30    | *       |
|--|----|---|------------|-------------|---------|
| REAR SHOCK ABSORBER MOUNTING           |    | 1 | \$125.30   | \$125.30    | ×       |
| REAR LOWER ARM                         |    | 1 | \$497.50   | \$497.50    | X       |
| REAR UPPER ARM                         |    | 1 | \$356.80   | \$356.80    | X       |
| REAR KNUCKLE ARM                       |    | 1 | \$810.60   | \$810.60    | X       |
| REAR STABILIZER BAR                    |    | 1 | \$311.50   | \$311.50    | X       |
| REAR STABILIZER LINK                   |    | 1 | \$151.60   | \$151.60    | X       |
| REAR TRAILING ARM                      |    | 1 | \$314.20   | \$314.20    | X       |
| REAR ASSIST ARM                        |    | 1 | \$342.20   | \$342.20    | X       |
| FENDER SUB-ASSY, FRONT LH              |    | 1 | \$1,111.93 | \$1,111.93  |         |
| FRONT FENDER SHIELD                    |    | 1 | \$255.00   | \$255.00    |         |
| FRONT FENDER SHIELD CLIP               |    | 1 | \$14.90    | \$14.90     |         |
| FRONT FENDER HYBRID EMBLEM, LH         |    | 1 | \$86.50    | \$86.50     |         |
|  |    |   |            |             | 8417-77 |
| SUB TOTAL                              |    |   |            | \$18,483.53 | 6537.67 |
| LESS 30% 25%                           |    |   |            | \$3,696.71  | 0.000   |
| DISCOUNTED TOTAL                       |    |   |            | \$14,786.82 | 4903.25 |
|  |    |   |            |             | 5       |
| FRONT DOOR COMFORT LOGO                | SN | 1 | \$75.00    | \$75.00     |         |
| REAR DOOR COMFORT & APPS STICKER       | SN | 1 | \$80.00    | \$80.00     |         |
| REAR TYRE (LH)                         | SN | 1 | \$216.00   | \$216.00    | X       |
|  |    |   |            |             | 155.00  |
| SUB TOTAL                              |    |   |            | \$371.00    |         |
|  |    |   |            |             |         |
| Labour Charge                          |    |   |            |             |         |
| Panel Beating                          |    | 1 | \$1,800.00 | \$1,800,00  | 800 (   |
| Spray Painting Charge                  |    | 1 | \$1,600.00 | \$1,600.00  | 1000/-  |
| Wiring Charge                          |    | 1 | \$100.00   | \$100.00    | the     |
| Tuff Kote                              |    | 1 | \$100.00   | \$100.00    | 30(-    |
| Towing Charge                          |    | 1 | \$80.00    | \$80.00     | MA      |
| Remove/Refix Cushion & Upholstery Rear |    | 1 | \$150.00   | \$150.00    | 80  -   |
| Remove/Refix Undercarriage (RR)        |    | 1 | \$400.00   | \$400.00    | 1       |
| Remove/Refix Fuel Tank                 |    | 1 | \$80.00    | \$80.00     | 1       |
| Transfer of Door Mechanism FRONT       |    | 1 | \$80.00    | \$80.00     | 60(-    |
| Re-set Frt Power Window System         |    | 1 | \$200.00   | \$200.00    | ) Lak   |
| Transfer of Door Mechanism REAR        |    | 1 | \$80.00    | \$80.00     | 60/2    |
| Re-set Rear Power Window System        |    | 1 | \$200.00   | \$200.00    | H       |

| Four Wheel Alignment                       | 1 | \$120.00 | \$120.00    |
|--|---|----------|-------------|
| Diagnostic & Resetting To Erase Fault Code | 1 | \$550.00 | \$550.00    |
| TOTAL LABOUR                               |   |          | \$5,540.00  |
| ESTIMATE TOTAL                             |   |          | \$20,697.82 |

60/-HH

2040-00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims\_ltr@bifrostauto.com

12/11/2024 e 1000m Hay Andrew 2/5mm 6 dys.

LIS 5,7001'

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: