

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: PRIYA

Date: 18/11/2024

PRELIMINARY ADVICE

Vehicle No	GBK 5024S	Accident Date	09/11/2024
Make	TOYOTA HIACE	Policy No.	D19MFL0005549_05
Assignment Date	11/11/2024	Excess	-
Inspection Date	12/11/2024	Est. Duration of Repair	4

Inspected At: 8 KAKI BUKIT AVE 4 #04-35 PREMIER SINGAPORE 415875

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$14,670.45
Revised Estimate Amount:	\$4,200.00
"Check" Items Amount	\$0.00
Total	\$4,200.00

Total Loss Consideration

Book Value	\$0.00
Market Value	\$70,000.00
COE / PARF Rebate	\$13,928.00
Salvage Value	\$0.00
Margin for Repair	\$56,072.00

Remarks

- [] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.