



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE

Account Details	Account No.	Acknowledged by Repairer	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Signature:	
	Document No. 0	Date: Ivy Lam Bee Lian (Lan Meilian)	
	Document Date 11/11/2024	14A Lorong 7 Toa Payoh #25-233 Singapore 311014	Mobile: 97304413

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2024	ZRE210R	GEXGPZ S3	20/08/2024	SNS5526B	0	34604	72/DS/SNS5526B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2BE3BE800030232	1ZR3A89375	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI TP INS:INDIA INTERNATIONAL INSURANCE TP VEH:SGT8571C DATE OF ACC:08.11.2024				50 100.00
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				✓ 198.00
3	B	BP-LAB2 CHECK WIRING SYSTEM				✓ 134.64
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				✓ 198.00
5	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR				✓ 198.00
6	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				792 1584.00
7	B	BP-RES2 REPLACE ACC DAMAGED PARTS				656 1312.00
8	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				✓ 91.59
9	1	S52159-0Z961 COVER, RR BUMPER L/C	1.00	824.30		de ✓ 824.30
10	2	S52462-02340 PAD, RR BUMPER, RH	2.00	28.00		rel ✓ 56.00
11	3	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		rel ✓ 58.00
12	4	S52576-02220 RETAINER, RR BUMPER	1.00	153.50		x 153.50
13	5	S52563-02300 RETAINER, RR BUMPER,	1.00	153.50		x 153.50
14	6	S52023-02240 REINFORCEMENT SUB-AS	1.00	512.40		x 512.40
15	7	S81920-02360 REFLECTOR ASSY, REFL	1.00	54.10		cm ✓ 54.10
16	8	SPC507-12005 2A BACK SENSOR (1K3, CELESTITE GR	1.00	224.10		rw ✓ 224.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			5,852.13
Tanjong 97495749 wpd 11/12/24 4pm p/p Resurvey before paint Tanjong C Khawto.com	Please acknowledge receipt of vehicle	Parts 2,035.90	GST 9.00% 526.69
		Labour 3,724.64	
		Sublet 91.59	
		Lubrication/Fluid 0.00	
		Others 0.00	
		Less	0.00
		Amount Due	6,378.82

Customer Copy