



ESTABLISHED 1984

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD  
75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557  
ATTN: JULIE

Ref: CS/INC24110205/Avh3m4(N)  
Date: 06/02/2025  
Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKW 9267L	<b>Veh. Inspected</b>	YR 969P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1303146-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANNIE KOH	<b>Assign Date</b>	11/11/2024

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HINO XZU710R	<b>c.c</b>	4009
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2023
<b>Chassis No.</b>	JHHUCV3F30K051712	<b>Colour</b>	WHITE
<b>Odometer</b>	26307 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/85 R15	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	195/85 R15	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	195/85 R15	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	195/85 R15	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	07/11/2024	<b>Inspect Date / Time</b>	13/11/2024 ( 02:36 PM )
<b>Survey held at</b>	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**