

# 國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.  
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177  
Email: ktmotorwerk@hotmail.com  
Reg. No.: 533734628

DATE : 12.11.2024

VEHICLE NO : **YR 969P**  
 MODEL : **HINO XZU**  
 DATE OF REG : **31.10.2023**  
 DATE OF ACCIDENT : **07.11.2024**  
 CHASSIS : **JHHUCV3F30K051712**

TPINC  
Veron.

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL LAMP <i>cracked. RH</i>	2	\$ 365.80	\$ <del>731.60</del> <i>365.80</i>
3	REAR NUMBER PLATE LAMP <i>new</i>	1	\$ 95.20	\$ 95.20 <i>X</i>
4	REAR NUMBER PLATE SUPPORT BRACKET <i>new</i>	1	\$ 195.00	\$ 195.00 <i>X</i>
5	REAR LOWER END PANEL <i>Regis</i>	1	\$ 1,684.10	\$ 1,684.10 <i>+</i>
TOTAL PRICE				\$ 2,705.90
LESS 10%				\$ 405.89
SUB TOTAL PRICE				\$ 2,300.02

365.80  
32922

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00 <i>X</i>
2	REAR CARRIER FLOOR WOODEN MEMBER <i>new</i>	1	\$ 1,200.00	\$ 1,200.00 <i>+</i>
3	TAIL GATE '70KM/H' STICKER <i>new</i>	1	\$ 20.00	\$ 20.00 <i>+</i>
4	TAIL GATE 22 PAX <i>new</i>	1	\$ 20.00	\$ 20.00 <i>+</i>
5	REAR REINFORCEMENT LOWER(SPECIAL TYPE) <i>Regis</i>	1	\$ 1,200.00	\$ 1,200.00 <i>+</i>
6	REAR REINFORCEMENT LOWER REFLECTIVE STICKER <i>new</i>	1	\$ 250.00	\$ 250.00 <i>30</i>
7	HYDRAULIC FLUID <i>new</i>	2	\$ 60.00	\$ 120.00 <i>+</i>
8	REAR HYDRAULIC "L" ARM <i>2 NP</i>	2	\$ 3,500.00	\$ 7,000.00 <i>+</i>
9	REAR HYDRAULIC "T" ARM <i>new</i>	2	\$ 4,100.00	\$ 8,200.00 <i>+</i>
10	CRANE MAIN LIFTING BEAM HYDRAULIC CYLINDER JACK <i>new</i>	1	\$ 1,800.00	\$ 1,800.00 <i>X</i>
11	TAILAMP LOWER SUPPORT BRACKET <i>RH Bent</i>	2	\$ 280.00	\$ 560.00 <i>280</i>

Tailamp Lower Support Bracket Beam 1 TOTAL \$ 20,420.00  
 280 200 -  
 cracked 510

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST

1	TO PANEL BEAT, WELD , CUT, ADJUST, KNOCK	\$	<del>1,600.00</del>	300
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$	<del>1,000.00</del>	250
3	REAR CHASSIS ALIGHMENT	\$	250.00	x
4	TO REMOVE /INSTALL REAR LIFTING PLATFORM,ALIGN AND ADJUSTMENT	\$	850.00	x

650

**TOTAL \$ 3,700.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 22,720.02  
 TOTAL LABOUR COST : \$ 3,700.00  
 TOTAL REPAIR COST : \$ 26,420.02

Adom Cj

1/s 13/11/24.

03 Days

Total: 1489.22

1/s: 1.2k

1.2k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: