

Not Authorized
 on
 record
 7 days
 d/s # 6600
 date 2/11/14

Vehicle: GX70M

Make & Model: TOYOTA HIACE
 Chassis No: JTFHT02PX00200055

1 set

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend	
1	Left Headlamp			\$ 980.60	CR ✓	
2	Front Grille Assy		645.10	\$ 1,182.50	CR ✓	
3	Front Bumper			\$ 729.60	TO ✓	
4	Front Bumper Beam			\$ 293.40	DD ✓	
5	Front Bumper Licence Plate			\$ 40.00 SN	But / S/W	
6	Front Bumper Clips			\$ 30.00 SN	re ✓ S/W	
7	Rear Boot			\$ 1,817.40	Body DD ✓	
8	Rear Boot Glass Sealant			\$ 60.00 SN	re 40 S/W	
9	Rear Boot "Emblem"			\$ 68.50	re ✓	
10	Rear Boot "70km/h" Sticker			\$ 10.00 SN	re ✓ S/W	
11	Rear Boot Handle Moulding			\$ 329.40	SC X	
12	Rear Boot Licence Plate			\$ 40.00 SN	SC ✓ 40 S/W	
13	Rear Boot Lock			\$ 298.50	Doyle ✓	
14	Rear end panel top steel plate			\$ 208.30	Gen ✓	
15	Rear Boot weatherstrip			\$ 366.00	TM ✓	
16	Rear Taillamp (Left & Right)	408.10	2	\$ 487.50	\$ 975.00	disc one disc in 1pc
17	Left Rear Corner Panel Garnish			\$ 138.40	R X	
18	Left Rear Corner Panel Garnish Retainer			\$ 63.50	re X	
19	Rear Bumper			\$ 687.40	DIS ✓	
20	Rear Bumper Clips			\$ 30.00 SN	re ✓ S/W	
21	Rear Bumper Reverse Sensor			\$ 200.00 SN	modification ✓ S/W	
22	Rear Bumper Retainer (Left & Right)		2	\$ 89.50	\$ 179.00	re X
23	Rear End Panel	646.10		252	\$ 985.80	500.50 ✓

1 set

1 set

24 taillamp housing panel LH

520.50 re/bent ✓

25	rear bumper lower brackets @60.20	4pcs		\$ 240.80	501 ✓
26	Rear Floor Matt Stay			\$ 196.80	11X
			(252)		
Labour					
1	To Dismantle & refix rear windscreen			\$ 120.00	✓
2	Transfer Boot			\$ 150.00	60
3	Check Air Con & Refill Gas			\$ 120.00	11X
4	Check Wiring			\$ 80.00	30
5	Anti Rust Proof			\$ 80.00	70
6	Panel Beating & Install Parts			\$ 900.00	850
7	Paint Work			\$ 1,000.00	800

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) for the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-7910.30
 252
 P-5932.73
 SN-390
 L-1930
 8252.73
 203
 6002