

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC 24110207/4063

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GY 70M

at Workshop m/s sty tech

of _____

Insured: SKR 4912S

Policy No. _____

Claims No. MT/1303578-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

⊗	
N/S	O/S
⊙	

Bal. or Market Value: 825/c.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

550/c

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

LTA 6814

Veh No: GX 70M Yr Regn: 29/07/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Toyota hiace c.c. 2982

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 23/78/ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P X00200055

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 195-215 habited

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or kapser

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 08/11/24 D.O.I. 12/11/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & hp

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 20/11/24

20/11/24 have vides at folder
1/5 @ 6600 : spend on. nston 18-11-24 pass out.
(red 6521.40, 49%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	501L
Vehicle Details	
Vehicle No.:	GX70M
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 4 DR AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2628120
Chassis No.:	JTFHT02PX00200055
Maximum Power Output:	-
Open Market Value:	\$28,859.00
Original Registration Date:	29 Jul 2016
First Registration Date:	29 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$1,443.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$39,858.00
COE Rebate Amount:	\$6,814.00
Total Rebate Amount:	\$6,814.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 12 Nov 2024

OK

DIRECT OWNER



Toyota Hiace Commuter
3.0A GL

\$43,500
Instl. \$1,738 /mth
\$20,430 /yr
30-Dec-2016 (2yrs 1mth COE left)
N.A. 2,982 cc
1 Owner

2017 Toyota Hiace commuter GL model. 100% loan welcomed. Easy approval. Low depreciation. Good for short term use. Ideal monthly repayment. Everything is in good condition! Buy with piece of mind! View to believe! Call us today to secure this unit now!

Think One Automobile & Trading|Posted 26-Oct-2024

Compare

PREMIUM AD

ADVERTISING



Toyota Hiace 3.0M

\$31,500
Instl. \$1,310 /mth
\$15,230 /yr
08-Dec-2016 (2yrs COE left)
N.A. 2,982 cc
3 Owners
Diesel

Viewing by appointment please, passing through do not miss! Most popular Hiace for sales, condition too good to scrap! Service regularly with no repair needed, light to heavy goods no worries. Trade in/bank/in house or full loan available here. Grab this beauty now before she's gone!

Posted 26-Oct-2024

Compare



Toyota Hiace 3.0A DX

\$31,800
Instl. \$1,585 /mth
N.A.
20-Jul-2016 (1yr 8mths COE left)
N.A. 2,982 cc
2 Owners
Diesel

2016 Toyota Hiace standard roof auto. Good condition. 4 doors. 100% loan welcomed.

Think One Automobile & Trading|Posted 25-Oct-2024

Compare

PREMIUM AD



Toyota Hiace Commuter
3.0A GL

\$35,000
Instl. \$2,055 /mth
\$24,330 /yr
22-Apr-2016 (1yr 5mths COE left)
N.A. 2,982 cc
4 Owners
Diesel

If you manage to drive a commuter, you will understand how valuable it is. Each of the 15 seats is very comfortable and properly cushioned. The aisle is wide enough to walk through and is spacious. You can easily go off for a nap as the suspension setup is praiseworthy. Workshop check/STA evaluation can be arranged. Viewing available in our showroom. Bank and in house loan available. Contact us.

Posted 25-Oct-2024

Compare

PREMIUM AD

Compare

Not Authorized
 on
 motor
 d/s # 6600
 7 days

Vehicle: GX70M

Make & Model: TOYOTA HIACE

Chassis No: JTFHT02PX00200055

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Left Headlamp			\$ 980.60	one ✓
2	Front Grille Assy		645.10	\$ 1,182.50	one ✓
3	Front Bumper			\$ 729.60	two ✓
4	Front Bumper Beam			\$ 293.40	two ✓
5	Front Bumper Licence Plate			\$ 40.00 SN	but ✓ s/n
6	Front Bumper Clips			\$ 30.00 SN	new ✓ s/n
7	Rear Boot			\$ 1,817.40	Body ✓
8	Rear Boot Glass Sealant			\$ 60.00 SN	new ✓ s/n
9	Rear Boot "Emblem"			\$ 68.50	new ✓
10	Rear Boot "70km/h" Sticker			\$ 10.00 SN	new ✓ s/n
11	Rear Boot Handle Moulding			\$ 329.40	sub X
12	Rear Boot Licence Plate			\$ 40.00 SN	scr ✓ 40 s/n
13	Rear Boot Lock			\$ 298.50	daye ✓
14	Rear end panel top steel plate			\$ 208.30	best ✓
15	Rear Boot weatherstrip			\$ 366.00	two ✓
16	Rear Taillamp (Left & Right) 408.10	2	\$487.50	\$ 975.00	disc one o/s n 1 p c
17	Left Rear Corner Panel Garnish			\$ 138.40	R X
18	Left Rear Corner Panel Garnish Retainer			\$ 63.50	in X
19	Rear Bumper			\$ 687.40	dis ✓
20	Rear Bumper Clips			\$ 30.00 SN	new ✓ s/n
21	Rear Bumper Reverse Sensor			\$ 200.00 SN	replacement ✓ s/n
22	Rear Bumper Retainer (Left & Right)	2	\$89.50	\$ 179.00	in X
23	Rear End Panel 646.10		257	\$ 985.80	5.0.5.00 ✓

1 set

1 set

1 set

24 foillamp housing panel LH

520.50 two/best ✓

25	rear bumper lower brackets @60.20	4pcs		\$ 240.80	sent ✓
26	Rear Floor Matt Stay			\$ 196.80	11X
			(252)		
Labour					
1	To Dismantle & refix rear windscreen			\$ 120.00	✓
2	Transfer Boot			\$ 150.00	60
3	Check Air Con & Refill Gas			\$ 120.00	11X
4	Check Wiring			\$ 80.00	30
5	Anti Rust Proof			\$ 80.00	70
6	Panel Beating & Install Parts			\$ 900.00	850
7	Paint Work			\$ 1,000.00	800

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reserved and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-7910.30
 252
 P-5932.73
 SW-390
 L-1930
 8252.73
 208
 6602