



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110207/Uvh3m4
75 BRAS BASAH ROAD	Date:	22/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 4912S	Veh. Inspected	GX 70M
Policy No.	-	Coverage	0
Claim No.	MT/1303578- 001	Excess	\$0.00
Assign From	YEE PEI LI	Assign Date	11/11/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE VAN TURBO 4 DR AUTO	C.C	2982
Engine No.	1KD2628120	Year of Reg.	29/07/2016
Chassis No.	JTFHT02PX00200055	Colour	SILVER
Odometer	231781 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	HABILEAD	7
L/H Front Tyre	195R15	HABILEAD	7
R/H Rear Tyre	195R15	KAPSEN	7
L/H Rear Tyre	195R15	KAPSEN	7

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	08/11/2024	Inspection Date	12/11/2024 (09:36)
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days