



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMS 523D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	CUT/TORN	\$591.00	\$484.20
2	REAR BUMPER REVERSE SENSORS @\$169	SERVICEABLE	\$338.00	\$0.00
2	REAR BUMPER REFLECTORS @\$221	N/S TWISTED	\$442.00	\$221.00
1	REAR BUMPER REINFORCEMENT	CRACKED	\$454.00	\$294.80
2	REAR BUMPER INNER BRACKETS @\$99	NOT NECESSARY	\$198.00	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$594.00	\$0.00
1	REAR BUMPER LOWER GARNISH	CUT/TORN	\$380.00	\$340.00
1	REAR LICENCE PLATE HOLDER	DEFORMED	\$85.00	\$85.00
	<b>LESS 20.00% DISCOUNT</b>		(\$616.40)	(\$285.00)
			<b>\$2,465.60</b>	<b>\$1,140.00</b>
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER INNER CLIPS (SN)	NECESSARY	\$80.00	\$30.00
1	REAR NUMBER PLATE WITH COVER (SN)	BENT	\$100.00	\$40.00
			<b>\$180.00</b>	<b>\$70.00</b>
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUSTPROOF	NOT NECESSARY	\$100.00	\$0.00
	TO REMOVE/REFIT REAR INTERIOR TO EFFECT REPAIR	NOT NECESSARY	\$100.00	\$0.00
	TO DISMANTLE/RENEW ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$1,200.00	\$300.00
	TO SPRAY PAINT		\$1,000.00	\$500.00
			<b>\$2,400.00</b>	<b>\$800.00</b>
<b>GRAND TOTAL</b>			<b>\$5,045.60</b>	<b>\$2,010.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$1,600.00</b>
Report Ref No: CS/AGI24110210/Unp3m4				



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.