

SOON SAN MOTOR TRADING

Blk 3006 Ubi Rd 1, #01-390 Singapore 408700

Fax: 67473546 Tel: 68414445

Email: soonsanmotor@gmail.com

To :Motor Claims Dept

BUDGET DIRECT INSURANCE

190, Clemenceau Ave #03-01

Singapore Shopping Centre

Singapore 239924

Accident date: 02/11/2024

Date:06/11/2024

Estimate cost to repair vel: SMS 523D (Hyundai Avante S) claims under vel: SLN 3041X.

1pce rear bumper	cut/Torn	484.20\$	591.00 ✓
2pcs rear bumper reverse sensors @\$169	sc		338.00 X
2pcs rear bumper reflectors @\$221	N/S tm		442.00 12 L
10pcs rear bumper inner clips @\$10	neu		100.00 30 S/W
1pce rear bumper reinforcement	294.80 cne		454.00 ✓
2pcs rear bumper inner brackets @\$99	^^		198.00 X
1pce rear end panel	R		594.00 X
1pce rear bumper Lower garnish	cut/Torn		382.00 ✓ 340
1pc rear licence plate holder	re + 85.00		\$ 2,717.00
Less 20%			543.40
			2,173.60
1pce rear number plate with cover	Bent		100.00 40 S/W
To rustproof	^^		100.00 X
To remove/refit rear interior to effect repair	^^		100.00 X
To dismantle/renew accident portion			1,200.00 300
To spray paint			1,000.00 500
Total:			\$4,673.60

not Authorised
in
motor
1/11/24
L/S \$1600
to ph. Atty.
3 days.

Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1425
20%
1140
70
800
2010
202
1608