

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE 24.06.2024

TO	AIG MOTOR CLAIMS DEPTS
VEHICLE NO	SMD5241M
MODEL	HYUNDAI ELANTRA
DATE OF ACCIDENT	13.06.2024
TIME OF ACCIDENT	23:550 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>corn</i>	1	\$ 757.40	\$ 757.40
2	REAR BUMPER REFLECTOR RH <i>new</i>	1	\$ 72.50	\$ 72.50
3	REAR BUMPER MUDFLAP RH <i>gal n</i>	1	\$ 159.00	\$ 159.00
4	REAR BUMPER SIDE RETAINER	2	\$ 57.30	\$ 114.60
5	REAR FENDER RH <i>Reis</i>	1	\$ 1,470.00	\$ 1,470.00
6	REAR FENDER COWLING RH <i>gal</i>	1	\$ 250.00	\$ 250.00
7	REAR WINDSCREEN MOULDING <i>gal</i>	1	\$ 180.00	\$ 180.00
8	TAILLAMP RH	1	\$ 876.80	\$ 876.80
9	REAR WHEEL RIM RH <i>gal</i>	1	\$ 1,120.00	\$ 1,120.00
10	REAR AXLE <i>gal</i>	1	\$ 2,140.00	\$ 2,140.00
11	REAR SHOCK ABSORBER RH <i>gal</i>	1	\$ 475.00	\$ 475.00
12	REAR WHEEL HUP WITH BEARING RH <i>gal</i>	1	\$ 525.00	\$ 525.00
13	REAR ABS SENSOR RH	1	\$ 325.00	\$ 325.00
14	REAR DOOR RH <i>Dented</i>	1	\$ 1,280.00	\$ 1,280.00
15	REAR DOOR WEATHER STRIP RH <i>gal</i>	1	\$ 198.00	\$ 198.00
16	REAR DOOR LOCK CATCH RH <i>gal</i>	1	\$ 45.00	\$ 45.00
17	REAR DOOR INNER LOCK RH <i>gal</i>	1	\$ 425.00	\$ 425.00
18	REAR DOOR GLASS REGULATOR GEAR MOTOR RH <i>Reis</i>	1	\$ 770.00	\$ 770.00
19	REAR DOOR GLASS FRAME BLACK STICKER RH <i>new</i>	1	\$ 160.00	\$ 160.00
20	REAR DOOR OUTER MOULDING RH <i>gal</i>	1	\$ 118.00	\$ 118.00
21	REAR DOOR INNER TRIM BOARD RH <i>gal</i>	1	\$ 950.00	\$ 950.00

TO
VEHICLE NO
MODEL
DATE OF ACCIDENT
TIME OF ACCIDENT

AIG MOTOR CLAIMS DEPTS
SMD5241M
HYUNDAI ELANTRA
13.06.2024
23:550 HOURS

TOTAL PRICE \$ 12,411.30
LESS 20% \$ 2,482.26
SUB TOTAL PRICE \$ 9,929.04

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	TAILLAMP CLIP RH (SET) <i>New</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
3	REAR DOOR TRIM BOARD CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
4	REAR FENDER SEALANT RH <i>New</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
5	REAR WINDSCREEN GLASS SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
6	REAR WINDSCREEN GLASS INNER SHIELD RH <i>New</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
7	REAR WHEEL TYRE <i>New</i>	2	\$ 380.00	\$ 760.00 <i>+</i>
8	BRAKE OIL <i>New</i>	1	\$ 30.00	\$ 30.00 <i>+</i>

TOTAL \$ 1,190.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (SIDE)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,000.00	<i>400</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>40.</i>
4	WIRING CHECK	\$ 250.00	<i>+</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 650.00	<i>+</i>
6	FOUR WHEEL ALIGNMNET	\$ 120.00	<i>+</i>
7	TRANSFER REAR DOOR MECHANISM	\$ 80.00	<i>60</i>

TO
VEHICLE NO
MODEL
DATE OF ACCIDENT
TIME OF ACCIDENT

AIG MOTOR CLAIMS DEPTS
SMD5241M
HYUNDAI ELANTRA
13.06.2024
23:550 HOURS

8	REMOVE & REFIX AUDIO SPEAKER	\$	150.00	X
9	CONDUCT WATER LEAKAGE TEST	\$	120.00	X
10	REMOVE & REFIX REAR WINDSCREEN	\$	120.00	X
11	REMOVE AND REFIX REAR UNDERCARRIAGE	\$	650.00	X
12	RESET ABS LIGHT	\$	350.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	350.00	X

TOTAL \$ **6,540.00**

ESTIMATE REPORT

TOTAL PARTS COST \$ 11,119.04
TOTAL LABOUR COST \$ 6,540.00
TOTAL REPAIR COST \$ 17,659.04

Adnan G
1/1 24/06/24
04 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: