

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@proccarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay

#21-00

Singapore 048580

Tel: 62222311

Fax: 62223547

Attn: Motor Claim Department \ FIRST
CAPITAL

Your Ref No: TP 1124-8354

Claim Type: Third Party

Accident Date: 09 November 2024

TP Veh Reg No: SHA7260U

Estimate No: EST1512027

Date: 11 Nov 2024

Policy No: DMPPHQ24-00033

Veh Reg No: SNM7075D

Make/Model: SUBARU FORESTER

2.0I-L CVT AWD SR

Chassis No: JF1SJ5KC5JG111819

Engine No: FB20YE42383

Reg. Date: 17 Sep 2018

Estimate Repair Cost to Vehicle No: SNM7075D

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 FRONT BUMPER	641.90	1 PC	641.90	✓
2 FRONT BUMPER SIDE RETAINER - LH/RH	19.50	2 PC	39.00	✓
3 FRONT BUMPER CLIPS	3.90	10 PC	39.00	✓
4 FRONT FENDER - RH	306.00	1 PC	306.00	✓
5 FRONT FENDER COWLING - RH	126.70	1 PC	126.70	✓
6 FRONT FENDER COWLING CLIPS - RH	5.40	10 PC	54.00	✓
			1,206.60	
		Less 20%	-241.32	965.28
Labour				
7 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	500.00	1 JOB	500.00	200
8 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	550.00	1 JOB	550.00	400
9 TO CHECK WIRING-	50.00	1 JOB	50.00	20
10 ANTI RUST-	40.00	1 JOB	40.00	✓
				1,140.00

Total 2,105.28

Add GST @ 9% 189.48

Total Amount Payable SGD 2,294.76

SINGAPORE DOLLAR TWO THOUSAND TWO HUNDRED NINETY FOUR AND CENTS SEVENTY SIX ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE