

F-1 AUTOCLINIC PTE LTD

25 KAKI BUKIT ROAD4 # 05-26 SYNERGY @KB Singapore 417800

L RENO
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

T? AIG.
Daphne

12th NOV 2024

Accident date: 08th NOV 2024

Estimated repair cost for vehicle no: GBD2309C TOYOTA DYNA DYNA 150 2014 (COE 2029)

S/n	Qty	Items	U/price	Amount	
1	1	Front bumper <i>Distorted</i>		\$588.00	✓
2	1	Front bumper inner center crossmember <i>Dented</i>		\$681.25	259. ✓
3	1	Front R/H chassis <i>Repair</i>		\$788.00	x. ✓
4	1	Front grille <i>Smashed</i>		\$387.72	✓
5	4	Front grille clips <i>new</i>	\$12.90	\$51.60	20. ✓
6	1	Front center top crossmember <i>new</i>		\$581.40	x ✓
7	2	Front center top crossmember side bracket <i>new</i>	\$231.75	\$463.50	x ✓
8	1	Front wiper panel (center) <i>new</i>		\$591.25	x ✓
9	1	Front panel <i>Repair</i>		\$981.40	x ✓
10	1	Front panel top cover (center) <i>new</i>		\$287.72	x ✓
11	1	front panel emble logo <i>new</i>		\$83.70	✓
12	1	Front side panel <i>Dented</i>		\$182.25	✓
13	2	Front side panel top cover (side) <i>new</i>	\$141.25	\$282.50	x ✓
14	8	Front side panel top cover clips <i>new</i>	\$12.90	\$103.20	x ✓
15	1	Front panel top cover (center) clips <i>new</i>		\$12.90	x ✓
16	2	Front headlamp <i>RH Smashed, LH could</i>	\$877.00	\$1,754.00	✓
17	2	Front headlamp panel <i>new</i>	\$381.40	\$762.80	x ✓
18	1	front side mirror RH <i>new</i>	\$282.00	\$282.00	x ✓
19	1	Front brake booster <i>new</i>		\$899.00	x ✓
20	1	front brake booster with sensor <i>Air Tank But</i>		\$455.00	321 ✓
21	1	Front R/H door <i>Distorted</i>		\$981.40	✓
22	1	Front R/H door inner hinges <i>new</i>		\$80.70	x ✓
23	1	Front RH door step panel rubber cover <i>missing</i>		\$289.90	✓
24	1	Front R/H door inner lock <i>new</i>		\$381.55	✓
25	1	Front R/H door inner gear <i>new</i>		\$161.40	x ✓
26	1	Front R/H door inner gear motor <i>new</i>		\$561.55	x ✓
27	1	Front R/H door outer handle <i>new</i>		\$161.70	x ✓

28	1	Front R/H door inner trim board <i>could</i>	\$561.35	✓
29	1	Front R/H door inner rubber <i>at</i>	\$182.20	✓
30	1	Front R/H arch panel <i>Revis</i>	\$281.10	x
31	1	Front R/H arch panel garnish cover <i>could</i>	\$261.70	✓

6253.77
4690.32

Subtotal :- \$14,123.74

Labour charges

To remove & re-fix front brake booster with sensor

\$180.00 x

To check wheel alignment computer

\$120.00 x

To check wiring system

\$100.00 30

Tuff kote

\$150.00 80

Panel beating

\$1,400.00 80

Spray painting

\$1,200.00 100

Subtotal :- \$3,150.00

Total:- \$17,273.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6600.32
4/5: 5.2K
07 Days