

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

**KONG HWEE IRON WORKS &
 CONSTRUCTION PTE LTD**
 7 SENOKO SOUTH ROAD
 SINGAPORE 758071

Contact : 87000343 90661047

TAX INVOICE

Repair Code : CLM18453

Date in : 27/10/2024

Vehicle Num. : GBK2627Y

Model : NISSAN CABSTAR SINGLE CAB AT

Chassis/Eng# : JN1SA2F24Z0000129/QR20999953Q

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR END PANEL	1	326.00	326.00
REAR END SIDE PANEL LH	1	105.00	105.00
REAR END SIDE PANEL RUBBER STOPPER LH	2	20.00	40.00
REAR LH TAILLAMP ASSY	1	206.70	206.70
REAR LH TAILLAMP BRACKET	1	65.00	65.00
REAR TAILGATE	1	1459.60	1,459.60
REAR TAILGATE HINGES	3	27.30	81.90
REAR TAILGATE SIDE LOCK LH	1	182.90	182.90
Subtotal before discount			2,467.10
Percentage discount 10%			246.71
Sub-total 1			2,220.39
REAR NUMBER PLATE	1	25.00	25.00
REAR NUMBER PLATE HOLDER	1	50.00	50.00
REAR REVERSE SENSOR - SET	1	280.00	280.00
REAR TAILGATE '12PAX' STICKER	1	25.00	25.00
REAR TAILGATE '70KM' STICKER	1	25.00	25.00
REAR TAILGATE 'COMPANY 3D ARTWORK' STICKER	1	450.00	450.00
REAR TAILGATE ALUMINIUM PLATE	1	800.00	800.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

**KONG HWEE IRON WORKS &
 CONSTRUCTION PTE LTD**
 7 SENOKO SOUTH ROAD
 SINGAPORE 758071

TAX INVOICE

Repair Code : CLM18453

Date in : 27/10/2024

Vehicle Num. : GBK2627Y

Model : NISSAN CABSTAR SINGLE CAB AT

Chassis/Eng# : JN1SA2F24Z0000129/QR20999953Q

Contact : 87000343 90661047

REAR TAILGATE ALUMINIUM PLATE RIVET	1	120.00	120.00
REAR TAILGATE HINGES PIN & NUT - SET	3	25.00	75.00
Subtotal before discount			1,850.00
Percentage discount 0%			0.00
Sub-total 2			1,850.00
Parts-total			4,070.39

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800.00
To apply anti-rust chemical on repaired and replaced panel.	120.00
Labour Total	1,880.00
Parts & Labour Total	5,950.39

*** This is a computer-generated document which requires no signature.***