

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

TP INC.  
 Xiao Chan.

**KONG HWEE IRON WORKS &  
 CONSTRUCTION PTE LTD**  
 7 SENOKO SOUTH ROAD  
 SINGAPORE 758071

## TAX INVOICE

Repair Code : CLM18453

Date in : 27/10/2024

Vehicle Num. : GBK2627Y

Model : NISSAN CABSTAR SINGLE CAB AT

Chassis/Eng# : JN1SA2F24Z0000129/QR20999953Q

Contact : 87000343 90661047

### Parts and Labour Assesment

| Description of part                                     | Qty | Unit Price | Amount          |
|---------------------------------------------------------|-----|------------|-----------------|
| FRONT BUMPER <i>Abd m</i>                               | 1   | 907.30     | + 907.30        |
| FRONT CABIN REAR MUDFLAP <i>lit</i>                     | 1   | 307.50     | ✓ 307.50        |
| FRONT LH DOOR <i>Rejo</i>                               | 1   | 1674.90    | + 1,674.90      |
| FRONT LH DOOR CHECKER <i>re u</i>                       | 1   | 60.92      | + 60.92         |
| FRONT LH DOOR HINGE (BOTTOM) <i>2</i>                   | 1   | 65.70      | + 65.70         |
| FRONT LH DOOR HINGE (TOP) <i>lit</i>                    | 1   | 65.70      | + 65.70         |
| FRONT LH DOOR INNER TRIM BOARD <i>lit</i>               | 1   | 823.70     | + 823.70        |
| FRONT LH DOOR SIGNAL LAMP <i>combined</i>               | 1   | 67.80      | ✓ 67.80         |
| FRONT LH DOOR STEP GARNISH <i>lit</i>                   | 1   | 192.30     | - 192.30        |
| FRONT LH DOOR WEATHER STRIP <i>re u</i>                 | 1   | 159.10     | + 159.10        |
| REAR LH SIDE GATE <i>Rejo</i>                           | 1   | 2987.10    | + 2,987.10      |
| REAR LH SIDE GATE HINGES <i>Abd m</i>                   | 5   | 63.20      | + 316.00        |
| Subtotal before discount                                |     |            | 7,628.02        |
| Percentage discount 10%                                 |     |            | 762.80          |
| <b>Sub-total 1</b>                                      |     |            | <b>6,865.22</b> |
| FRONT LH DOOR '3D' ART WORK STICKER <i>3 per</i>        | 1   | 400.00     | 150 400.00      |
| FRONT LH DOOR COMPANY DECAL STICKER                     | 1   | 25.00      | ✓ 25.00         |
| FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>Abd m</i> | 1   | 50.00      | + 50.00         |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

KONG HWEE IRON WORKS &  
CONSTRUCTION PTE LTD  
7 SENOKO SOUTH ROAD  
SINGAPORE 758071

Contact : 87000343 90661047

## TAX INVOICE

Repair Code : CLM18453

Date in : 27/10/2024

Vehicle Num. : GBK2627Y

Model : NISSAN CABSTAR SINGLE CAB AT

Chassis/Eng# : JN1SA2F24Z0000129/QR20999953Q

|                                          |   |        |     |          |
|------------------------------------------|---|--------|-----|----------|
| FRONT LH DOOR STEP GARNISH CLIPS - SET   | 1 | 30.00  | x   | 30.00    |
| FRONT LH RIM                             | 1 | 800.00 | +   | 800.00   |
| FRONT LH TYRE                            | 1 | 380.00 | +   | 380.00   |
| REAR LH SIDE GATE '3D' ART WORK STICKER  | 1 | 600.00 | 280 | 600.00   |
| REAR LH SIDE GATE HINGES PIN & NUT - SET | 5 | 80.00  | +   | 400.00   |
| Subtotal before discount                 |   |        |     | 2,685.00 |
| Percentage discount 0%                   |   |        |     | 0.00     |
| Sub-total 2                              |   |        |     | 2,685.00 |
| Parts-total                              |   |        |     | 9,550.22 |

## LABOUR

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

|                      |           |
|----------------------|-----------|
| Labour Total         | 1,760.00  |
| Parts & Labour Total | 11,310.22 |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian L  
2/s 12/11/24  
03 Days  
Total: 1705.84  
2/s 13K ✓