

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TRINC.

xiao Chan.

**KONG HWEE IRON WORKS &
 CONSTRUCTION PTE LTD**
 7 SENOKO SOUTH ROAD
 SINGAPORE 758071

TAX INVOICE

Repair Code : CLM18453

Date in : 27/10/2024

Vehicle Num. : GBK2627Y

Model : NISSAN CABSTAR SINGLE CAB AT

Chassis/Eng# : JN1SA2F24Z0000129/QR20999953Q

Contact : 87000343 90661047

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Abd m</i>	1	907.30	+ 907.30
FRONT CABIN REAR MUDFLAP <i>lit</i>	1	307.50	✓ 307.50
FRONT LH DOOR <i>Rejo</i>	1	1674.90	+ 1,674.90
FRONT LH DOOR CHECKER <i>re u</i>	1	60.92	+ 60.92
FRONT LH DOOR HINGE (BOTTOM) <i>2</i>	1	65.70	+ 65.70
FRONT LH DOOR HINGE (TOP) <i>lit</i>	1	65.70	+ 65.70
FRONT LH DOOR INNER TRIM BOARD <i>lit</i>	1	823.70	+ 823.70
FRONT LH DOOR SIGNAL LAMP <i>combined</i>	1	67.80	✓ 67.80
FRONT LH DOOR STEP GARNISH <i>lit</i>	1	192.30	- 192.30
FRONT LH DOOR WEATHER STRIP <i>re u</i>	1	159.10	+ 159.10
REAR LH SIDE GATE <i>Rejo</i>	1	2987.10	+ 2,987.10
REAR LH SIDE GATE HINGES <i>Abd m</i>	5	63.20	+ 316.00
Subtotal before discount			7,628.02
Percentage discount 10%			762.80
Sub-total 1			6,865.22
FRONT LH DOOR '3D' ART WORK STICKER <i>3 per</i>	1	400.00	150 400.00
FRONT LH DOOR COMPANY DECAL STICKER	1	25.00	✓ 25.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>Abd m</i>	1	50.00	+ 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KONG HWEE IRON WORKS &
CONSTRUCTION PTE LTD
7 SENOKO SOUTH ROAD
SINGAPORE 758071

Contact : 87000343 90661047

TAX INVOICE

Repair Code : CLM18453

Date in : 27/10/2024

Vehicle Num. : GBK2627Y

Model : NISSAN CABSTAR SINGLE CAB AT

Chassis/Eng# : JN1SA2F24Z0000129/QR20999953Q

FRONT LH DOOR STEP GARNISH CLIPS - SET	1	30.00	+	30.00
FRONT LH RIM	1	800.00	+	800.00
FRONT LH TYRE	1	380.00	+	380.00
REAR LH SIDE GATE '3D' ART WORK STICKER	1	600.00	280	600.00
REAR LH SIDE GATE HINGES PIN & NUT - SET	5	80.00	+	400.00
Subtotal before discount				2,685.00
Percentage discount 0%				0.00
Sub-total 2				2,685.00
Parts-total				9,550.22

LABOUR

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,760.00
Parts & Labour Total	11,310.22

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
2/s 12/11/24
03 Days
Total: 1705.84
2/s 13K ✓