

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	INCOME INSURANCE LTD  75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Ref:	CS/INC24110219/Avh3m4
			Date:	23/12/2024
	INCOME CENTRE	ON ONE 100007	Code:	INC
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBQ 7013D	Veh. Inspected	SLR 9329G
	Policy No.	-	Coverage	0
	Claim No.	MT/1301433-002	Excess	\$0.00
	Assign From	AZHARI AFIDI	Assign Date	11/11/2024
2. Vehicle Details				
	Make & Model	TOYOTA PRIUS	C.C	1797
	Engine No.	2ZR1986885	Year of Reg.	31/08/2017
	Chassis No.	ZVW400026063	Colour	SILVER
	Odometer	580865 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	3. Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	205/60R16	BRIDGESTONE	6
	L/H Front Tyre	205/60R16	BRIDGESTONE	6
	R/H Rear Tyre	205/60R16	BRIDGESTONE	6
	L/H Rear Tyre	205/60R16	BRIDGESTONE	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	25/10/2024	Inspection Date	12/11/2024 (15:09)
	Survey held at	N-51 AUTOMOTIVE PL	•	·
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB		
		SINGAPORE 417921		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				