

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP MC
Veron.

TWINBIZ RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

TAX INVOICE

Repair Code : CLM18447

Date in : 08/11/2024

Vehicle Num. : SLR9329G

Model : TOYOTA PRIUS ALPHA 1.8S CVT

Chassis/Eng# : ZVW400026063/2ZR1986885

Contact : 91528314

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>torn</i>	1	869.00	869.00 <i>630</i>
FRONT BUMPER LED LAMP RH <i>Cracked</i>	1	895.00	895.00 <i>390</i>
FRONT BUMPER LOWER GRILLE <i>cut</i>	1	789.60	789.60 <i>486</i>
FRONT BUMPER NUMBER PLATE GARNISH <i>Delivered</i>	1	115.00	115.00 <i>-</i>
FRONT BUMPER REINFORCEMENT <i>new</i>	1	1010.00	1,010.00 <i>+</i>
FRONT BUMPER RH FOGLAMP <i>new</i>	1	516.00	516.00 <i>+</i>
FRONT BUMPER SIDE AIR DUCT RH <i>new cut</i>	1	178.90	178.90 <i>✓</i>
FRONT BUMPER SIDE BRACKET RH <i>new</i>	1	79.00	79.00 <i>104.50</i>
FRONT BUMPER SIDE RETAINER L/R <i>new RH Cracked</i>	2	104.50	209.00 <i>104.50</i>
FRONT BUMPER SPONGE <i>new Cracked</i>	1	110.20	110.20 <i>✓</i>
FRONT BUMPER TOP RUBBER SEAL <i>new</i>	1	141.00	141.00 <i>+</i>
FRONT BUMPER TOW HOOK COVER L/R <i>new</i>	2	42.70	85.40 <i>+</i>
FRONT BUMPER UNDER COVER <i>new</i>	1	405.00	405.00 <i>+</i>
FRONT GRILLE <i>new</i>	1	572.00	572.00 <i>+</i>
FRONT RH FENDER <i>Repair</i>	1	1400.50	1,400.50 <i>+</i>
FRONT RH FENDER 'HYBRID' EMBLEM <i>new</i>	1	75.90	75.90 <i>-</i>
FRONT RH HEADLAMP <i>Cracked</i>	1	3890.00	3,890.00 <i>12721</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINBIZ RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 91528314

TAX INVOICE

Repair Code : CLM18447
Date in : 08/11/2024
Vehicle Num. : SLR9329G
Model : TOYOTA PRIUS ALPHA 1.8S CVT
Chassis/Eng# : ZVW400026063/2ZR1986885

		Subtotal before discount	5980.50	11,341.50
Percentage discount 25%			4485.37	2,835.38
		Sub-total 1		8,506.13
FRONT BUMPER CLIPS - SET	1	80.00	80.00	30
FRONT BUMPER NUMBER PLATE	1	25.00	25.00	85
FRONT BUMPER NUMBER PLATE HOLDER	1	50.00	50.00	30
		Subtotal before discount		155.00
Percentage discount 0%				0.00
		Sub-total 2		155.00
		Parts-total		8,661.13

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total 1,780.00
Parts & Labour Total 10,441.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*** This is a computer-generated document which requires no signature. ***

page 2

4.21C

Adrian L
A/c 12/11/24.
03 Days
Total: 5300.37
L/S: A.2K