

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	S INCOME INSURANCE LTD		Ref:	CS/INC24110220/Avh3m4	
	75 BRAS BASAH ROAD		Date:	23/12/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
4		Deline Bertherless - 3			
1.					
		SLA 44 18E	Veh. Inspected		
	Policy No. Claim No.	- MT/1303709-001	Coverage Excess	\$0.00	
		YEE PEI LI	-	11/11/2024	
•	Assign From		Assign Date	11/11/2024	
2.	Make & Model	Vehicle KIA NIRO	C.C	1580	
		G4LLPS179492		14/07/2023	
	Engine No. Chassis No.	KNACT81EVR5107346	Year of Reg.	WHITE	
	Odometer	31688 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)		General	GOOD	
_	Times of Cities in the Cities				
3.					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/60R16	NEXEN	6	
	L/H Front Tyre	205/60R16	NEXEN	6	
	R/H Rear Tyre	205/60R16	NEXEN	6	
	L/H Rear Tyre	205/60R16	NEXEN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	11/11/2024	Inspection Date	12/11/2024 (15:01)	
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD			
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB			
		SINGAPORE 417921			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.					
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					