

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

RAYSON ONG RUI JUN
BLK 473A NORTHSHORE DR #06-1575
SINGAPORE 821437

Contact : 93804455

TAX INVOICE

Repair Code : CLM16469

Date in : 11/11/2024

Vehicle Num. : SND6280G

Model : KIA NIRO SG2 HYBRID 1.6 SX DCT SUNROOF

Chassis/Eng# : KNACT81EVR5107346/G4LLPS179492

TP INC.
Veron

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Disturbed</i>	1	1837.00	✓ 1,837.00
FRONT LH DOOR CHECKER <i>new</i>	1	65.00	+ 65.00
FRONT LH DOOR FRAME GARNISH (REAR) <i>new</i>	1	50.00	+ 50.00
FRONT LH DOOR HINGE (BOTTOM) <i>new</i>	1	40.00	+ 40.00
FRONT LH DOOR HINGE (TOP) <i>new</i>	1	40.00	+ 40.00
FRONT LH DOOR INNER GARNISH <i>Disturbed</i>	1	175.00	✓ 175.00
FRONT LH DOOR INNER PILLAR (FRONT) <i>new</i>	1	1180.00	+ 1,180.00
FRONT LH DOOR INNER TRIM BOARD <i>Disturbed</i>	1	757.00	✓ 757.00
FRONT LH DOOR LOWER GARNISH <i>missing</i>	1	171.00	✓ 171.00
FRONT LH DOOR MECHANISM LOCK <i>Disturbed</i>	1	269.00	✓ 269.00
FRONT LH DOOR NOSE COVER <i>new</i>	1	30.00	+ 30.00
FRONT LH DOOR OUTER HANDLE <i>new</i>	1	163.00	+ 163.00
FRONT LH DOOR OUTER HANDLE INNER BRACKET <i>new</i>	1	52.00	+ 52.00
FRONT LH DOOR OUTER MOULDING <i>new</i>	1	60.00	+ 60.00
FRONT LH DOOR OUTER TOP FRAME CHROME MOULDING <i>new</i>	1	90.00	+ 90.00
FRONT LH DOOR SIDE MIRROR ASSY <i>new</i>	1	950.00	+ 950.00
FRONT LH DOOR WEATHER STRIP <i>new</i>	1	120.00	✓ 120.00
FRONT LH DOOR WINDOW GLASS REGULATOR <i>Disturbed</i>	1	283.00	✓ 283.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

RAYSON ONG RUI JUN
BLK 473A NORTHSHORE DR #06-1575
SINGAPORE 821437

Contact : 93804455

TAX INVOICE

Repair Code : CLM16469

Date in : 11/11/2024

Vehicle Num. : SND6280G

Model : KIA NIRO SG2 HYBRID 1.6 SX DCT SUNROOF

Chassis/Eng# : KNACT81EVR5107346/G4LLPS179492

FRONT LH DOOR WINDOW GLASS REGULATOR MOTOR	<i>Dmgd</i>	1	362.00	<i>✓</i>	362.00
FRONT LH FENDER	<i>Repr</i>	1	435.00	<i>+</i>	435.00
FRONT LH FENDER ARCH GARNISH	<i>nt</i>	1	125.00	<i>✓</i>	125.00
FRONT LH FENDER INNER SHIELD COVER	<i>nt</i>	1	100.00	<i>+</i>	100.00
LH ROCKER PANEL	<i>Repr</i>	1	649.00	<i>+</i>	649.00
REAR LH DOOR	<i>Dented</i>	1	1542.00	<i>✓</i>	1,542.00
REAR LH DOOR CHECKER	<i>nt</i>	1	65.00	<i>+</i>	65.00
REAR LH DOOR FRAME GARNISH (FRONT)	<i>nt</i>	1	98.00	<i>+</i>	98.00
REAR LH DOOR FRAME GARNISH (REAR)	<i>2</i>	1	60.00	<i>+</i>	60.00
REAR LH DOOR HINGE (BOTTOM)	<i>nt</i>	1	38.00	<i>+</i>	38.00
REAR LH DOOR HINGE (TOP)	<i>nt</i>	1	38.00	<i>+</i>	38.00
REAR LH DOOR INNER PROTECTOR GARNISH	<i>nt</i>	1	115.00	<i>✓</i>	115.00
REAR LH DOOR WEATHER STRIP (FRONT)	<i>nt</i>	1	125.00	<i>✓</i>	125.00
Subtotal before discount					10,084.00
Percentage discount 10%					1,008.40
Sub-total 1					9,075.60
FRONT LH DOOR INNER SPEAKER	<i>nt</i>	1	800.00	<i>+</i>	800.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	<i>nt</i>	1	50.00	<i>30</i>	<i>50.00</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

RAYSON ONG RUI JUN
BLK 473A NORTHSHORE DR #06-1575
SINGAPORE 821437

Contact : 93804455

TAX INVOICE

Repair Code : CLM16469

Date in : 11/11/2024

Vehicle Num. : SND6280G

Model : KIA NIRO SG2 HYBRID 1.6 SX DCT SUNROOF

Chassis/Eng# : KNACT81EVR5107346/G4LLPS179492

FRONT LH DOOR LOWER GARNISH CLIPS - SET <i>new</i>	1	50.00	<i>30</i> 50.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	30.00	<i>✓</i> 30.00
FRONT LH FENDER INNER SHIELD COVER CLIPS - SET <i>new</i>	1	30.00	<i>120</i> 30.00
REAR LH DOOR INNER PROTECTOR GARNISH CLIPS - SET <i>new</i>	1	50.00	<i>50</i> 50.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>50</i> 50.00
Subtotal before discount			1,060.00
Percentage discount 0%			0.00
Sub-total 2			1,060.00
Parts-total			10,135.60

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	3,080.00
Parts & Labour Total	13,215.60

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin LG
2/5 12/11/24
06 Days
Total: 7362.90
4/5: 5.8K ✓