

CENTURY MOTORS PRIVATE LIMITED
INCHCAPE CENTRE
SINGAPORE 128462

Insurer Reference: SJT7976P
Repairer Reference: CM/10/24/0025
Date calculated: 10/12/2024 4:03 PM

Full Report
Registration: SJT7976P
Printed: 10/12/2024 4:03 PM

Summary Information

| | | | |
|------------------------|----------------|-------------------|---|
| Claim | | | |
| Location: | Singapore (SG) | Work Provider: | China Taiping Insurance (Singapore) Pte Ltd |
| Printed by: | Lim Mei Hong | Currency: | SGD |
| Claim Reference: | SJT7976P | Date of Incident: | 01/10/24 |
| Estimated Repair Time: | 3 | Hire Car Start: | |
| Actual Repair Days: | 3 | Hire Car End: | |

Vehicle Details


| | | | |
|----------------------|-------------------|---------------------|--|
| Vehicle | | | |
| Manufacturer: | LEXUS | | |
| Model: | IS (E2) | | |
| Sub Model: | 250C | | |
| Model Sheet Number: | 24 83 18 | | |
| Registration: | SJT7976P | | |
| VIN number: | JTHFK252102507468 | | |
| Odometer: | | | |
| Model Specs | | | |
| FRT/RR PARK DIST CON | TWO COAT METALLIC | PREPARE OFF VEHICLE | |

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

| Tyre Brand | Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner),Tread (Right Outer),Tread (Right Middle), mm | | | | | | Condition |
|------------------|---|----|----|----|----|----|-----------|
| | mm | mm | mm | mm | mm | mm | |
| | | | | | | | |
| Spare Tyre Brand | Tread (Spare), mm | | | | | | |

Labour

| | | Time Base 10 WU/h | Price = 42.00 SGD/h | |
|---------------------------|---|-------------------|---------------------|-----------|
| Code | Description | | WU | Price SGD |
| B410 | R + R REAR BUMPER INCLUDES: R + R BOOT TRIMS | | 9.0 | 37.80 |
| NO NUMBER | R + R REAR PARKING AID SENSOR/S | | 2.0 | 8.40 |
| 2583 | REAR BUMPER REPAIR | To repair | 30.0* | 126.00 / |
| Labour Cost | | Hrs | WU | |
| Panel / Mechanical Labour | | 4.10 | 41.0 | 172.20 |
| Total of Labour | | | | 172.20 |

Paint

| Paint Work | | SYSTEM AZT | Time Basis 10 WU/h |
|------------|----------------------------------|------------|--------------------|
| Code | Description - TWO COAT METALLIC | | WU Price SGD |
| | REAR BUMPER REPAIR PAINT PLASTIC | | 17.0 |

Insurer Reference: SJT7976P
 Repairer Reference: CM/10/24/0025
 Date calculated: 10/12/2024 4:03 PM

Full Report
 Registration: SJT7976P
 Printed: 10/12/2024 4:03 PM

Paint Material Per Part

| Code | Description | Price SGD |
|------|----------------------------------|-----------|
| 2583 | REAR BUMPER REPAIR PAINT PLASTIC | 55.89 |

Labour Cost - Paint

| | 42.00 SGD/h | Hrs | WU | Price SGD |
|--------------------------------|----------------|-------------|-------------|---------------|
| Factor | | | | |
| Time Paint | | | 17.0 | |
| Preparation Comp. Work Plastic | | 2.50 | 25.0 | 105.00 |
| Total | 10 WU/h | 4.20 | 42.0 | 176.40 |

Material Cost - Paint

| | Price SGD |
|---------------------------|--------------|
| Repair Painting Plastic | 55.89 |
| Material-constant Plastic | 28.60 |
| Total | 84.49 |

Spare Parts

| Code | Description | Part Number | Part Source | prices as at 2015-06-01 | Price SGD |
|------------------|---------------------|-------------|---------------|-------------------------|---------------|
| 2675 | L/R CTR SENSOR BRKT | 89348 44010 | Supplementary | Nec (Nett) | 80.00 / |
| 2676 | R/R CTR SENSOR BRKT | 89348 44010 | Supplementary | Nec (Nett) | 80.00 / |
| f: OEM Parts | Savings | | | | 0.00 |
| n: Non-OEM Parts | Subtotal | | | | 160.00 |
| u: Used parts | Total | | | | 160.00 |

Final Calculation

| | SGD | SGD |
|---------------------------------------|--------|---------------|
| Parts | 160.00 | |
| Total Parts | | 160.00 |
| Labour Time Base 10 WU/h | | |
| Total 41.0 WU X 42.00 SGD/h | 172.20 | |
| Total of Labour | | 172.20 |
| Paint Work Time Base 10 WU/h | | |
| Labour Cost 42.0 WU X 42.00 SGD/h | 176.40 | |
| Material Cost | 84.49 | |
| Total Paint Including Material | | 260.89 |
| Repair Cost Excludes GST | | 593.09 |
| GST (+9.00%) | | 53.38 |
| Repair Cost Included GST | | 646.47 |

Insurer Reference: SJT7976P
Repairer Reference: CM/10/24/0025
Date calculated: 10/12/2024 4:03 PM

Full Report
Registration: SJT7976P
Printed: 10/12/2024 4:03 PM

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.