



BFCARS



AUTOMOBILE
BANG. FIX. CLAIM.

Not Allowed
as
Motor
12/10/24
1/5 \$ 4000
Chassis Assembly
5 day

Carplate: SFM23U
Chassis No: MR053BK4107032344
Accident Date: 07/10/2024
Make & Model: Toyota Camry

No.	Item	List Price	✓/✗	Remarks
1	Front Fender LH	\$ 780.90		2 X
2	Front Fender LH Splashguard	\$ 162.40		1 X
3	Front Fender Logo VVT-I	\$ 79.10		net
4	Front Door LH	\$ 1,250.60		2 X
5	Front Door LH Trim Board	\$ 480.20		1 X
6	Front Door LH Weatherstrip	\$ 168.90		1 X
7	Front Door LH Side View Mirror Assembly	\$ 996.20		2 X
8	Front Door LH Moulding (Outer) <i>protector</i>	\$ 180.20		not required
9	Front Door LH Chrome (Outer)	\$ 132.90		sch
10	Rear Door LH	\$ 1,190.80		no/gel
11	Rear Door Hinge LH (Upper)	\$ 123.15		1 X
12	Rear Door Hinge LH (Lower)	\$ 123.15		1 X
13	Rear Door Check LH	\$ 115.20		1 X
14	Rear Door LH Trim Board	\$ 439.50		1 X
15	Rear Door LH Weatherstrip	\$ 172.90		1 X
16	Rear Door LH Lock Assembly	\$ 385.20		1 X
17	Rear Door LH Window Glass	\$ 312.60		1 X
18	Rear Door LH Window Glass Regulator	\$ 210.90		But
19	Rear Door LH Window Glass Motor	\$ 401.20		BU X
20	Rear Door LH Window Glass Moulding	\$ 131.60		1 X
21	Rear Door LH Moulding (Outer) <i>protector</i>	\$ 192.60		not required
22	Rear Door LH Chrome (Outer)	\$ 149.20		net
23	LH Rocker Panel <i>garage</i>	\$ 992.60		BU
24	Rear LH Fender	\$ 829.10		2 X
25	Rear LH Fender Splash Guard	\$ 165.20		1 X
26	Rear Bumper <i>732/0</i>	\$ 932.60		201/201
27	Rear Bumper Side Retainer LH	\$ 78.20		1 X
28	Rear Thrust Arm LH	\$ 362.10		1 X
29	Rear Wheel Bearing LH	\$ 210.90		1 X
30	Rear Knuckle Assembly LH	\$ 410.20		1 X
31	Rear Shock Absorber LH	\$ 439.20		1 X
32	Rear Control Arm LH	\$ 395.40		1 X
33				
34				
35				
36				

	Special Nett Items	Price	✓/✗	Remarks
1	Rear Door Trim Board Clips (1Set)	\$ 40.00		11X
2	Rear Fender Splash Guard Clips (1 Set)	\$ 40.00		11X
3	Front Fender Splash Guard Clips (1 Set)	\$ 40.00		11X
4	Front Door Trim Board Clips (1 Set)	\$ 40.00		11X
5	Rear Bumper Clips (1 Set)	\$ 40.00		11X 30 SIN
6	Rear Tyre LH	\$ 380.00		8X
7	Rear Tyre Rim LH	\$ 680.00		11X 380 SIN
8				
9				
No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		30
2	Rewiring to Facilitate Works	\$ 120.00		20
3	Transfer of Front Door Mechanism	\$ 140.00		11X
4	Transfer of Rear Door Mechanism	\$ 140.00		50
5	Remove and Refit All Trims, Upholders, Garnish and All Necessary to Facilitate Repair Works	\$ 320.00		11X
6	To Conduct 4 Wheel Alignment	\$ 180.00		60
7				
8				
9	Labour to remove and replace damaged parts (Including refitting and repositioning of replaced parts) and to repair all necessary (including knocking and jacking of panels required for repairs)	\$ 1,200.00		500
10	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 1,500.00		1100
	Estimated No. of days for repairs and respray of all necessary	5-8 Days		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-38604
252
2898.30
410
1760
5065.3
292
4000